

considered relevant to the ultimate disposition of issues.

Because of the diversity and complexities of the air carrier industry, the committee will be structured with a steering committee with the FAA as the chairperson. The steering committee will consist of members selected by the FAA, including aviation associations, industry representatives, employee unions, the FAA and other government entities (such as OSHA), and other participants, to provide a balance of views, interests, and expertise. Membership on the committee will be limited to facilitate discussions. Priority will be given to those applicants representing an identified segment of the air carrier community who are empowered to speak for that segment.

Other subcommittees or work groups may be established if required.

All non-Government representatives serve without Government compensation and bear all costs related to their participation on the committee or work groups. Members and participants should be available to attend all scheduled committee or work group meetings for the duration of the committee activities.

The first meeting of the committee will be scheduled as soon as possible after the comment period is expired. Work groups will be scheduled as determined by the committee and work group members to provide information and meet schedule requirements.

Make your request to participate in the ASHPP and/or on the committee, in writing, on or before March 31, 2003. Your request should provide the following information:

- Contact information (name, company and position, address, phone, facsimile, and e-mail)
- Segment(s) of the industry or organization/association you represent
- Experience, subject expertise, or other background information

The FAA will notify all selected members and participants, in writing, in advance of the first meeting. Additional information on the committee, membership, dates, and other information may be obtained on the FAA ASHP Web site at <http://www.faa.gov/avr/afs/asha/ashp.cfm>.

Commenters should be as specific as possible and provide as much detail in comments as necessary to facilitate decisionmaking. The FAA anticipates that the comments provided in response to this voluntary ASHPP and ASHP Aviation Rulemaking Committee will assist the FAA in considering options to address and enhance the safety and

health of employees in the air carrier industry.

Issued in Washington, DC on February 26, 2003.

Louis C. Cusimano,

Deputy Director, Flight Standards Service.

[FR Doc. 03-5000 Filed 3-3-03; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-23-AD; Amendment 39-13059; AD 2003-04-11]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-200B and -200F Series Airplanes Powered by Pratt & Whitney JT9D-70 Series Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 747-200B and -200F series airplanes powered by Pratt & Whitney JT9D-70 series engines, that requires repetitive detailed inspections of the pylon skin and internal structure of the nacelle struts adjacent to and aft of the precooler exhaust vent for heat damage (discoloration), wrinkling, and cracking; and corrective action, if necessary. The actions specified by this AD are intended to find and fix such damage, which could result in cracking or fracture of the nacelle struts, and consequent reduced structural integrity and possible separation of the strut and engine from the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective April 8, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 8, 2003.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Tamara L. Anderson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6421; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to Boeing Model 747-200B and -200F series airplanes powered by Pratt & Whitney JT9D-70 series engines was published in the **Federal Register** on November 27, 2002 (67 FR 70875). That action proposed to require repetitive detailed inspections of the pylon skin and internal structure of the nacelle struts adjacent to and aft of the precooler exhaust vent for heat damage (discoloration), wrinkling, and cracking; and corrective action, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Explanation of Editorial Change

We have changed the service bulletin citation throughout this final rule to exclude the Evaluation Form. The form is intended to be completed by operators and submitted to the manufacturer to provide input on the quality of the service bulletin; however, this AD does not include such a requirement.

Conclusion

After careful review of the available data, the FAA has determined that air safety and the public interest require the adoption of the rule with the change previously described. The FAA has determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

Cost Impact

There are approximately 7 airplanes of the affected design in the worldwide fleet. The FAA estimates that 6 airplanes of U.S. registry will be affected by this AD, that it will take approximately 8 work hours per airplane to accomplish the inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$2,880, or \$480 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2003-04-11 Boeing: Amendment 39-13059. Docket 2002-NM-23-AD.

Applicability: Model 747-200B and -200F series airplanes powered by Pratt & Whitney JT9D-70 series engines, certificated in any category; as listed in Boeing Special Attention Service Bulletin 747-54-2210, dated December 19, 2001.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To find and fix heat damage of the pylon skin and internal structure of the nacelle struts, which could result in cracking or fracture of the struts, and consequent reduced structural integrity and possible separation of the strut and engine from the airplane; accomplish the following:

Repetitive Inspections/Corrective Action

(a) Within 6 months after the effective date of this AD: Do a detailed inspection of the pylon skin and internal structure of the nacelle struts adjacent to and aft of the precooler exhaust vent for heat discoloration, wrinkling, and cracking, per the Work Instructions of Boeing Special Attention Service Bulletin 747-54-2210, dated December 19, 2001, excluding Evaluation Form. Repeat the inspection at least every 18 months.

Note 2: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(1) If any sign of heat discoloration is found, but there is no wrinkling: Before further flight, do a conductivity test of the discolored area(s) per the service bulletin. If the conductivity test is within the limits specified in Figures 3 and 4, as applicable, of the Work Instructions of the service bulletin, and no cracking is found, before further flight, do a penetrant or high frequency eddy current (HFEC) inspection for cracking.

(2) If any sign of wrinkling is found: Before further flight, do a penetrant or HFEC inspection of the wrinkled area(s) for cracking, per the service bulletin.

(3) If any sign of cracking is found: Before further flight, do the corrective action required by paragraph (b) of this AD.

(b) If, during any inspection or test done by this AD, any wrinkling or cracking is found, or the conductivity limits exceed the limits specified in Figures 3 and 4, as applicable, of the Work Instructions of Boeing Special Attention Service Bulletin 747-54-2210, dated December 19, 2001, excluding Evaluation Form: Before further flight, repair per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved, the approval must specifically reference this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) Except as provided by paragraph (b) of this AD, the actions shall be done in accordance with Boeing Special Attention Service Bulletin 747-54-2210, dated December 19, 2001, excluding Evaluation Form. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on April 8, 2003.

Issued in Renton, Washington, on February 20, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-4589 Filed 3-3-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-CE-32-AD; Amendment 39-13075; AD 2003-04-26]

RIN 2120-AA64

Airworthiness Directives; Raytheon Aircraft Company Model 1900D Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that applies to certain Raytheon Aircraft Company (Raytheon) Model 1900D airplanes. This AD requires you to inspect the alternating current (AC) inverter and modify the AC inverter and inverter sync wire shield. This AD is the result of reports that electrical noise causes the inverter to shut down in flight with loss of AC-powered flight instruments. The actions specified by this AD are intended to prevent electrical noise causing the inverter to shut down, which could result in failure of key aircraft electrical systems. Such failure could lead to loss of flight instruments during flight.

DATES: This AD becomes effective on April 21, 2003.

The Director of the Federal Register approved the incorporation by reference

of certain publications listed in the regulations as of April 21, 2003.

ADDRESSES: You may get the service information referenced in this AD from Raytheon Aircraft Company, 9709 E. Central, Wichita, Kansas 67201-0085; telephone: (800) 429-5372 or (316) 676-3140. You may view this information at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2002-CE-32-AD, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Todd Dixon, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4152; facsimile: (316) 946-4407.

SUPPLEMENTARY INFORMATION:

Discussion

What events have caused this AD? The FAA has received nine reports of electrical noise causing the alternating current (AC) inverter to shutdown on certain airplanes. These airplanes are equipped with KGS Electronics AC Inverter part number (P/N) SPC-10(PW), Mod 2, serial numbers 306 to 803. The shutdown of the inverter resulted in the loss of the electronic flight information system (EFIS), Radio Magnetic Indicator (RMI), and related AC-powered systems. Some airplanes experienced the loss of engine torque indication.

What is the potential impact if FAA took no action? Such failure of the inverter could lead to loss of flight instruments during a critical phase of flight.

Has FAA taken any action to this point? We issued a proposal to amend part 39 of the Federal Aviation

Regulations (14 CFR part 39) to include an AD that would apply to certain Raytheon Model 1900D airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on October 25, 2002 (67 FR 65519). The NPRM proposed to require you to inspect the alternating current (AC) inverter and modify the AC inverter and inverter sync wire shield.

Was the public invited to comment? The FAA encouraged interested persons to participate in the making of this amendment. We did not receive any comments on the proposed rule or on our determination of the cost to the public.

FAA's Determination

What is FAA's final determination on this issue? After careful review of all available information related to the subject presented above, we have determined that air safety and the public interest require the adoption of the rule as proposed except for minor editorial corrections. We have determined that these minor corrections:

- Provide the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Cost Impact

How many airplanes does this AD impact? We estimate that this AD affects 232 airplanes in the U.S. registry.

What is the cost impact of this AD on owners/operators of the affected airplanes? We estimate the following costs to accomplish the AC inverter inspection:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
2 workhours × \$60 = \$120 for each inverter	No cost for parts	\$240	232 × \$240 = \$55,680

We estimate the following costs to accomplish any necessary AC inverter modification that would be required

based on the results of the inspection. We have no way of determining the

number of airplanes that may need such modification:

Labor cost	Parts cost	Total cost per airplane
2 workhours × \$60 = \$120 for each inverter (\$240 per aircraft)	\$310	\$550 for each airplane.

We estimate the following costs to accomplish any necessary AC inverter sync wire shield modification that

would be required based on the results of the inspection. We have no way of

determining the number of airplanes that may need such modification: