Rules and Regulations

Federal Register Vol. 88, No. 23 Friday, February 3, 2023

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

NUCLEAR REGULATORY COMMISSION

10 CFR Part 52

[NRC-2017-0029]

RIN 3150-AJ98

NuScale Small Modular Reactor Design Certification

Correction

In rule document 2023–00729, appearing on page 3187 through 3310 in the issue of Thursday, January 19, 2023, make the following correction:

On page 3303, in the table titled, "Documents Related To NuScale Design Certification Rule", the fourth row is corrected to read as follows:

Annotated Comment Submissions	*ML22045A213
Small Modular Reactor Design	
RIN 3150–AJ98), June 2022.	

[FR Doc. C1–2023–00729 Filed 2–2–23; 8:45 am] BILLING CODE 0099–10–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–1302; Project Identifier MCAI–2022–00062–E; Amendment 39–22301; AD 2023–01–07]

RIN 2120-AA64

Airworthiness Directives; GE Aviation Czech s.r.o. (Type Certificate Previously Held by WALTER Engines a.s., Walter a.s., and MOTORLET a.s.) Turboprop Engines

Editorial Note: Rule document 2023– 00490 originally published on pages 2501– 2503 in the issue of Friday, January 13, 2023. In that publication, on page 2502, the effective date in section (a) appeared incorrectly. The rule is republished here corrected and in its entirety. **AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all GE Aviation Czech s.r.o. (GEAC) H75–100, H75-200, H80, H80-100, H80-200, H85-100, and H85-200 model turboprop engines. This AD is prompted by the manufacturer revising the airworthiness limitations section (ALS) of the existing engine maintenance manual (EMM) to introduce updated coefficients for the calculation of the cyclic life and safe life for the main shaft. This AD requires revising the ALS of the existing EMM and the operator's existing approved maintenance or inspection program, as applicable, to incorporate the updated coefficients and recalculate the cycles accumulated on critical parts. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective February 21, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2022–1302; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Barbara Caufield, Aviation Safety

Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7146; email: barbara.caufield@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all GEAC H75–100, H75–200, H80, H80–100, H80–200, H85–100, and H85–200 model turboprop engines. The NPRM published in the **Federal Register** on October 24, 2022 (87 FR 64175). The NPRM was prompted by AD 2022–0008, dated January 19, 2022,

issued by the European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union (referred to after this as the MCAI). The MCAI states that the airworthiness limitations for H series engine models, which are approved by EASA, are currently defined and published in the ALS of the GEAC EMM. These instructions have been identified as mandatory for continued airworthiness. Failure to accomplish these instructions could result in an unsafe condition. The MCAI explains that recently GEAC published a revision to the ALS, introducing updated coefficients for the calculation of the cyclic life and safe life for the main shaft.

In the NPRM, the FAA proposed to require revising the ALS of the existing EMM and the operator's existing approved maintenance or inspection program, as applicable, to incorporate the updated coefficients and recalculate the cycles accumulated on critical parts. An owner/operator (pilot) holding at least a private pilot certificate may revise the ALS of the existing EMM, and the owner/operator must enter compliance with the applicable paragraphs of the AD into the aircraft records in showing compliance with this AD in accordance with 14 CFR 43.9(a) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439. This is an exception to the FAA's standard maintenance regulations. The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2022–1302.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant