

List of Subjects in 10 CFR Part 1703

Freedom of Information.

For the reasons discussed in the preamble, the Defense Nuclear Facilities Safety Board amends section 1703.107 of the Code of Federal Regulations to read as follows:

■ 1. The authority citation for part 1703 continues to read:

Authority: 5 U.S.C. 301, 552; 31 U.S.C. 9701; 42 U.S.C. 2286b.

■ 2. Amend § 1703.107 by revising by:

- a. In paragraph (b)(1), revising the definition of “Direct costs”; and
- b. Revising paragraphs (b)(2)(i), (ii), (iii), and (b)(6).

The revisions read as follows:

§ 1703.107 Fees for Record Requests.

* * * * *

(b) * * *

(1) * * *

* * * * *

Direct costs mean those expenditures which DNFSB incurs in search, review, and duplication, as applicable to different categories of requesters, to respond to requests under § 1703.105. Direct costs include, for example, the hourly salary and projected benefits costs of agency personnel who search for, review, or duplicate records in response to a request. Overhead expenses such as cost of space, and heating or lighting the facility in which DNFSB records are stored are not included in direct costs.

* * * * *

(2) * * *

(i) If documents are requested for commercial use, DNFSB shall charge the hourly salary and projected benefits costs of agency personnel who search for and review records in response to a request, and for the costs of duplication as set out in subsection (b)(6) of this section.

(ii) If documents are not sought for commercial use and the request is made by an educational or noncommercial scientific institution, whose purpose is scholarly or scientific research, or a representative of the news media, DNFSB's charges shall be limited to the direct costs of duplication as set out in subsection (b)(6) of this section. There shall be no charge for the first 100 pages of duplication.

(iii) For a request not described in paragraphs (b)(2) (i) or (ii) of this section, DNFSB shall charge the hourly salary and projected benefits costs of the agency's personnel who search for records in response to a request and the direct costs of duplication as set out in subsection (b)(6) of this section. There shall be no charge for document review

time, and the first 100 pages of reproduction and the first two hours of search time will be provided without charge.

* * * * *

(6) *Schedule of Fees.* To the extent authorized by these regulations, DNFSB is authorized to seek the following fees to recover costs incurred in responding to FOIA requests:

(i) *Document search charges.* (A) *Manual:* Salary rate(s) (basic hourly pay plus 16%) of personnel performing records search or review.

(B) *Electronic:* Salary rate(s) (basic hourly pay plus 16%) of personnel performing search or review.

(C) *Document Review Charges:* Salary rate(s) (basic hourly pay plus 16%) of personnel performing search or review.

(iii) *Commercial requests.* DNFSB will charge requesters who seek records for commercial purposes for the cost of reviewing them to determine whether they are exempt from mandatory disclosure. The agency will assess these charges only when the records are first analyzed to determine the applicability of a specific exemption to a record or portion thereof. DNFSB will not charge for the review of an exemption previously applied at the administrative review level. If a record or portion thereof was withheld in full under an exemption that is subsequently found inapplicable, it may be reviewed again to determine the applicability of other exemptions not previously considered. DNFSB may charge for the cost of such review.

(iv) *Copying charges.* (1) *Paper:* \$.05 per page, if done in-house, or generally available commercial rate, approximately \$0.10 per page.

(2) *Electronic media:* Direct cost, including operator time (basic hourly pay plus 16%).

(3) *Audio and video cassette:* Actual commercial rates.

(4) *Duplication of CD or DVD:* Direct cost, including operator time (basic hourly pay plus 16%).

(5) *Large documents, e.g., maps or diagrams:* Actual commercial rates.

Dated: August 22, 2024.

Joyce Connery,
Chair.

[FR Doc. 2024-19527 Filed 9-9-24; 8:45 am]

BILLING CODE 3670-01-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2024-1005; Project Identifier AD-2022-00996-T; Amendment 39-22796; AD 2024-15-05]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 767-300 series airplanes. This AD was prompted by report that some Model 767-300 series airplanes that had been converted into a freighter configuration are missing an electrical bracket for a wire bundle in the main equipment center. This AD requires installing an electrical support bracket and re-installing wire bundles. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective October 15, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 15, 2024.

ADDRESSES:

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-1005; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For Boeing material, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110 SK57, Seal Beach, CA 90740-5600; telephone 562 797 1717; website myboeingfleet.com.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2024-1005.

FOR FURTHER INFORMATION CONTACT:

Samuel Dorsey, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3415; email: samuel.j.dorsey@faa.gov.

SUPPLEMENTARY INFORMATION:**Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to The Boeing Company Model 767-300 airplanes with certain line numbers. The NPRM published in the **Federal Register** on April 23, 2024 (89 FR 30284). The NPRM was prompted by a report that some Model 767-300 series airplanes that had been modified to operate in a freighter configuration by the manufacturer are missing an electrical support bracket for a wire bundle in the main equipment center. The missing electrical support bracket affects wire separation configuration requirements for fuel quantity indicating system wiring and could result in an electrical fault condition. In addition, the missing electrical support bracket is needed for some Model 767-

300 cargo airplanes to accomplish the service bulletin required by the alternative actions in paragraph (h)(2)(ii) of AD 2020-18-16, Amendment 39-21237 (85 FR 62993, October 6, 2020).

In the NPRM, the FAA proposed to require installing an electrical support bracket and re-installing wire bundles. The FAA is issuing this AD to prevent possible ignition sources in the fuel tank due to an electrical fault, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

Discussion of Final Airworthiness Directive**Comments**

The FAA received comments from two commenters.

The Air Line Pilots Association, International, supported the NPRM without change.

Aviation Partners Boeing stated that installing winglets under Supplemental Type Certificate ST01920SE does not affect compliance with the proposed actions. The FAA agrees. The FAA has not changed this AD in this regard.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. This AD is adopted as proposed in the NPRM.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed Boeing Alert Service Bulletin 767-24A0261, Revision 1, dated August 17, 2022. This material specifies procedures for installing an electrical support bracket in the main equipment center and re-installing wire bundles. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 18 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Installation of bracket	3 work-hours × \$85 per hour = \$255	\$93	\$348	\$6,264

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a

substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2024-15-05 The Boeing Company:

Amendment 39-22796; Docket No. FAA-2024-1005; Project Identifier AD-2022-00996-T.

(a) Effective Date

This airworthiness directive (AD) is effective October 15, 2024.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 767-300 series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 767-24A0261, Revision 1, dated August 17, 2022.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical Power.

(e) Unsafe Condition

This AD was prompted by a report that some Model 767–300 series airplanes that have been modified to operate in a freighter configuration are missing an electrical bracket for a wire bundle in the main equipment center, which affects wire separation configuration requirements for fuel quantity indicating system wiring and could result in an electrical fault condition. The FAA is issuing this AD to prevent possible ignition sources in the fuel tank due to an electrical fault, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Service Bulletin 767–24A0261, Revision 1, dated August 17, 2022, do all applicable actions identified as “RC” (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 767–24A0261, Revision 1, dated August 17, 2022.

(h) Exceptions to Service Information Specifications

Where the “Compliance” paragraph of Boeing Alert Service Bulletin 767–24A0261, Revision 1, dated August 17, 2022, refers to the Revision 1 date of this service bulletin, this AD requires using the effective date of this AD.

(i) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Service Bulletin 767–24–0261, dated May 19, 2021.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company

Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as specified by paragraph (h) of this AD: For material that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

(1) For more information about this AD, contact Samuel Dorsey, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3415; email: samuel.j.dorsey@faa.gov.

(2) Material identified in this AD that is not incorporated by reference is available at the addresses specified in paragraph (l)(3) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 767–24A0261, Revision 1, dated August 17, 2022.

(ii) [Reserved]

(3) For the material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website myboeingfleet.com.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on September 5, 2024.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024–20389 Filed 9–9–24; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2024–1289; Project Identifier MCAI–2023–01049–T; Amendment 39–22797; AD 2024–15–06]

RIN 2120–AA64

Airworthiness Directives; Airbus Canada Limited Partnership (Type Certificate Previously Held by C Series Aircraft Limited Partnership (CSALP); Bombardier, Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Canada Limited Partnership Model BD–500–1A10 and BD–500–1A11 airplanes. This AD was prompted by a report indicating that at various lavatory and galley locations within the airplane, incorrect terminal lugs were installed which are not compatible with the associated wire gauge. This AD requires removing and replacing existing lug terminals at various lavatory and galley locations, as specified in a Transport Canada AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective October 15, 2024.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 15, 2024.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2024–1289; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.