

members of the public to comment on the proposed rule through EDA's Web site. This issue has since been resolved. However, because of strong interest in this initiative, and to ensure stakeholders and the public have ample time and optimal access to comment on these changes, EDA is extending the deadline for submitting comments from February 6, 2012 to February 15, 2012.

Comments should be submitted to EDA as described in **ADDRESSES** above. EDA encourages using the online feature of the agency's Web site to submit comments and suggestions to EDA's proposed regulatory changes. The Web site is easily accessible at <http://www.eda.gov/>, and offers participants an opportunity to view the comments of others. EDA will consider all comments submitted electronically by 5 p.m. Eastern Time on February 15, 2012, or that are postmarked by that date, as referenced in **DATES** above. EDA will not accept public comments accompanied by a request that part or all of the material submitted be treated confidentially for any reason; EDA will not consider such comments and will return them and their accompanying materials to the commenter. All public comments (including those faxed or emailed to the agency) submitted in response to this notice must be in writing and will be a matter of public record.

Dated: February 2, 2012.

Jamie Lipsey,

Acting Deputy Chief Counsel, Economic Development Administration.

[FR Doc. 2012-2743 Filed 2-7-12; 8:45 am]

BILLING CODE 3510-24-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0104 Directorate Identifier 2011-NM-279-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 777-200, -200LR, -300, -300ER, and 777F series airplanes. This proposed AD was prompted by a report indicating that a fire originated near the first officer's

area, which caused extensive damage to the flight deck. This proposed AD would require replacing the low-pressure oxygen hoses with non-conductive low-pressure oxygen hoses in the flight compartment. We are proposing this AD to prevent electrical current from passing through the low-pressure oxygen hose internal anti-collapse spring, which can cause the low-pressure oxygen hose to melt or burn, and a consequent oxygen-fed fire in the flight compartment.

DATES: We must receive comments on this proposed AD by March 26, 2012.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone (206) 544-5000, extension 1; fax (206) 766-5680; email me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA 98057-3356. For information on the availability of this material at the FAA, call (425) 227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Susan Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA,

Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: (425) 917-6457; fax: (425) 917-6590; email: susan.l.monroe@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-0104 2011-NM-279-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We received a report indicating that a fire originated near the first officer's area, which caused extensive damage to the flight deck. The cause of this incident is unknown. One scenario of the causes being considered is that an electrical fault or short circuit resulted in electrical heating of the low-pressure oxygen hoses in the flight crew oxygen system. This condition, if not corrected, could cause electrical current to pass through the low-pressure oxygen hose internal anti-collapse spring, which can cause the low-pressure oxygen hose to melt or burn, and a consequent oxygen-fed fire in the flight compartment.

Relevant Service Information

We reviewed Boeing Alert Service Bulletin 777-35A0027, dated December 15, 2011. The service information describes procedures for replacing the low-pressure oxygen hoses with non-conductive low-pressure oxygen hoses in the flight compartment.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in

the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 169 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement	18 work-hours × \$85 per hour = \$1,530	\$1,743	\$3,273	\$553,137

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2012–0104; Directorate Identifier 2011–NM–279–AD.

(a) Comments Due Date

We must receive comments by March 26, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 777–200, –200LR, –300, –300ER, and 777F series airplanes; certificated in any category; as identified in Boeing Alert Service Bulletin 777–35A0027, dated December 15, 2011.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 35; Oxygen.

(e) Unsafe Condition

This AD was prompted by a report indicating that a fire originated near the first officer's area, which caused extensive damage to the flight deck. We are issuing this AD to prevent electrical current from passing through the low-pressure oxygen hose internal anti-collapse spring, which can cause the low-pressure oxygen hose to melt or burn, and a consequent oxygen-fed fire in the flight compartment.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within 18 months after the effective date of this AD: Replace the low-pressure oxygen hoses with non-conductive low-pressure

oxygen hoses in the flight compartment, in accordance with Boeing Alert Service Bulletin 777–35A0027, dated December 15, 2011.

(h) Parts Installation

As of the effective date of this AD, no person may install in the airplane flight compartment oxygen system on any airplane a low-pressure oxygen hose having part number 57034–81220, 57034–81320, or 57034–91100.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.]

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Susan Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM–150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: (425) 917–6457; fax: (425) 917–6590; email: susan.l.monroe@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, Washington 98124–2207; telephone (206) 544–5000, extension 1; fax (206) 766–5680; email me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA 98057–3356. For information on the availability of this material at the FAA, call (425) 227–1221.

Issued in Renton, Washington, on January 25, 2012.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-2906 Filed 2-7-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0106; Directorate Identifier 2011-NM-150-AD]

RIN 2120-AA64

Airworthiness Directives; BAE SYSTEMS (OPERATIONS) LIMITED Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all BAE SYSTEMS (OPERATIONS) LIMITED Model BAe 146 and Avro 146-RJ airplanes. This proposed AD was prompted by reports of baggage bay fire bottles that can be misassembled such that two squib electrical connectors can be cross-connected. This proposed AD would require a general visual inspection of certain baggage bay fire bottles for correct connection and for the length of the wiring loom, modifying the wiring loom to certain squib connectors, and corrective actions if necessary. We are proposing this AD to detect and correct excessive wiring loom length and improper connection of the squib connectors, which in conjunction with a fire in one of the baggage bays, could result in the fire extinguishing agent being discharged into a wrong compartment and consequent damage to the airplane.

DATES: We must receive comments on this proposed AD by March 26, 2012.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey

Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact BAE SYSTEMS (OPERATIONS) LIMITED, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email RApublications@baesystems.com; Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call (425) 227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the

ADDRESSES section. Include "Docket No. FAA-2012-0106; Directorate Identifier 2011-NM-150-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2011-0065, dated April 7, 2011 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

The baggage bay fire bottles of certain BAe 146 and AVRO 146-RJ aeroplanes can be misassembled such that two squib electrical connectors can be cross-connected. This has been caused by an error in the baggage bay fire bottle Component Manufacturer Manual (CMM) and by excessive wiring loom length.

This condition, if not corrected and in conjunction with a fire in one of the baggage bays, could result in the fire extinguishant to be discharged into a wrong compartment and consequent potential damage to the aircraft

* * *

In addition to the CMM revision, to address this unsafe condition, BAE Systems developed modifications to reroute the baggage bay fire bottle wiring looms and prevent crossed electrical connections.

For the reasons described above, this [EASA] AD requires the implementation of modifications HCM36250A and HCM36250B to affected aeroplanes.

Required actions include general visual inspections of certain baggage bay fire bottles for correct connection and for the length of the wiring loom, modifying the wiring loom to certain squib connectors, and corrective action if necessary. Corrective actions include reconnecting the squibs connectors and modifying the loom to proper length. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

BAE SYSTEMS (Operations) Limited has issued Modification Service Bulletin SB.26-077-36250A.B, Revision 4, dated January 7, 2011. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.