

under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–11–13 Bell Textron Canada Limited:
Amendment 39–21575; Docket No. FAA–2020–1170; Project Identifier MCAI–2020–00720–R.

(a) Applicability

This airworthiness directive (AD) applies to Bell Textron Canada Limited (Bell) Model 429 helicopters, certificated in any category, with a Bell Emergency Flotation System (EFS) kit part number (P/N) 429–706–069–101/–103/–105/–121/–123/–125/–139/–141/–143/or –157 manufactured before July 2019, with a float supply hose manufactured before January 2014, installed, except for float supply hoses marked with “SB 025–69–21” above the external identification marking.

(b) Unsafe Condition

This AD defines the unsafe condition as a blocked float supply hose installed on an EFS. This condition could result in partial inflation of an EFS float during an emergency landing on water and subsequently preventing a timely egress from the helicopter.

(c) Effective Date

This AD is effective July 15, 2021.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 100 hours time-in-service (TIS):

(i) Remove each EFS supply hose from the float and inspect each end of the EFS supply hose by inserting a plastic cable tie, 300 mm minimum × 5 mm maximum (11.811 in. minimum × .196 in. maximum), into the holes of the related fitting as shown in Figure 1 of Safran Aerosystems Services Service Bulletin No. 025–69–21, Revision 00, dated March 23, 2020 (SB 025–69–21).

Note 1 to paragraph (e)(1)(i): Each end of the supply hose may also be referred to as fitting or banjo.

(ii) If the cable tie does not pass through the hose, before further flight, remove the EFS supply hose from service and replace it with an airworthy part.

(iii) If the cable tie passes through the supply hose, mark a green dot with indelible ink on the base of the supply hose and write “SB 025–69–21” above the external identification marking of the EFS with indelible ink.

(2) As of the effective date of this AD, do not install an EFS supply hose manufactured before January 2014 on any helicopter unless the requirements in paragraph (e)(1) of this AD have been completed.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (g)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(g) Related Information

(1) For more information about this AD, contact Matt Fuller, AD Program Manager, Operational Safety Branch, Airworthiness Products Section, General Aviation & Rotorcraft Unit, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817–222–5110; email matthew.fuller@faa.gov.

(2) The subject of this AD is addressed in Transport Canada AD CF–2020–212R1, dated August 19, 2020. You may view the Transport Canada AD on the internet at <https://www.regulations.gov> in Docket No. FAA–2020–1170.

(h) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Safran Aerosystems Services Service Bulletin No. 025–69–21, Revision 00, dated March 23, 2020 (SB 025–69–21).

Note 2 to paragraph (h)(2)(i): SB 025–69–21 is attached to Bell Alert Service Bulletin No. 429–20–52, dated March 30, 2020, which is not incorporated by reference in this AD.

(ii) [Reserved]

(3) As the design approval holder for the product identified in paragraph (a) of this AD, contact Bell Textron Canada Limited for the Safran Aerosystems Services service information identified in this AD, at Bell Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4; telephone 450–437–2862 or 800–363–8023; fax 450–

433–0272; or at <https://www.bellcustomer.com>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 18, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–12042 Filed 6–9–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0187; Project Identifier AD–2020–01664–E; Amendment 39–21583; AD 2021–11–21]

RIN 2120–AA64

Airworthiness Directives; CFM International, S.A. Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain CFM International, S.A. (CFM) LEAP–1A model turbofan engines. This AD was prompted by a report of a manufacturing quality escape found during an inspection of a high-pressure turbine (HPT) case. This AD requires the removal from service of the affected HPT case. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 15, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 15, 2021.

ADDRESSES: For service information identified in this final rule, contact CFM International, S.A., Aviation Operations Center, 1 Neumann Way, M/D Room 285, Cincinnati, OH 45125; phone: (877) 432–3272; email: aviation.fleetssupport@ge.com. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District

Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238-7759. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0187.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0187; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Christopher McGuire, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington MA 01803; phone: (781) 238-7120; fax: (781) 238-7199; email: Chris.McGuire@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain CFM LEAP-1A23, LEAP-1A24, LEAP-1A24E1, LEAP-1A26, LEAP-1A26CJ, LEAP-1A26E1, LEAP-1A29, LEAP-1A29CJ, LEAP-1A30, LEAP-1A32, LEAP-1A33, LEAP-1A33B2, and LEAP-1A35A model turbofan engines. The NPRM published in the **Federal Register** on March 23, 2021 (86 FR 15443). The NPRM was prompted by a report of a manufacturing quality escape found during an inspection of an HPT case. In the NPRM, the FAA proposed to require the removal from service of the affected HPT case. The FAA is issuing this AD to address the unsafe condition on these products.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. This AD is adopted as proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

The FAA reviewed CFM Service Bulletin (SB) LEAP-1A-72-00-0421-01A-930A-D, Issue 001, dated October 22, 2020. This SB specifies procedures for replacing the affected HPT cases. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Costs of Compliance

The FAA estimates that this AD affects 8 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Remove and replace the HPT case	1 work-hour × \$85 per hour = \$85	\$217,600	\$217,685	\$1,741,480

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on

the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021-11-21 CFM International, S.A.:
Amendment 39-21583; Docket No. FAA-2021-0187; Project Identifier AD-2020-01664-E.

(a) Effective Date

This airworthiness directive (AD) is effective July 15, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to CFM International, S.A. (CFM) LEAP-1A23, LEAP-1A24, LEAP-1A24E1, LEAP-1A26, LEAP-1A26CJ, LEAP-1A26E1, LEAP-1A29, LEAP-1A29CJ, LEAP-1A30, LEAP-1A32, LEAP-1A33, LEAP-1A33B2, and LEAP-1A35A model turbofan engines, with a high-pressure turbine (HPT) case, part number (P/N) 2668M94G01, that

contains a stage 7 port, P/N 2614M30P01, with a port casting serial number (S/N) listed in Table 1 in Planning Information, Paragraph 3.A., of CFM Service Bulletin (SB) LEAP-1A-72-00-0421-01A-930A-D, Issue 001, dated October 22, 2020.

(d) Subject

Joint Aircraft System Component (JASC) Code 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by a report of a manufacturing quality escape found during inspection of an HPT case. The FAA is issuing this AD to prevent failure of the HPT case. The unsafe condition, if not addressed, could result in failure of the HPT case, uncontained rotor release, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Before the HPT case exceeds the cycles since new limit in Table 1, Planning Information, Paragraph 3.A., of CFM SB LEAP-1A-72-00-0421-01A-930A-D, Issue 001, dated October 22, 2020, or during the next piece part exposure, whichever occurs first after the effective date of this AD, remove the affected HPT case from service and replace with a part eligible for installation.

(h) Definitions

For the purpose of this AD:

(1) A part eligible for installation is an HPT case, P/N 2668M94G01, that contains a stage 7 port, P/N 2614M30P01, with an S/N that is not listed in Table 1 in Planning Information, Paragraph 3.A., of CFM SB LEAP-1A-72-00-0421-01A-930A-D, Issue 001, dated October 22, 2020.

(2) Piece-part exposure is when the HPT case is removed from the engine and fully disassembled.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in Related Information. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Christopher McGuire, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7120; fax: (781) 238-7199; email: Chris.McGuire@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) CFM Service Bulletin LEAP-1A-72-00-0421-01A-930A-D, Issue 001, dated October 22, 2020.

(ii) [Reserved]

(3) For CFM service information identified in this AD, contact CFM International, S.A., Aviation Operations Center, 1 Neumann Way, M/D Room 285, Cincinnati, OH 45125; phone: (877) 432-3272; email: aviation.fleetsupport@ge.com.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238-7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 21, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-12137 Filed 6-9-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF JUSTICE

Drug Enforcement Administration

21 CFR Part 1308

[Docket No. DEA-715]

Schedules of Controlled Substances: Placement of Oliceridine in Schedule II

AGENCY: Drug Enforcement Administration, Department of Justice.

ACTION: Final rule.

SUMMARY: This final rule adopts, with a change as mentioned below, an interim final rule with request for comments published in the **Federal Register** on October 30, 2020, placing oliceridine, *N*-[(3-methoxythiophen-2-yl)methyl]({2-[(9*R*)-9-(pyridin-2-yl)-6-oxaspiro[4.5]decan-9-yl]ethyl}amine fumarate, including its isomers, esters, ethers, salts and salts of isomers, esters and ethers whenever the existence of such isomers, esters, ethers and salts is possible, in schedule II of the Controlled Substances Act. In response to an error in the chemical name of oliceridine as noted by one of the commenters to the interim final rule, the Drug Enforcement

Administration makes a correction to the above mentioned chemical name of oliceridine by removing the word “fumarate” to read as *N*-[(3-methoxythiophen-2-yl)methyl]({2-[(9*R*)-9-(pyridin-2-yl)-6-oxaspiro[4.5]decan-9-yl]ethyl}amine. This change clarifies the control of oliceridine free base and its salts, to include the fumarate salt, by definition.

DATES: Effective July 12, 2021.

FOR FURTHER INFORMATION CONTACT: Dr. Terrence L. Boos, Drug and Chemical Evaluation Section, Diversion Control Division, Drug Enforcement Administration; Telephone: (571) 362-3249.

SUPPLEMENTARY INFORMATION:

Background and Legal Authority

On October 30, 2020, the Drug Enforcement Administration (DEA), pursuant to 21 U.S.C. 811(j), published an interim final rule (IFR) to place oliceridine (including its isomers, esters, ethers, salts and salts of isomers, esters and ethers whenever the existence of such isomers, esters, ethers and salts is possible), a medication approved recently by the Food and Drug Administration (FDA) for medical use as an intravenous drug for the management of acute pain severe enough to require an intravenous opioid analgesic and for patients for whom alternative treatments are inadequate, in schedule II of the Controlled Substances Act (CSA). 85 FR 68749. The IFR provided an opportunity for interested persons to submit comments, as well as file a request for hearing or waiver of hearing, on or before November 30, 2020. DEA received three comments and did not receive any requests for hearing or waiver of hearing.

Comments Received

In response to the IFR, DEA received three comments. The submissions were from individuals or anonymous commenters. One commenter suggested that oliceridine be placed in schedule III rather than schedule II, one commenter had a statement on the controlled name, and the third commenter discussed another substance entirely that was unrelated to oliceridine. As such, the third comment was outside the scope of this current scheduling action.

Comment: One commenter suggested that oliceridine be placed in schedule III of the CSA, rather than schedule II. The commenter mentioned that placement of oliceridine in schedule II will limit its medical applications and limit access to the drug due to schedule II manufacturing quotas. The commenter stated that oliceridine has the potential