

part 50 and in accordance with 10 CFR 50.59, “Changes, Tests and Experiments,” to support the staff’s performance of potential inspections of a licensee’s implementation of these requirements for AMT-fabricated components.

III. Specific Considerations

This report documents completion of the staff’s initial review of QA criteria and 10 CFR 50.59 requirements for AMT applications at U.S. nuclear power plants. This report does not represent a complete and final analysis of all aspects of QA criteria and 10 CFR 50.59 requirements and guidance that might be applicable to the use of AMT components at U.S. nuclear power plants. This report does not create new regulatory requirements or establish new regulatory positions with respect to the use or manufacture of AMT components for nuclear power plants. The scope of this report is limited to the review of existing requirements and guidance to address AMT components and the consideration of potential regulatory and technical challenges. This report may be subject to future revision, as additional insights and operating experience for use of AMT components are gained.

The NRC is requesting general comments on this document to be open and transparent in processes involving the installation of AMT-fabricated components.

IV. Public Meeting

The NRC plans to hold a public meeting during the public comment period for this action. A public meeting is planned for December 2020, via webinar. The public meeting will provide forums for the NRC staff to discuss issues and questions with members of the public. The NRC does not intend to provide any responses to comments submitted during the public meeting. The public meeting will be noticed on the NRC’s public meeting website at least 10 calendar days before the meeting. Members of the public should monitor the NRC’s public meeting website for additional information about the public meetings at <https://www.nrc.gov/public-involve/public-meetings/index.cfm>. The NRC will post the notices for the public meetings and webinars and may post additional material related to this action to the Federal Rulemaking website at <https://www.regulations.gov/> under Docket ID NRC–2020–0253. The Federal Rulemaking website allows you to receive alerts when changes or additions occur in a docket folder. To subscribe: (1) Navigate to the docket folder (NRC–

2020–0253); (2) click the “Sign up for Email Alerts” link; and (3) enter your email address and select how frequently you would like to receive emails (daily, weekly, or monthly).

Dated: November 23, 2020.

For the Nuclear Regulatory Commission.

Anna H. Bradford,

Director, Division of New and Renewed Licenses, Office of Nuclear Reactor Regulation.

[FR Doc. 2020–26272 Filed 11–27–20; 8:45 am]

BILLING CODE 7590–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–1037; Project Identifier 2019–SW–077–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters Deutschland GmbH Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus Helicopters Deutschland GmbH Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3 helicopters. This proposed AD would require removing certain Titanium (Ti) bolts from service and prohibit installing these Ti-bolts in a critical area. This proposed AD was prompted by a report of a broken Ti-bolt. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 14, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202–493–2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1037; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the European Union Aviation Safety Agency (EASA) AD, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

For service information identified in this NPRM, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone 972–641–0000 or 800–232–0323; fax 972–641–3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110.

FOR FURTHER INFORMATION CONTACT:

Katherine Venegas, Aviation Safety Engineer, Los Angeles ACO, FAA, 3960 Paramount Blvd., Lakewood, CA 90712; telephone 562–627–5353; email katherine.venegas@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2020–1037; Product Identifier 2019–SW–077–AD” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this proposal.

Confidential Business Information

CBI is commercial or financial information that is both customarily and

actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Katherine Venegas, Aviation Safety Engineer, Los Angeles ACO, FAA, 3960 Paramount Blvd., Lakewood, CA 90712; telephone 562-627-5353; email katherine.venegas@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Discussion

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD No. 2019-0199, dated August 16, 2019, to correct an unsafe condition for Airbus Helicopters Deutschland GmbH (AHD), formerly Eurocopter Deutschland GmbH, Eurocopter España S.A., Model EC135 P1, EC135 P2, EC135 P2+, EC135 P3, EC135 T1, EC135 T2, EC135 T2+, EC135 T3, EC635 P2+, EC635 P3, EC635 T1, EC635 T2+, and EC635 T3 helicopters. EASA advises of a report of a broken Ti-bolt. Subsequent investigation revealed that an improper heat treatment process was accomplished on a batch of Ti-bolts, which can lead to hydrogen embrittlement. The investigation also identified the critical location where these Ti-bolts are installed on helicopters. According to EASA, this condition, if not detected and corrected, could lead to failure of an affected Ti-bolt installed in a critical location, possibly resulting in reduced control of the helicopter. Accordingly, the EASA AD requires a one-time inspection of Ti-bolt part number (P/N) L535M2001203 marked with manufacturer monogram "D" or with an illegible manufacturer monogram installed on the forward tail rotor (T/R) drive shaft and, depending on the inspection results, replacing the Ti-bolt. The EASA AD also prohibits the (re)installation of these Ti-bolts.

FAA's Determination

These helicopters have been approved by EASA and are approved for operation

in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA is proposing this AD after evaluating all known relevant information and determining that an unsafe condition is likely to exist or develop on other helicopters of these same type designs.

Related Service Information

The FAA reviewed Airbus Helicopters Alert Service Bulletin (ASB) No. EC135-00A-001, Revision 1, dated September 2, 2019, for Airbus Helicopters Deutschland GmbH Model EC135 T1, T2, T2+, T3, P1, P2, P2+, P3, 635 T1, 635 T2+, 635 T3, 635 P2+, and 635 P3 helicopters, and Airbus Helicopters ASB No. EC135H-00A-001, Revision 1, dated September 2, 2019, for Airbus Helicopters Deutschland GmbH Model EC135, T3H, P3H, 635 T3H, and 635 P3H helicopters. This service information specifies inspecting the forward T/R drive shaft, distance plate of the 5B-0.50-2.50P-XN-1 antenna, main rotor controls, FWD connection of ball bearing control, and AFT connection of ball bearing control and yaw actuator for the installation of Ti-bolt P/N L535M2001203, EN3308-040020F, L221M1040201, EN3740-060020F, and EN3308-060020F, marked with manufacturer monogram "D" or an illegible manufacturer monogram. If a specified Ti-bolt is installed, the service information specifies replacing the Ti-bolt and discarding the removed Ti-bolt.

Proposed AD Requirements

This proposed AD would require removing any Ti-bolt P/N L535M2001203 marked with manufacturer monogram "D" or with an illegible manufacturer monogram installed on the forward T/R drive shaft from service. This proposed AD would also prohibit installing an affected Ti-bolt on the forward T/R drive shaft of any helicopter.

Differences Between This Proposed AD and the EASA AD

The EASA AD applies to Model EC135 P1, EC135 P2, EC135 P2+, EC135 P3, EC135 T1, EC135 T2, EC135 T2+, EC135 T3, EC635 P2+, EC635 P3, EC635 T1, EC635 T2+, and EC635 T3 helicopters and requires inspecting Ti-bolt P/N L535M2001203 marked with manufacturer monogram "D" or with an illegible manufacturer monogram installed on the forward T/R drive shaft. This proposed AD applies to Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3 helicopters

with a Ti-bolt P/N L535M2001203 marked with manufacturer monogram "D" or with an illegible manufacturer monogram installed on the forward T/R drive shaft instead. This proposed AD does not apply to Model EC635 P2+, EC635 P3, EC635 T1, EC635 T2+, or EC635 T3 helicopters because these models are not FAA type-certificated. The EASA AD requires discarding the affected Ti-bolts, whereas this proposed AD would require removing the affected Ti-bolts from service instead.

Costs of Compliance

The FAA estimates that this proposed AD affects 326 helicopters of U.S. registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates that operators may incur the following costs in order to comply with this proposed AD.

Replacing a Ti-bolt would take about four work-hours and parts would cost about \$82 for an estimated cost of \$422 per Ti-bolt.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus Helicopters Deutschland GmbH:
Docket No. FAA-2020-1037; Project Identifier 2019-SW-077-AD.

(a) Applicability

This airworthiness directive (AD) applies to Airbus Helicopters Deutschland GmbH Model EC135P1, EC135P2, EC135P2+, EC135P3, EC135T1, EC135T2, EC135T2+, and EC135T3 helicopters, certificated in any category, with a Titanium (Ti) bolt part number L535M2001203 marked with manufacturer monogram "D" or with an illegible manufacturer monogram installed on the forward tail rotor drive shaft.

Note 1 to paragraph (a): Helicopters with an EC135P3H designation are Model EC135P3 helicopters. Helicopters with an EC135T3H designation are Model EC135T3 helicopters.

(b) Unsafe Condition

This AD defines the unsafe condition as failure of an affected Ti-bolt installed in a critical location, possibly resulting in reduced control of the helicopter.

(c) Comments Due Date

The FAA must receive comments by January 14, 2021.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 50 hours time-in-service or 3 months, whichever occurs first, remove any Ti-bolt identified in paragraph (a) of this AD, located on the forward tail rotor drive shaft, from service.

(2) As of the effective date of this AD, do not install a Ti-bolt identified in paragraph

(a) of this AD on the forward tail rotor drive shaft of any helicopter.

(f) Alternative Methods of Compliance (AMOCs):

The Manager, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Manager, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(g) Additional Information

(1) Airbus Helicopters Alert Service Bulletin (ASB) No. EC135-00A-001 and ASB No. EC135H-00A-001, each Revision 1 and dated September 2, 2019, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) No. 2019-0199, dated August 16, 2019. You may view the EASA AD on the internet at <https://www.regulations.gov> in the AD Docket.

(h) Subject

Joint Aircraft System Component (JASC)
Codes: 1430, Fasteners; and 6510, Tail Rotor Drive Shaft.

Issued on November 20, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-26253 Filed 11-27-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-1038; Project Identifier MCAI-2020-00569-E]

RIN 2120-AA64

Airworthiness Directives; Safran Helicopter Engines, S.A. (Type Certificate Previously Held by Turbomeca, S.A.) Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Safran Helicopter Engines, S.A. (Safran) Arriel 2D and Arriel 2E model

turboshaft engines. This proposed AD was prompted by the manufacturer revising the maintenance and overhaul manuals to introduce new or more restrictive airworthiness limitations and maintenance tasks. This proposed AD would require the replacement of certain critical parts before reaching their published in-service life limits, performing scheduled maintenance tasks before reaching their published periodicity, and performing unscheduled maintenance tasks when the engine meets certain conditions. As a terminating action, this proposed AD would require operators to revise the airworthiness limitation section (ALS) of their existing approved aircraft maintenance program (AMP) by incorporating the revised airworthiness limitations and maintenance tasks. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 14, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12 140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Safran Helicopter Engines, S.A., 64511 Bordes—Cedex, France; phone: (33) 05 59 74 40 00; fax: (33) 05 59 74 45 15. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238-7759.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1038; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other