

with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
- a. Removing Airworthiness Directive 2021–13–07, Amendment 39–21612 (86 FR 31601, June 15, 2021); and
 - b. Adding the following new airworthiness directive:

GE Aviation Czech s.r.o. (Type Certificate Previously held by WALTER Engines a.s., Walter a.s., and MOTORLET a.s.):
Docket No. FAA–2023–2002; Project Identifier MCAI–2023–00176–E.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 11, 2023.

(b) Affected ADs

This AD replaces AD 2021–13–07, Amendment 39–21612 (86 FR 31601, June 15, 2021).

(c) Applicability

This AD applies to GE Aviation Czech s.r.o. (type certificate previously held by WALTER Engines a.s., Walter a.s., and MOTORLET a.s.) Model M601E–11, M601E–11A, M601E–11AS, and M601E–11S engines with a centrifugal compressor case having part number (P/N) M601–154.61 installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by the manufacturer determining that the life limit of a compressor case having P/N M601–154.61 is not listed in the airworthiness limitations section of the existing engine maintenance manual. The FAA is issuing this AD to prevent the failure of the engine. The unsafe condition, if not addressed, could result in uncontained release of a critical part, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD: Perform all required actions within the compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021–0125R1, dated January 30, 2023 (EASA AD 2021–0125R1).

(h) Exceptions to EASA AD 2021–0125R1

(1) Where EASA AD 2021–0125R1 refers to May 11, 2021 (the effective date of EASA Emergency AD 2021–0125–E, dated May 7, 2021), this AD requires using June 30, 2021 (the effective date of AD 2021–13–07).

(2) This AD does not adopt the Remarks paragraph of EASA AD 2021–0125R1.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

For more information about this AD, contact Barbara Caufield, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (781) 238–7146; email: barbara.caufield@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021–0125R1, dated January 30, 2023.

(ii) [Reserved]

(3) For EASA AD 2021–0125R1, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; website: easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locationsoremailfr.inspection@nara.gov.

Issued on October 19, 2023.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–23634 Filed 10–26–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–2005; Project Identifier AD–2022–01523–A]

RIN 2120–AA64

Airworthiness Directives; WACO Classic Aircraft Corporation Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain WACO Classic Aircraft Corporation Model 2T–1A–2 airplanes. This proposed AD was prompted by reports of multiple types of cracks at the leading edge former ribs and trailing edge former ribs in the upper wing

center section. This proposed AD would require installing maneuver restriction placards in the front and rear cockpits, inspecting the leading and trailing edge former ribs for cracking, replacing any cracked ribs, modifying the upper wing center section assembly, and removing the maneuver restriction placards after completing the modification. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by December 11, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA-2023-2005; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For service information identified in this NPRM, contact WACO Classic Aircraft Corporation, 15955 South Airport Road, Battle Creek, MI 49015; phone: (269) 565-1000; email: *hello@wacoaircraft.com*; website: *wacoaircraft.com*.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

FOR FURTHER INFORMATION CONTACT: Tim Eichor, Aviation Safety Engineer, FAA, 1801 S Airport Road, Wichita, KS 67209; phone: (847) 294-7141; email: *tim.d.eichor@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed

under **ADDRESSES**. Include “Docket No. FAA-2023-2005; Project Identifier AD-2022-01523-A” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Tim Eichor, Aviation Safety Engineer, FAA, 1801 S Airport Road, Wichita, KS 67209. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA received reports of multiple types of cracks after low flight hours on WACO Classic Aircraft Corporation Model 2T-1A-2 airplanes. The cracks were approximately 1 to 1.5 inches long and located in the leading edge former ribs and trailing edge former ribs in the upper wing center section, along the top flange where the ribs attach to the spar. Due to the cracking, the fabric support channels have come close to separating from the trailing edge former ribs. When fabric support channels detach from a rib, they would still be attached to the fabric, but the upper center wing airfoil may not maintain its shape due to the

fabric support channels being pulled up by aerodynamic loads, which could lead to unexpected and unknown flight characteristics. The type certificate holder determined that this unsafe condition affects airplane serial numbers 1200 and subsequent with the upper wing center section assembly 30116-100 configuration.

This condition, if not addressed, could result in reduced structural integrity of the airplane and the reduced ability of the flightcrew to maintain the safe flight and landing of the airplane.

FAA’s Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Related Service Information Under 14 CFR Part 51

The FAA reviewed WACO Great Lakes 2T-1A-2 Service Bulletin GL-SB0002, Revision NR, dated July 6, 2023 (WACO SB 2T-1A-2, Revision NR). This service information specifies procedures for inspecting the leading edge former ribs and trailing edge former ribs in the upper wing center section for cracking, replacing any cracked ribs, and modifying the upper wing center section assembly by installing new fabric support channels, saddles, and brackets. Modifying the upper wing center section assembly changes the configuration from the 30116-100 upper wing center section assembly configuration to the 30116-104 upper wing center section assembly configuration. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in

ADDRESSES.

Proposed AD Requirements in This NPRM

This proposed AD would require installing maneuver restriction placards in the front and rear cockpits, inspecting the leading and trailing edge former ribs for cracking, replacing any cracked rib, modifying the upper wing center section assembly, and removing the maneuver restriction placards after completing the modification.

Difference Between This Proposed AD and the Service Information

Although section B of the Accomplishment Instructions in WACO SB 2T-1A-2, Revision NR, specifies to record the locations of all identified cracks found on the leading edge former ribs and the trailing edge former ribs

and share this information with WACO Aircraft, this proposed AD would not require those actions.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 19 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Maneuver restriction placard installation/ removal	1 work-hour × \$85 per hour = \$85	\$10	\$95	\$1,805
Rib inspection	4 work-hours × \$85 per hour = \$340	0	340	6,460
Upper wing center assembly modification	185 work-hours × \$85 per hour = \$15,725	4,063	19,788	375,972

The FAA estimates the following costs to do any necessary rib replacement that would be required

based on the results of the proposed inspection. The agency has no way of

determining the number of airplanes that might need this replacement:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Rib replacement (8 ribs)	16 work-hours × \$85 per hour = \$1,360 (8 ribs)	\$1,032 (8 ribs)	\$2,392 (8 ribs)

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

WACO Classic Aircraft Corporation: Docket No. FAA-2023-2005; Project Identifier AD-2022-01523-A.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 11, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to WACO Classic Aircraft Corporation Model 2T-1A-2 airplanes, serial numbers 1200 and subsequent with the

30116-100 upper wing center section assembly configuration, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 5712, Wing, Rib/Bulkhead.

(e) Unsafe Condition

This AD was prompted by reports of multiple cracks at the leading edge former ribs and trailing edge former ribs in the upper wing center section along the top flange where the ribs attach to the spar after low flight hours. The FAA is issuing this AD to detect and correct cracks in the leading and trailing edge former ribs in the upper wing center section. The unsafe condition, if not addressed, could result in reduced structural integrity of the airplane and the reduced ability of the flightcrew to maintain the safe flight and landing of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 30 days after the effective date of this AD, insert maneuver restriction placards on the instrument panel of the front and rear cockpits, and next to the operating placard in the rear cockpit, stating "NO AEROBATIC MANEUVERS ALLOWED."

(2) Within 100 hours time-in-service (TIS) or within 12 months after the effective date of this AD, whichever occurs first, accomplish the following:

(i) Inspect the leading edge former ribs and trailing edge former ribs in the upper wing center section for cracking in accordance with section B and before further flight, replace any cracked rib in accordance with section C of the Accomplishment Instructions in WACO Great Lakes 2T-1A-2 Service Bulletin GL-SB0002, Revision NR,

dated July 6, 2023 (WACO SB 2T-1A-2, Revision NR). Although section B of the Accomplishment Instructions in WACO SB 2T-1A-2, Revision NR, specifies to record the locations of all identified cracks found on the leading edge former ribs and the trailing edge former ribs and share this information with WACO Aircraft, this AD does not require those actions.

(ii) Modify the center section to the 30116-104 upper wing center section assembly configuration in accordance with section C of the Accomplishment Instructions in WACO SB 2T-1A-2, Revision NR.

(3) After replacing all cracked ribs and modifying the center section to the 30116-104 upper wing center section assembly configuration, aerobatic maneuvers can resume and the “NO AEROBATIC MANEUVERS ALLOWED” maneuver restriction placards can be removed from the front and rear cockpits.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Central Certification Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the Central Certification Branch, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Additional Information

For more information about this AD, contact Tim Eichor, Aviation Safety Engineer, FAA, 1801 S Airport Road, Wichita, KS 67209; phone: (847) 294-7141; email: tim.d.eichor@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) WACO Great Lakes 2T-1A-2 Service Bulletin GL-SB0002, Revision NR, dated July 6, 2023.

(ii) [Reserved]

(3) For service information identified in this AD, contact WACO Classic Aircraft Corporation, 15955 South Airport Road, Battle Creek, MI 49015; phone: (269) 565-1000; email: hello@wacoaircraft.com; website: wacoaircraft.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on

the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on October 20, 2023.

Ross Landes,

*Deputy Director for Regulatory Operations,
Compliance & Airworthiness Division,
Aircraft Certification Service.*

[FR Doc. 2023-23633 Filed 10-26-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Parts 732, 734, 736, 740, 742, 744, 746, 748, 758, 770, 772, and 774

[Docket No. 231024-0253]

RIN 0694-XC101

Procedures for Access to the Public Briefing on Additional Export Controls on Certain Advanced Computing and Supercomputing Items; and Semiconductor Manufacturing Items

AGENCY: Bureau of Industry and Security, U.S. Department of Commerce.

ACTION: Procedures for accessing a public briefing on regulatory actions.

SUMMARY: On October 25, 2023, the Bureau of Industry and Security (BIS) is publishing in the **Federal Register** two interim final rules, “Implementation of Additional Export Controls: Certain Advanced Computing Items; Supercomputer and Semiconductor End Use; Updates and Corrections” and “Export Controls on Semiconductor Manufacturing Items,” which were both filed for public inspection at the **Federal Register** on October 18, 2023. BIS published an associated final rule, “Entity List Additions,” in the **Federal Register** on October 19, 2023. On November 6, 2023, Assistant Secretary for Export Administration Thea D. Rozman Kendler will conduct a public briefing on these two interim final rules and one final rule. This announcement provides details on the procedures for participating in the public briefing.

DATES:

Public briefing: The public briefing call will be held on November 6, 2023. The public briefing call will begin at 3 p.m. Eastern Daylight (EDT) local time and conclude at 5 p.m. EDT. The registration link for attending this event will be posted no later than October 30, 2023.

Deadline for submitting questions for the public briefing: Questions for the briefing must be received no later than November 1, 2023.

ADDRESSES: The registration link for attending this event will be posted on the BIS website at <https://www.bis.doc.gov/index.php/about-bis/newsroom/2082>. This briefing will be virtual; no in-person attendance is available.

Submitting questions: Questions for BIS for the public briefing may be submitted in writing to BIS_briefingquestions@bis.doc.gov no later than November 1, 2023. Please tag the questions submitted by adding “Public Briefing on AC/S and SME IFRs,” along with a brief description of the question, e.g., 744.23, AI, or SME, in the subject line.

Recording: Within 7 business days after this public briefing is completed, BIS will add a link to a recording, including captioning, of the public briefing to make the recording accessible to people with disabilities.

FOR FURTHER INFORMATION CONTACT: Karen Nies-Vogel, Director, Office of Exporter Services, Bureau of Industry and Security, Department of Commerce, phone: (202) 482-0436, email: BIS_briefingquestions@bis.doc.gov. For emails, include “Public Briefing on AC/S and SME IFRs” in the subject line.

SUPPLEMENTARY INFORMATION:

Background

On October 7, 2022, BIS released the interim final rule (IFR) “Implementation of Additional Export Controls: Certain Advanced Computing and Semiconductor Manufacturing Items; Supercomputer and Semiconductor End Use; Entity List Modification” (October 7 IFR) (87 FR 62186), which amended the Export Administration Regulations (EAR) to implement controls on advanced computing integrated circuits (ICs), computer commodities that contain such ICs, and certain semiconductor manufacturing items, and to make other EAR changes to implement appropriate related controls, including on certain “U.S. person” activities.

In October 2023, BIS took further regulatory actions to address the national security and foreign policy concerns identified in the October 7 IFR. Specifically, on October 25, 2023, BIS is publishing in the **Federal Register** two interim final rules, “Implementation of Additional Export Controls: Certain Advanced Computing Items; Supercomputer and Semiconductor End Use; Updates and Corrections” and “Export Controls on Semiconductor Manufacturing Items,” which were both filed for public inspection at the **Federal Register** on October 18, 2023. BIS published an