

New Actions Required by This AD**New Service Bulletin Revision**

(i) As of the effective date of this AD, use only the Accomplishment Instructions of Boeing Service Bulletin 737-24A1141, Revision 3, dated February 20, 2008, to do all the applicable actions required by paragraph (f) of this AD.

Additional Operational Test

(j) For airplanes on which the actions required by paragraph (f) of this AD have been done in accordance with Boeing Service Bulletin 737-24A1141, Revision 2, dated December 1, 2005, before the effective date of this AD: Within 12 months after the effective date of this AD, do an operational test of the P5-14 panel in accordance with paragraphs 3.B.92. and 3.B.93., as applicable, of the Accomplishment Instructions of Boeing Service Bulletin 737-24A1141, Revision 3, dated February 20, 2008.

Alternative Methods of Compliance (AMOCs)

(k)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Binh Tran, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6485; fax (425) 917-6590; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(3) AMOCs approved previously in accordance with AD 2006-10-17 are approved as AMOCs for the corresponding provisions of this AD.

Issued in Renton, Washington, on October 20, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-25990 Filed 10-30-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-1141; Directorate Identifier 2008-NM-025-AD]

RIN 2120-AA64

Airworthiness Directives; BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During removal of forward and aft wing links, corrosion has been found on the wing links and the wing link attachment bolts in areas that are not readily accessible during the currently required Maintenance Review Board Report (MRBR) zonal inspections or Corrosion Prevention and Control Programme (CPCP) inspections. If left uncorrected, such corrosion could adversely affect the structural integrity of the wing to fuselage joint.

* * * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by December 1, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton,

Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-1141; Directorate Identifier 2008-NM-025-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2007-0303, dated December 14, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

During removal of forward and aft wing links, corrosion has been found on the wing links and the wing link attachment bolts in areas that are not readily accessible during the currently required Maintenance Review Board Report (MRBR) zonal inspections or Corrosion Prevention and Control Programme (CPCP) inspections. If left uncorrected, such corrosion could adversely affect the structural integrity of the wing to fuselage joint.

For this reason, this Airworthiness Directive (AD) requires repetitive detailed visual inspections at the forward and aft wing links and wing link attachment bolts for signs of corrosion, replacement of corroded nuts and bolts and repair of any defects.

The MRBR and CPCP will be amended to include the repeat inspections. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

The manufacturer has issued BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53-203, dated May 7, 2007. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a **Note** within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 1 product of U.S. registry. We also estimate that it would take about 20 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$1,600.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

BAE Systems (Operations) Limited (Formerly British Aerospace Regional Aircraft): Docket No. FAA-2008-1141; Directorate Identifier 2008-NM-025-AD.

Comments Due Date

- (a) We must receive comments by December 1, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to BAE Systems (Operations) Limited Model BAe 146-100A, -200A, and -300A series airplanes and Avro

146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes, certificated in any category, all models, all serial numbers.

Subject

- (d) Air Transport Association (ATA) of America Code 53: Fuselage.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: During removal of forward and aft wing links, corrosion has been found on the wing links and the wing link attachment bolts in areas that are not readily accessible during the currently required Maintenance Review Board Report (MRBR) zonal inspections or Corrosion Prevention and Control Programme (CPCP) inspections. If left uncorrected, such corrosion could adversely affect the structural integrity of the wing to fuselage joint.

For this reason, this Airworthiness Directive (AD) requires repetitive detailed visual inspections at the forward and aft wing links and wing link attachment bolts for signs of corrosion, replacement of corroded nuts and bolts and repair of any defects.

The MRBR and CPCP will be amended to include the repeat inspections.

Actions and Compliance

(f) Unless already done, do the following actions: Before accumulating 48 months on the wing link since new, or within 48 months of a wing link being repaired in accordance with a BAE Systems (Operations) Ltd. or EASA approved repair scheme, or within 24 months after the effective date of this AD, whichever occurs latest, and thereafter at intervals not to exceed 48 months, inspect the wing links in accordance with paragraph 2.C. of BAE Systems (Operations) Ltd. Inspection Service Bulletin ISB.53-203, dated May 7, 2007.

(1) If any corrosion is found on bolts or nuts, replace the affected bolts and nuts with airworthy parts before next flight in accordance with the service bulletin.

(2) If any corrosion to the wing links is found during an inspection, repair before further flight in accordance with a method approved in accordance with EASA (or its delegated agent).

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-114, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Todd Thompson, Aerospace Engineer, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the

FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2007-0303, dated December 14, 2007, and BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53-203, dated May 7, 2007, for related information.

Issued in Renton, Washington, on October 20, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E8-25999 Filed 10-30-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-1142; Directorate Identifier 2008-NM-060-AD]

RIN 2120-AA64

Airworthiness Directives; Hawker Beechcraft Corporation Model MU-300-10 Airplanes and Model 400 and 400A Series Airplanes; and Raytheon (Mitsubishi) Model MU-300 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede an existing airworthiness directive (AD) that applies to certain BEECH Model 400, 400A, and MU-300-10 airplanes. The existing AD currently requires installation of an improved adjustment mechanism on the flightcrew seats and replacement of the existing aluminum seat reinforcement assemblies with steel assemblies. This proposed AD would add airplanes to the applicability of the existing AD. This proposed AD results from reports of incomplete latching of the existing adjustment mechanism and cracked reinforcement assemblies, which could

result in sudden shifting of a flightcrew seat. We are proposing this AD to prevent sudden shifting of a flightcrew seat, which could impair the flightcrew's ability to control the airplane.

DATES: We must receive comments on this proposed AD by December 15, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal*: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax*: 202-493-2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Hawker Beechcraft Corporation, 9709 East Central, Wichita, Kansas 67206.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

William Griffith, Aerospace Engineer, Airframe Branch, ACE-118W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4116; fax (316) 946-4107.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-1142; Directorate Identifier 2008-NM-060-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy

aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On January 23, 1996, we issued AD 96-03-07, amendment 39-9504 (61 FR 5275, February 12, 1996), for certain BEECH Model 400, 400A, and MU-300-10 airplanes. That AD requires installation of an improved adjustment mechanism on the flightcrew seats and replacement of the existing aluminum seat reinforcement assemblies with steel assemblies. That AD resulted from reports of incomplete latching of the existing latching adjustment mechanism and cracked reinforcement assemblies. We issued that AD to prevent such shifting of a flightcrew seat, which could impair the flightcrew's ability to control the airplane.

Actions Since Existing AD Was Issued

Since we issued AD 96-03-07, we have determined that the same unsafe condition addressed in AD 96-03-07 could exist on Raytheon (Mitsubishi) Model MU-300 airplanes. Therefore, these additional airplanes must be added to the applicability of AD 96-03-07.

Relevant Service Information

We have reviewed Raytheon Mandatory Service Bulletin SB 25-2536, Revision 2, dated March 2002. The actions described in Revision 2 of the service bulletin are essentially the same as those specified in Beechcraft Service Bulletin 2536, Revision 1, dated April 1995 (we referred to Revision 1 as the appropriate source of service information for doing the actions required by AD 96-03-07). Revision 2 adds airplanes and certain kit numbers. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to develop on other airplanes of the same type design. For this reason, we are proposing this AD, which would supersede AD 96-03-07 and would retain the requirements of