

Restatement of Requirements of AD 2008–06–24, With New Service Information*Inspection and Related Investigative/Corrective Actions if Necessary*

(g) For airplanes identified in Boeing Special Attention Service Bulletin 737–35–1099, dated April 9, 2007: Within 60 months after April 23, 2008 (the effective date of AD 2008–06–24), do a general visual inspection to determine the manufacturer and manufacture date of the oxygen masks in the passenger service unit and the lavatory and attendant box assemblies, and do the applicable corrective action and other specified action, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737–35–1099, dated April 9, 2007; or Revision 1, dated April 23, 2009; except where these service bulletins specify repairing the oxygen mask assembly, replace it with a new or modified oxygen mask assembly having an improved flow indicator. The corrective action and other specified action must be done before further flight. As of the effective date of this AD, use only Revision 1 of Boeing Special Attention Service Bulletin 737–35–1099.

New Requirements of This AD*Inspection and Related Investigative/Corrective Actions if Necessary*

(h) For airplanes other than those identified in paragraph (g) of this AD: Within 60 months after the effective date of this AD, do a general visual inspection to determine the manufacturer and manufacture date of the oxygen masks in the passenger service unit and the lavatory and attendant box assemblies, and do the applicable corrective action and other specified action, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737–35–1099, Revision 1, dated April 23, 2009; except where this service bulletin specifies repairing the oxygen mask assembly, replace it with a new or modified oxygen mask assembly having an improved flow indicator. The corrective action and other specified action must be done before further flight.

Note 1: Boeing Special Attention Service Bulletin 737–35–1099, dated April 9, 2007; and Revision 1, dated April 23, 2009; refer to B/E Aerospace Service Bulletin 174080–35–01, dated February 6, 2006; Revision 1, dated May 1, 2006; and Revision 2, dated May 28, 2008; as additional sources of guidance for modifying the oxygen mask assembly by replacing the flow indicator with an improved flow indicator.

Parts Installation

(i) As of the effective date of this AD, no person may install a B/E Aerospace oxygen mask assembly having a part number in the 174080 series or 174095 series with a manufacturing date after January 1, 2002, and before March 1, 2006, on any airplane, unless it has been modified in accordance with the requirements of paragraph (h) of this AD.

Credit for Actions Done in Accordance With Previous Issue of the Service Bulletin

(j) Actions done before the effective date of this AD, in accordance with Boeing Special Attention Service Bulletin 737–35–1099, dated April 9, 2007, are acceptable for compliance with the requirements of paragraphs (g) and (h) of this AD.

Alternative Methods of Compliance (AMOCs)

(k)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Nicholas Wilson, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM–150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone (425) 917–6476; fax (425) 917–6590. Or, e-mail information to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

Material Incorporated by Reference

(l) You must use Boeing Special Attention Service Bulletin 737–35–1099, dated April 9, 2007; or Boeing Special Attention Service Bulletin 737–35–1099, Revision 1, dated April 23, 2009; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Boeing Special Attention Service Bulletin 737–35–1099, Revision 1, dated April 23, 2009, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The Director of the Federal Register previously approved the incorporation by reference of Boeing Special Attention Service Bulletin 737–35–1099, dated April 9, 2007, on April 23, 2008 (73 FR 14666, March 19, 2008).

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H–65, Seattle, Washington 98124–2207; telephone 206–544–5000, extension 1, fax 206–766–5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane

Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on June 18, 2010.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010–15816 Filed 6–30–10; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2010–0637; Directorate Identifier 2009–NM–062–AD; Amendment 39–16345; AD 2009–15–16]

RIN 2120–AA64

Airworthiness Directives; McDonnell Douglas Corporation Model DC–9–10 Series Airplanes, DC–9–30 Series Airplanes, DC–9–81 (MD–81) Airplanes, DC–9–82 (MD–82) Airplanes, DC–9–83 (MD–83) Airplanes, DC–9–87 (MD–87) Airplanes, MD–88 Airplanes, and MD–90–30 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: This document publishes in the **Federal Register** an amendment adopting airworthiness directive (AD) 2009–15–16 that was sent previously to all known U.S. owners and operators of the McDonnell Douglas Corporation airplanes identified above by individual notices. This AD requires modifying the flight deck door. This AD is prompted by a report indicating that certain equipment of the flight deck door is defective. We are issuing this AD to prevent failure of this equipment, which could jeopardize flight safety.

DATES: This AD becomes effective July 6, 2010 to all persons except those persons to whom it was made immediately effective by AD 2009–15–16, which contained the requirements of this amendment.

The Director of the Federal Register approved the incorporation by reference

of a certain publication listed in the AD as of July 6, 2010.

We must receive comments on this AD by August 16, 2010.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact TIMCO Aerosystems, 815 Radar Road, Greensboro, NC 27410-6221; telephone 336-668-4410, extension 3063; fax 336-662-8330; Internet: <http://www.timco.aero>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Linda Haynes, Aerospace Engineer, COS—Certificate Management Branch, ACE-102A, FAA, Atlanta Aircraft Certification Office, 1701 Columbia Avenue, College Park, GA 30337; telephone 404-474-5525; fax 404-474-5606.

SUPPLEMENTARY INFORMATION: On July 15, 2009, we issued AD 2009-15-16, which applies to all McDonnell Douglas Model DC-9-10 series airplanes, DC-9-30 series airplanes, DC-9-81 (MD-81) airplanes, DC-9-82 (MD-82) airplanes, DC-9-83 (MD-83) airplanes, DC-9-87 (MD-87) airplanes, MD-88 airplanes, and MD-90-30 airplanes.

Background

We have received a report indicating that certain equipment of the flight deck door is defective. This condition, if not corrected, could result in failure of the equipment, which could jeopardize flight safety.

Relevant Service Information

We reviewed TIMCO Service Bulletin TSB-88-52-045, Revision E, dated November 6, 2008. The service bulletin describes procedures for correcting the defect in the flight deck door.

FAA's Determination and Requirements of This AD

Since the unsafe condition described is likely to exist or develop on other airplanes of the same type design, we issued AD 2009-15-16 to prevent failure of certain equipment of the flight deck door, which could jeopardize flight safety. The AD requires accomplishing the actions specified in the service information previously described.

We have determined that notice and opportunity for prior public comment on AD 2009-15-16 were contrary to the public interest, and good cause existed to make the AD effective immediately by individual notices issued on July 15, 2009, to all known U.S. owners and operators of McDonnell Douglas Model DC-9-10 series airplanes, DC-9-30 series airplanes, DC-9-81 (MD-81) airplanes, DC-9-82 (MD-82) airplanes, DC-9-83 (MD-83) airplanes, DC-9-87 (MD-87) airplanes, MD-88 airplanes, and MD-90-30 airplanes. These conditions still exist, and the AD is hereby published in the **Federal Register** as an amendment to section 39.13 of the Federal Aviation Regulations (14 CFR 39.13) to make it effective to all persons.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not provide you with notice and an opportunity to provide your comments before it becomes effective. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2010-0637; Directorate Identifier 2009-NM-062-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

AD 2009-15-16 McDonnell Douglas Corporation: Amendment 39-16345. Docket No. FAA-2010-0637; Directorate Identifier 2009-NM-062-AD.

Effective Date

(a) This AD becomes effective July 6, 2010, to all persons except those persons to whom it was made immediately effective by AD 2009-15-16, issued on July 15, 2009, which contained the requirements of this amendment.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all McDonnell Douglas Corporation Model DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, and DC-9-15F airplanes, Model DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, and DC-9-32F (C-9A, C-9B) airplanes, DC-9-81 (MD-81) airplanes, DC-9-82 (MD-82) airplanes, DC-9-83 (MD-83) airplanes, DC-9-87 (MD-87) airplanes, MD-88 airplanes, and MD-90-30 airplanes; certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 52: Doors.

Unsafe Condition

(e) This AD results from a report indicating that the current design of certain equipment of the flight deck door is defective. We are issuing this AD to prevent the failure of this equipment, which could jeopardize flight safety.

Compliance

(f) Comply with this AD within the compliance times specified, unless already done.

Installation

(g) Within 30 days after the effective date of this AD, modify the flight deck door, in accordance with TIMCO Service Bulletin TSB-88-52-045, Revision E, dated November 6, 2008.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Atlanta Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Linda Haynes, Aerospace Engineer, COS—Certificate Management Branch, ACE-102A, FAA, Atlanta Aircraft Certification Office, 1701 Columbia Avenue, College Park, GA 30337; telephone 404-474-5525; fax 404-474-5606.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector

(PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically refer to this AD.

Material Incorporated by Reference

(i) You must use TIMCO Service Bulletin TSB-88-52-045, Revision E, dated November 6, 2008, to do the actions required by this AD, unless the AD specifies otherwise. (The revision date of this document is identified only on the title page and page I of the document; no other page of the document contains this information.)

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact TIMCO Aerosystems, 815 Radar Road, Greensboro, NC 27410-6221; telephone 336-668-4410, extension 3063; fax 336-662-8330; *Internet*: <http://www.timco.aero>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on June 18, 2010.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-15656 Filed 6-30-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2009-0995; Directorate Identifier 2009-NM-123-AD; Amendment 39-16336; AD 2010-13-05]

Airworthiness Directives; Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700 & 701) Airplanes, Model CL-600-2D15 (Regional Jet Series 705) Airplanes, and Model CL-600-2D24 (Regional Jet Series 900) Airplanes

Correction

In rule document 2010-14979 beginning on page 35613 in the issue of Wednesday, June 23, 2010, make the following correction:

On page 35613, in the second column under the “DATES:” heading, in the first

line, “June 23, 2010” should read “July 28, 2010”.

[FR Doc. C1-2010-14979 Filed 6-30-10; 8:45 am]

BILLING CODE 1505-01-D

DEPARTMENT OF HOMELAND SECURITY**Coast Guard****33 CFR Part 165**

[Docket No. USCG-2010-0457]

RIN 1625-AA00

Safety Zone; Fixed Mooring Balls, South of Barbers Pt. Harbor Channel, Oahu, HI

AGENCY: Coast Guard, DHS.

ACTION: Temporary final rule.

SUMMARY: Due to the placement of six fixed mooring balls in an area south of Barbers Pt. Harbor Channel, the Coast Guard is establishing a temporary safety zone around the mooring balls. This safety zone is needed to protect persons and vessels from safety hazards associated with navigation in the area of the mooring balls. Entry into this zone would be prohibited unless specifically authorized by the Captain of the Port Upper Mississippi River or a designated representative.

DATES: This rule is effective from 6 a.m. on July 1, 2010 through 6 p.m. on July 21, 2010.

ADDRESSES: Documents indicated in this preamble as being available in the docket are part of docket USCG-2010-0457 and are available online by going to <http://www.regulations.gov>, inserting USCG-2010-0457 in the “Keyword” box, and then clicking “Search.” They are also available for inspection or copying at the Docket Management Facility (M-30), U.S. Department of Transportation, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or e-mail Lieutenant Commander Marcella Granquist, Waterways Management Division, U.S. Coast Guard Sector Honolulu, telephone 808-842-2600, e-mail Marcella.A.Granquist@uscg.mil. If you have questions on viewing or submitting material to the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone 202-366-9826.

SUPPLEMENTARY INFORMATION: