

free and reserve percentages, and establishment of a reserve pool. One of the primary purposes of establishing free and reserve percentages is to equilibrate supply and demand. If raisin markets are over-supplied with product, grower prices will decline.

Raisins are generally marketed at relatively lower price levels in the more elastic export market than in the more inelastic domestic market. This results in a larger volume of raisins being marketed and enhances grower returns. In addition, this system allows the U.S. raisin industry to be more competitive in export markets. crop year.

There are no known additional costs incurred by small handlers that are not incurred by large handlers. While the level of benefits of this rulemaking are difficult to quantify, the stabilizing effects of the volume regulations impact small and large handlers positively by helping them maintain and expand markets even though raisin supplies fluctuate widely from season to season. Likewise, price stability positively impacts small and large producers by allowing them to better anticipate the revenues their raisins will generate.

After consideration of all relevant material presented, including the information and recommendation submitted by the Committee, the comments received, and other available information, it is hereby found that this rule, as hereinafter set forth, will tend to effectuate the declared policy of the Act.

#### List of Subjects in 7 CFR Part 989

Grapes, Marketing agreements, Raisins, Reporting and recordkeeping requirements.

#### PART 989—RAISINS PRODUCED FROM GRAPES GROWN IN CALIFORNIA

Accordingly, the interim final rule amending 7 CFR part 989 which was published at 67 FR 52390 on August 12, 2002, is adopted as a final rule without change.

Dated: November 26, 2002.

A. J. Yates,

*Administrator, Agricultural Marketing Service.*

[FR Doc. 02-30583 Filed 12-2-02; 8:45 am]

BILLING CODE 3410-02-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2002-NM-271-AD; Amendment 39-12970; AD 2002-24-05]

RIN 2120-AA64

#### Airworthiness Directives; Boeing Model 727 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that is applicable to certain Boeing Model 727 series airplanes. This action requires detailed inspections to detect cracking and corrosion of the upper chord of the rear spar of the wing; and repair, if necessary. This action also requires detailed inspections to detect and permanently repair any cracking that has been previously repaired by stop-drilling. This action is necessary to prevent failure of the wing and fuel leaks in the airplane due to stress corrosion cracking of the upper chord of the rear spar. This action is intended to address the identified unsafe condition.

**DATES:** Effective December 18, 2002.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 18, 2002.

Comments for inclusion in the Rules Docket must be received on or before February 3, 2003.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-271-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: [9-anm-iarcomment@faa.gov](mailto:9-anm-iarcomment@faa.gov). Comments sent via fax or the Internet must contain "Docket No. 2002-NM-271-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box

3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2131; fax (425) 227-1181.

**SUPPLEMENTARY INFORMATION:** The FAA has received reports of spanwise stress corrosion cracking of the upper chord of the rear spar of the wing between Wing Butt Line (WBL) 70.5 and the wing tip. Investigation revealed that some cracks were up to 14 inches long. Further, one of the cracks was almost long enough to jeopardize the residual strength capability of the upper chord of the rear spar. Such cracking of the upper chord of the rear spar of the wing, if not corrected, could result in structural failure of the wing and fuel leaks in the airplane.

#### Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin (ASB) 727-57A0145, revision 2, dated October 24, 2002. That ASB describes procedures for performing repetitive external detailed inspections on airplanes specified as "Group 1" to detect cracking and corrosion of the upper chord of the rear spar of the wing, and repair, if necessary. The ASB also describes procedures for detecting and permanently repairing any cracking that was previously repaired by stop-drilling. Additionally, the ASB describes procedures to perform high-frequency eddy current inspections (HFEC) on "Group 1" airplanes to detect cracking and corrosion of the upper chord of the rear spar and corrective action. Further, the ASB describes procedures to perform external detailed inspections and HFEC inspections on "Group 1" airplanes to detect cracking and corrosion of other areas such as the lower chord of the rear spar and the upper and lower chords of the front spar. In addition, the ASB describes procedures for certain other airplanes specified as "Group 2" airplanes that include external detailed inspections and HFEC inspections of various areas to detect cracking and corrosion; and repair, if necessary. The ASB also describes repair procedures for minor surface defects, corrosion, and cracking.

### Explanation of the Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design, this AD is being issued to prevent failure of the wing and fuel leaks in the airplane due to stress corrosion cracking of the upper chord of the rear spar. This AD requires the following actions for airplanes designated as "Group 1" in Boeing Alert Service Bulletin 727-57A0145, revision 2, dated October 24, 2002:

- Repetitive external detailed inspections to detect cracking and corrosion of the upper chord of the rear spar of the wing,
- Repair of cracking and corrosion,
- External detailed inspections to detect any cracking that has been previously repaired by stop-drilling, and
- Permanent repair of any previously stop-drilled cracking.

### Clarification of Certain Repair Conditions

Operators should note that, although the alert service bulletin specifies that the manufacturer may be contacted for disposition of certain repair conditions, this AD requires that those conditions be accomplished per a method approved by the FAA, or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the FAA to make such findings.

### Interim Action

The actions required by this AD are considered to be interim action. The FAA is currently considering requiring additional actions specified in the alert service bulletin. However, the planned compliance time for the implementation of those actions is sufficiently long so that notice and opportunity for prior public comment will be practicable.

### Determination of Rule's Effective Date

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

### Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or

arguments as they may desire. Communications shall identify the rules docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-271-AD." The postcard will be date stamped and returned to the commenter.

### Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT

regulatory policies and procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT regulatory policies and procedures, a final regulatory evaluation will be prepared and placed in the rules docket. A copy of it, if filed, may be obtained from the rules docket at the location provided under the caption **ADDRESSES**.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**2002-24-05 Boeing:** Amendment 39-12970. Docket 2002-NM-271-AD.

**Applicability:** Model 727 series airplanes, serial numbers 1 through 1832 inclusive; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent structural failure of the wing and fuel leaks in the airplane due to stress corrosion cracking of the upper chord of the rear spar, accomplish the following:

### Inspection and Repair

(a) For airplanes specified as "Group 1" airplanes in Boeing Alert Service Bulletin 727-57A0145, revision 2, dated October 24, 2002: Within 20 years after the date of manufacture or within 90 days after the effective date of this AD, whichever occurs

later, perform an external detailed inspection for cracking, corrosion, and existing stop-drilled repairs of cracking in the upper chord on the rear spar from Wing Butt Line (WBL) 70.5 through WBL 249.3, per Boeing Alert Service Bulletin 727-57A0145, revision 2, paragraph 3.B, "Work Instructions," part 1, dated October 24, 2002. Thereafter, repeat the inspection at intervals not to exceed 2 years.

**Note 2:** For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, *etc.*, may be used. Surface cleaning and elaborate access procedures may be required."

(1) If no cracking, corrosion, or existing stop-drilled repairs of previous cracking is detected during any inspection required by this AD, repeat the inspection at intervals not to exceed 2 years.

(2) If any existing stop-drilled repairs of previous cracking are detected during any inspection required by this AD, before further flight, permanently repair the cracking per the alert service bulletin.

(3) If any cracking or corrosion is detected during any inspection required by this AD that is within the limits specified in the alert service bulletin, before further flight, repair per the alert service bulletin.

(4) If any cracking or corrosion is detected during any inspection required by this AD that exceeds the limits specified in the alert service bulletin, and the bulletin specifies to contact Boeing for appropriate action: Before further flight, repair per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved, the approval must specifically reference this AD.

#### Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

#### Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

#### Incorporation by Reference

(d) Except as specified in paragraph (a)(4) of this AD, the actions shall be done in accordance with Boeing Alert Service Bulletin 727-57A0145, revision 2, dated October 24, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

#### Effective Date

(e) This amendment becomes effective on December 18, 2002.

Issued in Renton, Washington, on November 20, 2002.

**Ali Bahrami,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 02-30344 Filed 12-2-02; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2001-NM-192-AD; Amendment 39-12967; AD 2002-24-02]

**RIN 2120-AA64**

#### Airworthiness Directives; Boeing Model 757-200 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 757-200 series airplanes, that requires repetitive inspections for fatigue cracking of certain areas of the forward and aft frames of the cargo doorways and repair, if necessary. The actions specified by this AD are intended to find and fix such cracking, which could lead to rapid depressurization of the airplane and result in reduced structural integrity of the cargo doorway. This action is intended to address the identified unsafe condition.

**DATES:** Effective January 7, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 7, 2003.

**ADDRESSES:** The service information referenced in this AD may be obtained from Boeing Commercial Airplane

Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### FOR FURTHER INFORMATION CONTACT:

Dennis Stremick, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2776; fax (425) 227-1181.

#### SUPPLEMENTARY INFORMATION:

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 757-200 series airplanes was published in the **Federal Register** on July 12, 2002 (67 FR 46132). That action proposed to require repetitive inspections for fatigue cracking of certain areas of the forward and aft frames of the cargo doorways, and repair, if necessary.

#### Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received. One commenter states that the proposed AD does not apply to its fleet.

#### Request To Change Certain Terminology

One commenter states that the terminology throughout the proposed AD which reads, "cargo door frame(s)" should be changed to "cargo doorway frames." The commenter notes that the structures requiring the inspections are the cutout fuselage frames of the cargo door and not the cargo door frames. The commenter adds that the term "cargo doorway," as specified in Boeing Alert Service Bulletin 757-53A0080, dated February 3, 2000 (referenced in the proposed AD as the appropriate source of service information for accomplishment of the actions), is a better description.

We agree with the commenter in that the description of the frames of the cargo door should be clarified. We have changed the description throughout this final rule to read, "cargo doorway."

#### Explanation of Editorial Change

We have changed the service bulletin citation throughout this final rule to exclude the Evaluation Form. (The form is intended to be completed by operators and submitted to the