

Bulletin No. 01.00.56 R1) dated June 17, 1999, which describes procedures for verifying that the valve will correctly open and close in each engine fuel filter and conducting a filter clogging warning test on helicopters with certain fuel filters installed.

Since an unsafe condition has been identified that is likely to exist or develop on other Eurocopter France Model AS 332C, L, L1, and L2 helicopters of the same type designs, the proposed AD would supersede AD 99-13-02. In addition to the requirements in AD 99-13-02, the proposed AD would add a fuel filter, P/N 704A44620037, to the applicability. The actions are required to be accomplished in accordance with the service telex described previously.

The FAA estimates that one helicopter of U.S. registry would be affected by the proposed AD, that it would take approximately 3 work hours to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$180, assuming no valve would need to be replaced.

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part

39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-11195 (64 FR 32399, June 17, 1999) and by adding a new airworthiness directive (AD) to read as follows:

Eurocopter France: Docket No. 99-SW-78-AD. Supersedes AD 99-13-02, Amendment 39-11195, Docket No. 99-SW-17-AD.

Applicability: Eurocopter France Model AS 332C, L, L1, and L2 helicopters, with any of the following part-numbered fuel filters installed, certificated in any category:

Vendor Part No.	Eurocopter France Part No.
-4020P25	(704A44620031)
-4020P25-1	(704A44620034)
-4020P25-2	(704A44620035)
-4020P25-3	(704A44620036)
-4020P25-11	(704A44620037)

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent power loss due to fuel starvation, an engine flameout, and a subsequent forced landing, accomplish the following:

(a) Within 25 hours time-in-service (TIS) and after any subsequent flight during which either fuel filter clogged caution light illuminates:

(1) Verify that the fuel filter by-pass valve (valve) is correctly closed in each engine fuel filter in accordance with paragraph CC.1), Eurocopter France Service Telex 00087 (Service Bulletin No. 01.00.56 R1), dated June 17, 1999 (SB).

(2) After replacing both filter cartridges with airworthy filter cartridges, each helicopter may be operated on a one-time direct flight to a location where the requirements of paragraph (a) of this AD must be accomplished before further flight.

(3) Conduct a "filter" clogging warning test (test) in accordance with paragraphs CC.2), CC.2)A) and CC.2)B) of the SB.

(4) If a jammed valve (open or closed) is detected during the test, clean the valve in accordance with paragraph CC.2)B) of the SB or replace the valve with an airworthy valve. Repeat the requirements of paragraph (a)(3) of this AD.

(5) When the test result is satisfactory, repeat the requirements of paragraph (a)(1) of this AD.

(b) Within 25 hours TIS, insert a copy of this AD into the Rotorcraft Flight Manual (RFM) or make the following pen and ink addition to the RFM Emergency Procedure for fuel filter clogged caution light illumination: "If both fuel filter clogged caution lights illuminate, land as soon as practicable."

(c) If both filter clogged caution lights illuminate, after landing, either:

(1) Accomplish the requirements of paragraph (a) of this AD before further flight, or,

(2) Replace both filter cartridges with airworthy filter cartridges and conduct a one-time direct flight to a location where the requirements of paragraph (a) of this AD must be accomplished before further flight.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Manager, Regulations Group.

(e) Special flight permits will not be issued.

Note 3: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD's 1998-318-071(A)R2 and 1998-319-012(A)R2, both dated July 28, 1999.

Issued in Fort Worth, Texas, on April 7, 2000.

Henry A. Armstrong,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 00-9360 Filed 4-13-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-351-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to certain Airbus Model A319, A320, and A321 series airplanes, that currently requires revising the FAA-approved Airplane Flight Manual (AFM) to increase monitoring of the flight path of the airplane to detect certain software anomalies of the flight management guidance system, and take appropriate corrective actions. This proposed AD would add a requirement to either modify the existing on-board replaceable modules of the flight management guidance computers (FMGC) to incorporate software changes, or replace the FMGC's with new, improved FMGC's; which would terminate the requirements for the AFM revision. This proposal is prompted by the issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent erroneous navigational calculations, which could result in an increased risk of collision with terrain or other airplanes.

DATES: Comments must be received by May 15, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-351-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such

written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-351-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-351-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On October 9, 1997, the FAA issued AD 97-21-10, amendment 39-10163 (62 FR 53939, October 17, 1997), applicable to certain Airbus Model A319, A320, and A321 series airplanes, to require revising the FAA-approved Airplane Flight Manual to increase monitoring of the flight path of the airplane to detect certain software anomalies of the flight management guidance system (FMGS), and take appropriate corrective actions. That action was prompted by the issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The requirements of that AD are intended to ensure that the flightcrew detects and corrects an unintended flight path if certain software anomalies of the FMGS occur, which could result in an increased risk of collision with terrain or other airplanes.

Actions Since Issuance of Previous Rule

In the preamble to AD 97-21-10, the FAA specified that the actions required by that AD were considered "interim

action" until final action was identified, at which time further rulemaking action would be considered. Since the issuance of that AD, the Direction Generale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, advises that a new standard of the flight management guidance computer (FMGC) includes software changes that improve navigational guidance calculations. The FAA now has determined that further rulemaking action is indeed necessary to require either the modification of all existing on-board replaceable modules of the FMGC's to incorporate software changes, or replacement of all existing FMGC's with new, improved FMGC's, in order to address the unsafe condition and ensure the continued safe operation of those airplanes. This proposed AD follows from that determination and allows opportunity for public comment.

Explanation of Relevant Service Information

Airbus has issued the following service bulletins:

- A320-22-1063, Revision 01, dated October 8, 1999.
- A320-22-1064, dated September 15, 1998.
- A320-22-1065, dated October 28, 1998.
- A320-22-1067, Revision 01, dated July 7, 1999.
- A320-22-1068, dated December 9, 1998.
- A320-22-1069, dated February 1, 1999.

These service bulletins describe procedures for either the modification of all existing on-board replaceable modules of the FMGC's to incorporate software changes, or the replacement of all existing FMGC's with new, improved FMGC's. The DGAC classified these service bulletins as mandatory and issued French airworthiness directive 1999-411-140(B), dated October 20, 1999, in order to assure the continued airworthiness of these airplanes in France.

FAA's Conclusions

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this

type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would supersede AD 97-21-10 to continue to require a revision to the Airplane Flight Manual (AFM) to increase monitoring of the flight path of the airplane to detect certain software anomalies of the flight management guidance system, and take appropriate corrective actions. This proposed AD would add a requirement to either modify all existing on-board replaceable modules of the FMGC's to incorporate software changes, or replace all existing FMGC's with new, improved FMGC's; which would terminate the requirements for the AFM revision. The actions would be required to be accomplished in accordance with the service bulletins described previously, as applicable.

This proposed AD also would limit the applicability of the existing AD to airplanes on which a certain modification has been installed or service bulletin has been accomplished, and excludes airplanes on which another modification has been installed or service bulletin has been accomplished.

Other Relevant Rulemaking

The FAA previously has issued AD 98-19-08, amendment 39-10750 (63 FR 50503, September 22, 1998), applicable to certain Airbus Model A321 series airplanes. AD 98-19-08 requires revising the AFM to prohibit automatic landings and Category III operations on runways with a magnetic orientation of 170 degrees through 190 degrees inclusive. That amendment provides optional terminating action for the AFM revision.

The modification or replacement action that would be required by this

proposed AD constitutes terminating action for the AFM requirements of AD 98-19-08.

Cost Impact

There are approximately 200 Airbus Model A319, A320, and A321 series airplanes of U.S. registry that would be affected by this proposed AD.

The actions that are currently required by AD 97-21-10 and retained in this AD take approximately 1 work hour per airplane to accomplish, at an average labor rate of \$60 per work hour. Required parts would be provided by the manufacturer at no charge to the operators. Based on these figures, the cost impact of the currently required actions on U.S. operators is estimated to be \$60 per airplane.

The new actions that are proposed in this AD action would take approximately 1 work hour per airplane to accomplish, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the proposed requirements of this AD on U.S. operators is estimated to be \$12,000, or \$60 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the current or proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44

FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-10163 (62 FR 53939, October 17, 1997), and by adding a new airworthiness directive (AD), to read as follows:

Airbus Industrie: Docket 99-NM-351-AD. Supersedes AD 97-21-10, Amendment 39-10163.

Applicability: Model A319, A320, and A321 series airplanes; certificated in any category; on which any of the Airbus modifications has been installed or any of the Airbus service bulletins has been accomplished, as listed in the following table; except those airplanes on which Airbus Modification 26716, 26799, 26968, or 27831 has been installed; or except those airplanes on which Airbus Service Bulletin A320-22-1063, A320-22-1064, A320-22-1065, A320-22-1067, A320-22-1068, or A320-22-1069 has been accomplished:

Affected model(s)	Airbus modification installed
A319 and A321	25469 (reference Airbus Service Bulletin A320-22-1054).
A319, A320, and A321	26093.
A320	24065 (reference Airbus Service Bulletin A320-22-1040) or 24067 (reference Airbus Service Bulletin A320-22-1039).
A320	25314 (reference Airbus Service Bulletin A320-22-1051) or 25315 (reference Airbus Service Bulletin A320-22-1050).
A320 and A321	24064 (reference Airbus Service Bulletin A320-22-1034) or 24066 (reference Airbus Service Bulletin A320-22-1029).
A320 and A321	25199 (reference Airbus Service Bulletin A320-22-1045) or 25200 (reference Airbus Service Bulletin A320-22-1046).
A320 and A321	25240 (reference Airbus Service Bulletin A320-22-1033) or 25274 (reference Airbus Service Bulletin A320-22-1056).
A319, A320, and A321	26243.

Affected model(s)	Airbus modification installed
A319 and A320	26717.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent erroneous navigational calculations, which could result in an increased risk of collision with terrain or other airplanes, accomplish the following:

Restatement of Requirements of AD 97-21-10

(a) Within 10 days after November 3, 1997 (the effective date of AD 97-21-10, amendment 39-10163), revise the Normal Procedures Section of the FAA-approved Airplane Flight Manual (AFM) by inserting a copy of Model A319/320/321 Flight Manual Temporary Revision 4.03.00/02, dated May 28, 1997, into the AFM.

Note 2: When the temporary revision specified in paragraph (a) of this AD has been incorporated into the general revisions of the AFM, the general revisions may be inserted in the AFM, provided the information contained in the general revisions is identical to that specified in Model A319/320/321 Flight Manual Temporary Revision 4.03.00/02.

New Requirements of This AD

(b) Within 18 months after the effective date of this AD, accomplish either paragraph (b)(1) or (b)(2) of this AD, in accordance with Airbus Service Bulletin A320-22-1063, Revision 01, dated October 8, 1999; A320-22-1064, dated September 15, 1998; A320-22-1065, dated October 28, 1998; A320-22-1067, Revision 01, dated July 7, 1999; A320-22-1068, dated December 9, 1998; or A320-22-1069, dated February 1, 1999; as applicable. Following accomplishment of either paragraph (b)(1) or (b)(2) of this AD, the AFM revision required by paragraph (a) of this AD may be removed from the AFM.

(1) Modify all existing on-board replaceable modules of the flight management guidance computers (FMGC) to

incorporate software changes in accordance with the Accomplishment Instructions of the applicable service bulletin.

(2) Replace all existing FMGC's with new, improved FMGC's in accordance with the Accomplishment Instructions of the applicable service bulletin.

(c) Accomplishment of either the modification or replacement action required by paragraph (b) of this AD constitutes terminating action for the AFM requirements of paragraph (a) of AD 98-19-08, amendment 39-10750. Following accomplishment of either of those actions, remove the FAA-approved AFM revision required by that AD (Airbus A319/320/321 Airplane Flight Manual Temporary Revision 9.99.99/44, Issue 2, dated March 3, 1998).

Spares

(d) As of the effective date of this AD, no person shall install any FMGC part number B546BAM0205, B546CAM0101, B546BCM0204, B398BAM0207, B398AAM0410, B546CCM0101, B546CCM0102, B546CCM0103, or B398BCM0107; unless it has been modified in accordance with this AD.

Alternative Methods of Compliance

(e)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

(2) Alternative methods of compliance, approved previously in accordance with AD 97-21-10, amendment 39-10163, are approved as alternative methods of compliance with paragraph (a) of this AD.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(f) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in French airworthiness directive 1999-411-140(B), dated October 20, 1999.

Issued in Renton, Washington, on April 10, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 00-9361 Filed 4-13-00; 8:45 am]

BILLING CODE 4910-13-U

FEDERAL TRADE COMMISSION

16 CFR Part 423

Request for Comments Concerning Trade Regulation Rule on Care Labeling of Textile Wearing Apparel and Certain Piece Goods

AGENCY: Federal Trade Commission.

ACTION: Request for public comments.

SUMMARY: The Federal Trade Commission (the "Commission") is requesting public comments on a proposed exemption to its Trade Regulation Rule on Care Labeling of Textile Wearing Apparel and Certain Piece Goods ("the Care Labeling Rule" or "the Rule"). The proposed exemption would permit the Esprit de Corp company to distribute three specific styles of apron camisoles without attaching permanent care labels to the garments, as otherwise required by the Care Labeling Rule. Esprit de Corp petitioned the Commission for the exemption, and submitted samples of the camisoles for consideration. If the petition is granted, care instructions for the camisoles still must be given on a hang tag, or on the package, or in some other conspicuous place, so that consumers will be able to see the care information before buying the product. All interested persons are hereby given notice of the opportunity to submit written data, views and arguments concerning this proposal.

DATES: Written comments will be accepted until May 15, 2000.

ADDRESSES: Comments should be directed to: Secretary, Federal Trade Commission, Room H-159, 600 Pennsylvania Ave., NW, Washington, DC 20580. Comments about this exemption to the Care Labeling Rule