

PART 94—RINDERPEST, FOOT-AND-MOUTH DISEASE, FOWL PEST (FOWL PLAGUE), EXOTIC NEWCASTLE DISEASE, AFRICAN SWINE FEVER, CLASSICAL SWINE FEVER, AND BOVINE SPONGIFORM ENCEPHALOPATHY: PROHIBITED AND RESTRICTED IMPORTATIONS

1. The authority citation for part 94 continues to read as follows:

Authority: 7 U.S.C. 450, 7701–7772, 7781–7786, and 8301–8317; 21 U.S.C. 136 and 136a; 31 U.S.C. 9701; 7 CFR 2.22, 2.80, and 371.4.

2. Section 94.4 is amended as follows:

a. In paragraph (b)(7), by removing the citation “§ 94.4(b)(4) or (b)(5)” and adding the words “paragraph (b)(4) or (b)(5) of this section” in its place.

b. By redesignating paragraphs (b)(8) and (b)(9) as paragraphs (b)(9) and (b)(10), respectively, and adding a new paragraph (b)(8) to read as set forth below.

c. In newly redesignated paragraph (b)(9)(ii), by removing the citation “(b)(8)(i)” and adding the citation “(b)(9)(i)” in its place.

§ 94.4 Cured or cooked meat from regions where rinderpest or foot-and-mouth disease exists.

* * * * *

(b) * * *

(8) *Pork rind pellets (pork skins).* Pork rind pellets (pork skins) must be cooked in one of the following ways:

(i) *One-step process.* The pork skins must be cooked in oil for at least 80 minutes when oil temperature is consistently maintained at a minimum of 114 °C.

(ii) *Two-step process.* The pork skins must be dry-cooked at 260 °C for approximately 210 minutes after which they must be cooked in hot oil (deep-fried) at 104 °C for an additional 150 minutes.

* * * * *

3. Section 94.8 is amended as follows:

a. By redesignating paragraph (a)(4) as paragraph (a)(5), and by adding a new paragraph (a)(4) to read as set forth below.

b. In paragraph (a)(3)(i), by removing the citation “(a)(4)” and adding the words “(a)(5) of this section” in its place.

§ 94.8 Pork and pork product from regions where African swine fever exists or is reasonably believed to exist.

* * * * *

(a) * * *

(4) The pork product is pork rind pellets (pork skins) that were cooked in one of the following ways in an establishment that meets the

requirements in paragraph (a)(5) of this section:

(i) *One-step process.* The pork skins must be cooked in oil for at least 80 minutes when oil temperature is consistently maintained at a minimum of 114 °C.

(ii) *Two-step process.* The pork skins must be dry-cooked at a minimum of 260 °C for approximately 210 minutes after which they must be cooked in hot oil (deep-fried) at a minimum of 104 °C for an additional 150 minutes.

* * * * *

4. Section 94.9 is amended as follows:

a. By adding a new paragraph (c)(1)(iv) to read as set forth below.

b. In paragraph (c)(2), by removing the citation “(c)(1)(ii) or (iii)” and adding the citation “(c)(1)(ii), (iii), or (iv)” in its place.

c. In paragraph (c)(3), by removing the citation “(c)(1)(ii) or (iii)” both places it occurs and adding the words “(c)(1)(ii), (iii), or (iv) of this section” in its place.

§ 94.9 Pork and pork products from regions where classical swine fever exists.

* * * * *

(c) * * *

(1) * * *

(iv) Pork rind pellets (pork skins) originating in regions where classical swine fever is known to exist may be imported into the United States provided they have been cooked in one of the following ways:

(A) *One-step process.* The pork skins must be cooked in oil for at least 80 minutes when oil temperature is consistently maintained at a minimum of 114 °C.

(B) *Two-step process.* The pork skins must be dry-cooked at a minimum of 260 °C for approximately 210 minutes after which they must be cooked in hot oil (deep-fried) at a minimum of 104 °C for an additional 150 minutes.

* * * * *

5. In § 94.12, a new paragraph

(b)(1)(vi) is added to read as follows:

§ 94.12 Pork and pork products from regions where swine vesicular disease exists.

* * * * *

(b) * * *

(1) * * *

(vi) Pork rind pellets (pork skins) must be cooked in one of the following ways:

(A) *One-step process.* The pork skins must be cooked in oil for at least 80 minutes when oil temperature is consistently maintained at a minimum of 114 °C.

(B) *Two-step process.* The pork skins must be dry-cooked at a minimum of 260 °C for approximately 210 minutes

after which they must be cooked in hot oil (deep-fried) at a minimum of 104 °C for an additional 150 minutes.

* * * * *

Done in Washington, DC, this 26th day of June 2008.

Kevin Shea,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. E8–15014 Filed 7–1–08; 8:45 am]

BILLING CODE 3410–34–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2008–0730; Directorate Identifier 2008–NM–055–AD]

RIN 2120–AA64

Airworthiness Directives; Bombardier Model DHC–8–400, DHC–8–401, and DHC–8–402 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

All DHC–8 Series 400 aircraft have had a spoiler fuselage cable disconnect sensing system installed in production. Subsequently it was discovered that, in the event of a spoiler fuselage cable disconnect, only the ROLL SPLR INBD HYD caution light will be illuminated until the aircraft speed decreases below 165 kts [knots], at which time the ROLL SPLR OUTBD HYD caution light will also be illuminated. In the event of a spoiler fuselage cable disconnect in association with the existing indications described above, the reduction in roll authority could result in increased pilot workload during approach and landing.

* * * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by August 1, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Parrillo, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7305; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0730; Directorate Identifier 2008-NM-055-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2008-13, dated February 14, 2008 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

All DHC-8 Series 400 aircraft have had a spoiler fuselage cable disconnect sensing system installed in production. Subsequently it was discovered that, in the event of a spoiler fuselage cable disconnect, only the ROLL SPLR INBD HYD caution light will be illuminated until the aircraft speed decreases below 165 kts [knots], at which time the ROLL SPLR OUTBD HYD caution light will also be illuminated. In the event of a spoiler fuselage cable disconnect in association with the existing indications described above, the reduction in roll authority could result in increased pilot workload during approach and landing.

Modsums 4-110066 and 4-126356 (each applicable to a different batch of aircraft serial numbers) have been issued to rework the sensing circuit caution light indication to ensure that it is consistent for spoiler fuselage cable disconnects above and below 165 kts. Modsum 4-126356 has been installed in production on aircraft serial numbers 4130 and subsequent. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Bombardier has issued Service Bulletin 84-27-33, dated June 6, 2007; and Service Bulletin 84-27-28, Revision B, dated September 25, 2007. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are

highlighted in a NOTE within the proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 20 products of U.S. registry. We also estimate that it would take about 10 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$2,339 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$62,780, or \$3,139 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Bombardier, Inc. (Formerly de Havilland, Inc.): Docket No. FAA-2008-0730; Directorate Identifier 2008-NM-055-AD.

Comments Due Date

(a) We must receive comments by August 1, 2008.

Affected ADs

(b) None.

Applicability

(c) Bombardier Model DHC-8-400, DHC-8-401 and DHC-8-402 airplanes, serial numbers 4003, 4004, 4006, and 4008 through 4129, certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 27: Flight Controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

All DHC-8 Series 400 aircraft have had a spoiler fuselage cable disconnect sensing system installed in production. Subsequently it was discovered that, in the event of a spoiler fuselage cable disconnect, only the ROLL SPLR INBD HYD caution light will be illuminated until the aircraft speed decreases below 165 kts [knots], at which time the ROLL SPLR OUTBD HYD caution light will also be illuminated. In the event of a spoiler fuselage cable disconnect in association with the existing indications described above, the reduction in roll authority could result in increased pilot workload during approach and landing.

Modsums 4-110066 and 4-126356 (each applicable to a different batch of aircraft serial numbers) have been issued to rework the sensing circuit caution light indication to

ensure that it is consistent for spoiler fuselage cable disconnects above and below 165 kts. Modsum 4-126356 has been installed in production on aircraft serial numbers 4130 and subsequent.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) For airplanes with serial numbers 4003, 4004, 4006, and 4008 through 4094: Within 6,000 flight hours after the effective date of this AD, modify the spoiler cable disconnect sensing circuit by incorporating Modsum 4-110066 in accordance with Bombardier Service Bulletin 84-27-33, dated June 6, 2007.

(2) For airplanes with serial numbers 4095 through 4129: Within 6,000 flight hours after the effective date of this AD, modify the spoiler cable disconnect sensing circuit by incorporating Modsum 4-126356 in accordance with Bombardier Service Bulletin 84-27-28, Revision B, dated September 25, 2007.

(3) Installations of Modsum 4-126356 accomplished before the effective date of this AD according to Bombardier Service Bulletin 84-27-28, dated October 2, 2006; or Revision A, dated April 30, 2007; are considered acceptable for compliance with the corresponding action specified in this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Dan Parrillo, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7305; fax (516) 794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Canadian Airworthiness Directive CF-2008-13, dated February 14,

2008; and Bombardier Service Bulletins 84-27-33, dated June 6, 2007; and 84-27-28, Revision B, dated September 25, 2007; for related information.

Issued in Renton, Washington, on June 24, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-14964 Filed 7-1-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0676; Directorate Identifier 2007-NM-280-AD]

RIN 2120-AA64

Airworthiness Directives; Fokker Model F.28 Mark 0070 and 0100 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Service experience has shown that heavy MLG (main landing gear) shimmy vibration can occur due to faulty/empty dampers or due to excessive free play in the T/L (torque link) apex joint. In several cases this shimmy vibration resulted in a MLG main fitting failure * * * finally resulting in a collapse of the MLG causing extensive damage to the wingtip, aileron and flaps. * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by August 1, 2008.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-