

# Rules and Regulations

Federal Register

Vol. 71, No. 160

Friday, August 18, 2006

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2006-23884; Directorate Identifier 2006-CE-13-AD; Amendment 39-14726; AD 2006-17-05]

RIN 2120-AA64

#### Airworthiness Directives; Mitsubishi Heavy Industries MU-2B Series Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA adopts a new airworthiness directive (AD) for all Mitsubishi Heavy Industries (MHI) MU-2B series airplanes. This AD requires you to do flight checks of the rigging of the engine and propeller systems. This AD results from a recent safety evaluation that used a data-driven approach to evaluate the design, operation, and maintenance of the MU-2B series airplanes in order to determine their safety and define what steps, if any, are necessary for their safe operation. Part of that evaluation was the identification of unsafe conditions that exist or could develop on the affected type design airplanes. We are issuing this AD to detect and correct improper adjustment of the flight idle fuel flow setting. This condition, if uncorrected, could result in degraded performance and poor handling qualities with consequent loss of control of the airplane in certain situations.

**DATES:** This AD becomes effective on September 22, 2006.

As of September 22, 2006, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

**ADDRESSES:** To get the service information identified in this AD, contact Mitsubishi Heavy Industries America, Inc., 4951 Airport Parkway, Suite 800, Addison, Texas 75001; telephone: (972) 934-5480; facsimile: (972) 934-5488.

To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2006-23884; Directorate Identifier 2006-CE-13-AD.

**FOR FURTHER INFORMATION CONTACT:** Rao Edupuganti, Aerospace Engineer, ASW-150, Fort Worth Aircraft Certification Office, 2601 Meacham Blvd., Fort Worth, Texas 76193; telephone: (817) 222-5284; facsimile: (817) 222-5960.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

On April 21, 2006, we issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all Mitsubishi Heavy Industries (MHI) MU-2B series airplanes. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on April 28, 2006 (71 FR 25117). The NPRM proposed to require you to do flight checks of the rigging of the engine and propeller systems.

##### Comments

We provided the public the opportunity to participate in developing this AD. The following presents the comments received on the proposal and FAA's response to each comment:

##### *Comment Issue No. 1: Revise the Manufacturer Contact Information*

Ralph Sorrells, Deputy General Manager of Mitsubishi Heavy Industries America, Inc., requests that we revise the manufacturer contact information from Mitsubishi Heavy Industries in Nagoya, Japan, to Mitsubishi Heavy Industries America, Inc. in Addison, Texas.

We agree with the commenter and will incorporate the change into this final rule AD action.

##### *Comment Issue No. 2: Correct the Date of the Japanese AD*

Ralph Sorrells, Deputy General Manager of Mitsubishi Heavy Industries

America, Inc., requests that we correct the date of Japanese AD No. TCD 4890-98 from October 7, 1998, to November 4, 1998.

We agree with the commenter and will incorporate the change into this final rule AD action.

##### *Comment Issue No. 3: Remove Long-Body Models From Table 1, Paragraph (c)(1)*

The airplanes described in Table 1, paragraph (c)(1) are short-body airplanes. Models MU-2B-30, MU-2B-35, and MU-2B-36 are long-body airplanes.

Ralph Sorrells, Deputy General Manager of Mitsubishi Heavy Industries America, Inc., requests that we remove reference of the long-body airplanes from Table 1, paragraph (c)(1).

We agree with the commenter and will incorporate the change into this final rule AD action.

##### *Comment Issue No. 4: Remove the Requirement to Have the Flight Check Done by Two Individuals*

Richard W. Shine states that to require another pilot or mechanic to be on board in order to do the flight checks would require a specific flight just for that purpose. This requirement is unnecessarily burdensome and will add significant cost to their operation. The commenter states that he can and has successfully and safely performed the flight checks himself.

He requests that we remove the two-person flight check requirement.

We agree with the commenter that the flight checks required in paragraph (e) of the proposed AD can safely be conducted with one rated pilot. This procedure is consistent with the referenced service bulletin and current practices. We inadvertently added the requirement for two individuals to do this check.

We will incorporate the change into this final rule AD action and remove that requirement.

##### *Comment Issue No. 5: Add Procedures for Checking the Flight Idle Fuel Flow on the Ground*

Michael Machinski requests that we change the proposed AD to incorporate maintenance procedures for checking the flight idle fuel flow on the ground.

We do not agree with the commenter. Doing the flight idle flow check in flight is consistent with the referenced service

bulletins and current practices. The procedures in the service bulletins for doing this check have remained unchanged over the past 8 years.

Those procedures have proven to be good and acceptable; therefore, we are not changing the final rule AD action based on this comment.

**Conclusion**

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed except for the changes above and minor editorial corrections. We have determined that these changes and minor corrections:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and

- Do not add any additional burden upon the public than was already proposed in the NPRM.

**Costs of Compliance**

We estimate that this AD affects 397 airplanes in the U.S. registry.

We estimate the following costs to accomplish the initial flight check:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
1 work-hour × \$80 per hour = \$80 .....	Not applicable .....	\$80	\$31,760

The FAA is committed to updating the aviation community of expected costs associated with the MU-2B series airplane safety evaluation conducted in 2005. As a result of that commitment, the accumulating expected costs of all ADs related to the MU-2B series airplane safety evaluation may be found in the Final Report section at the following Web site: [http://www.faa.gov/aircraft/air\\_cert/design\\_approvals/small\\_airplanes/cos/mu2\\_foia\\_reading\\_library/](http://www.faa.gov/aircraft/air_cert/design_approvals/small_airplanes/cos/mu2_foia_reading_library/).

**Authority for this Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this AD.

**Regulatory Findings**

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD (and other information as included in the Regulatory Evaluation) and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "Docket No. FAA-2006-23884; Directorate Identifier 2006-CE-13-AD" in your request.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. FAA amends § 39.13 by adding a new AD to read as follows:

**2006-17-05 Mitsubishi Heavy Industries:**  
Amendment 39-14726; Docket No. FAA-2006-23884; Directorate Identifier 2006-CE-13-AD.

**Effective Date**

(a) This AD becomes effective on September 22, 2006.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD affects the following airplane models and serial numbers that are certificated in any category:

TABLE 1.—APPLICABILITY

Type certificate	Models	Serial Nos.
(1) A2PC .....	MU-2B, MU-2B-10, MU-2B-15, MU-2B-20, MU-2B-25, and MU-2B-26.	008 through 312, 314 through 320, and 322 through 347.
(2) A2PC .....	MU-2B-30, MU-2B-35, and MU-2B-36 .....	501 through 651, 653 through 660, and 662 through 696.
(3) A10SW .....	MU-2B-25, MU-2B-26, and MU-2B-26A, and MU-2B-40.	313SA, 321SA, and 348SA through 459SA.
(4) A10SW .....	MU-2B-35, MU-2B-36A, and MU-2B-60 .....	652SA, 661SA, and 697SA through 1569SA.

**Unsafe Condition**

(d) This AD results from a recent safety evaluation that used a data-driven approach to analyze the design, operation, and maintenance of the MU-2B series airplanes in order to determine their safety and define what steps, if any, are necessary for their safe

operation. Part of that evaluation was the identification of unsafe conditions that exist or could develop on the affected type design airplanes. The actions specified in this AD are intended to detect and correct improper adjustment of the flight idle fuel flow setting. The above issue, if uncorrected, could result

in degraded performance and poor handling qualities with consequent loss of control of the airplane in certain situations.

**Compliance**

(e) To address this problem, you must do the following:

TABLE 2.—ACTIONS/COMPLIANCE/PROCEDURES

Actions	Compliance	Procedures
Do flight checks of the rigging of the engine and propeller systems and make any necessary corrections. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may do these actions. Make an entry into the aircraft logbook showing compliance with this portion of the AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).	Check within 100 hours time-in-service (TIS) after September 22, 2006 (the effective date of this AD), and repetitively thereafter at intervals not to exceed 100 hours TIS. If any corrections are necessary, make the corrections before further flight.	<i>For airplanes listed in TCDS A2PC:</i> Follow MHI MV-2 Service Bulletin No. 234, dated October 7, 1998. <i>For airplanes listed in TCDS A10SW:</i> Follow MHI MV-2 Service Bulletin No. 097/73-001, dated July 24, 1998.

**Alternative Methods of Compliance (AMOCs)**

(f) The Manager, Fort Worth ACO, FAA, ATTN: Rao Edupuganti, Aerospace Engineer, ASW-150, 2601 Meacham Blvd., Fort Worth, Texas 76193; telephone: (817) 222-5284; facsimile: (817) 222-5960, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

**Related Information**

(g) Japan Civil Aviation Bureau Airworthiness Directive No. TCD 4890-98, dated November 4, 1998; and MHI MV-2 Service Bulletins No. 234, dated October 7, 1998; and No. 097/73-001, dated July 24, 1998, also address the subject of this AD.

**Material Incorporated by Reference**

(h) You must do the actions required by this AD following the instructions in Mitsubishi Heavy Industries MV-2 Service Bulletin No. 234, dated October 7, 1998; and Mitsubishi Heavy Industries MV-2 Service Bulletin No. 097/73-001, dated July 24, 1998. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. To get a copy of these service bulletins, contact Mitsubishi Heavy Industries America, Inc., 4951 Airport Parkway, Suite 800, Addison, Texas 75001; telephone: (972) 934-5480; facsimile: (972) 934-5488. To review copies of this service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html) or call (202) 741-6030. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2006-23884; Directorate Identifier 2006-CE-13-AD.

Issued in Kansas City, Missouri, on August 11, 2006.

**John R. Colomy,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E6-13554 Filed 8-17-06; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2006-23883; Directorate Identifier 2006-CE-12-AD; Amendment 39-14722; AD 2006-17-01]**

**RIN 2120-AA64**

**Airworthiness Directives; Mitsubishi Heavy Industries MU-2B Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA adopts a new airworthiness directive (AD) for all Mitsubishi Heavy Industries (MHI) MU-2B series airplanes. This AD requires you to incorporate power assurance charts into the Limitations Section of the Airplane Flight Manual (AFM), inspect the engine torque indication system, and recalibrate the torque pressure transducers as required. This AD results from a recent safety evaluation that used a data-driven approach to analyze the design, operation, and maintenance of the MU-2B series airplanes in order to determine their safety and define what steps, if any, are necessary for their safe operation. Part of that evaluation was the identification of unsafe conditions

that exist or could develop on the affected type design airplanes. We are issuing this AD to detect and correct torque transducers that are out of calibration. The above issue, if uncorrected, could result in degraded performance and poor handling qualities with consequent loss of control of the airplane in certain situations.

**DATES:** This AD becomes effective on September 22, 2006.

As of September 22, 2006, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

**ADDRESSES:** To get the service information identified in this AD, contact Mitsubishi Heavy Industries America, Inc., 4951 Airport Parkway, Suite 800, Addison, Texas 75001; telephone: (972) 934-5480; facsimile: (972) 934-5488.

To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001 or on the Internet at <http://dms.dot.gov>. The docket number is FAA-2006-23883; Directorate Identifier 2006-CE-12-AD.

**FOR FURTHER INFORMATION CONTACT:** Rao Edupuganti, Aerospace Engineer, ASW-150, Fort Worth Aircraft Certification Office, 2601 Meacham Blvd., Fort Worth, Texas 76193; telephone: (817) 222-5284; facsimile: (817) 222-5960.

**SUPPLEMENTARY INFORMATION:****Discussion**

On April 21, 2006, we issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all