

2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

328 Support Services GmbH (Formerly, AvCraft Aerospace GmbH, Formerly Fairchild Dornier GmbH, Formerly Dornier Luftfahrt GmbH): Docket No. FAA-2009-0616; Directorate Identifier 2009-NM-070-AD.

Comments Due Date

(a) We must receive comments August 17, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all 328 Support Services GmbH Dornier Model 328-100 and -300 airplanes, certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 25: Equipment/furnishings.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

A recent incident has been reported with a Dornier 328-100 aeroplane, where the right-hand (RH) power lever jammed in flight-idle position during the landing roll-out. The aeroplane was stopped by excessive braking.

The investigation by the operator revealed that the cockpit door locking device Part Number 001A252A3914012 had fallen off the RH cockpit wall and blocked the RH power/condition lever pulley/cable cluster below the door. Although the affected aeroplane had been modified, the technical

investigation showed that a loose Cockpit Door Locking device could also occur on 328-100 and 328-300 aeroplanes with a standard installation.

This condition, if not corrected, could cause interference with the engine- and/or flight control cables, possibly resulting in reduced control of the aeroplane.

For the reasons described above, this AD requires a one-time inspection of the cockpit door locking device and the surrounding area [for proper installation] and the reporting of all findings to the TC [type certificate] holder. This AD is considered to be an interim action and the retrofit of a new design may be implemented later.

The corrective action is re-torquing the attachment screws.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 3 months after the effective date of this AD, do a detailed visual inspection of the cockpit door locking device and the surrounding area for proper installation, in accordance with the Accomplishment Instructions of 328 Support Services Service Bulletin SB-328-25-485 or SB-328J-25-235, both dated January 28, 2009, as applicable.

(2) If any discrepancy is found during the inspection specified in paragraph (f)(1) of this AD, before further flight, do the corrective action in accordance with the Accomplishment Instructions of 328 Support Services Service Bulletin SB-328-25-485 or SB-328J-25-235, both dated January 28, 2009, as applicable.

(3) Submit a report of the findings (both positive and negative) of the inspection required by paragraph (f)(1) of this AD to the Manager, Attention Dept P1, 328 Support Services GmbH, Customer Services, P.O.B. 1252, D-82231 Wessling, Fed. Rep. of Germany; Fax +49 (0) 8153 88111-6565, at the applicable time specified in paragraph (f)(3)(i) or (f)(3)(ii) of this AD. The report must include the inspection results, a description of any discrepancies found, the airplane serial number, and the number of landings and flight hours on the airplane.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was accomplished prior to the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Standards, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *Attn:* Tom Groves, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind

Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1503; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2009-0082, dated April 7, 2009; and 328 Support Services Service Bulletins SB-328-25-485 and SB-328J-25-235, both dated January 28, 2009; for related information.

Issued in Renton, Washington, on July 6, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-16940 Filed 7-15-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0642; Directorate Identifier 2009-NM-001-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Boeing Model 767 series airplanes. This proposed AD would require inspections for scribe lines in the fuselage skin at skin lap joints, the skin at certain external approved repairs, the skin around external features such as antennas, and the skin at decals; and related investigative and corrective actions if necessary. This proposed AD

results from reports of scribe lines found at skin lap joints and butt joints, around external repairs and antennas, and at locations where external decals had been cut. We are proposing this AD to detect and correct scribe lines, which can develop into fatigue cracks in the skin and cause sudden decompression of the airplane.

DATES: We must receive comments on this proposed AD by August 31, 2009.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>, or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Berhane Alazar, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6577; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-0642; Directorate Identifier 2009-NM-001-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received reports indicating that scribe lines have been found by 11 operators on 13 Boeing Model 767 airplanes. Scribe lines were found at skin lap joints, butt joints, around external repairs and antennas, and at locations where external decals had been cut. Many of the scribe lines appear to have been made when sealant was removed as part of preparing the airplane for repainting. The Model 767 airplanes had accumulated between 6,300 and 24,600 total flight cycles. Although no cracks resulting from scribe lines on Model 767 airplanes have been reported to Boeing, fatigue cracks can develop in the skin at scribe line locations. Fatigue cracks, if not corrected, could grow large and cause sudden decompression of the airplane.

Related ADs

This proposed AD is similar to two existing ADs. AD 2006-07-12, amendment 39-14539 (71 FR 16211, March 31, 2006), applies to Boeing Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. AD 2007-19-07, amendment 39-15198 (72 FR 60244, October 24, 2007), applies to all Boeing Model 757-200, -200PF, and -200CB series airplanes. Those ADs require inspections to detect scribe lines in the fuselage skin at certain lap joints, butt joints, external repair doublers, and other areas; and related investigative/corrective actions if necessary. Those actions resulted from reports of fuselage skin cracks adjacent to the skin lap joints on airplanes that had scribe lines.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletin 767-53A0193, Revision 1, dated April 9, 2009. The service bulletin describes procedures for exploratory detailed inspections to detect scribe lines along skin lap joints, external features, external approved repairs, and decals. The service bulletin specifies removing paint and sealant from affected areas before the initial exploratory inspection. The compliance times for the exploratory inspections are 25,000, 37,500, and 50,000 total flight cycles (depending on the inspection location) plus the first scribe line inspection opportunity; or within 4,000 flight cycles after the date of the service bulletin; whichever occurs later.

The service bulletin specifies related investigative actions that include performing high frequency eddy current or ultrasonic inspections of the scribe lines to detect cracks, and the service bulletin specifies corrective actions as either repairing scribe lines and cracks or contacting Boeing for repair instructions and making the repair. The service bulletin specifies to repair cracks before further flight.

The service bulletin specifies repairing scribe lines before further flight, except when a limited return to service (LRTS) program for qualifying scribe lines would allow return to service for a limited period before scribe lines are repaired. The LRTS program includes repetitive inspections to detect cracks where scribe lines are found. To qualify for an LRTS program, scribe lines must meet certain criteria based on their depth and location. The service bulletin specifies contacting Boeing for final repair instructions, which would eliminate the need for the repetitive inspections of the LRTS program. The repetitive interval for the LRTS program is 1,500 to 9,000 flight cycles, depending on the depth and location of the scribe lines and the configuration of the airplane.

The service bulletin notes that certain inspections would not be required under the following conditions:

- The airplane had never been stripped or repainted.
- The airplane had never been stripped or repainted under the wing-to-body fairings.
- No sealant had been removed except in accordance with the specified sealant removal processes as given in Appendix A of the service bulletin.

The service bulletin specifies submitting the exploratory inspection results to Boeing.

FAA's Determination and Requirements of This Proposed AD

We are proposing this AD because we evaluated all relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design. This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under "Differences Between the Proposed AD and Service Bulletin." This proposed AD would also require

sending the results of the exploratory inspections to Boeing.

Differences Between the Proposed AD and Service Bulletin

The service bulletin specifies to contact the manufacturer for instructions on how to repair certain conditions, but this proposed AD would require repairing those conditions in one of the following ways:

- Using a method that we approve; or
- Using data that meet the certification basis of the airplane, and

that have been approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization whom we have authorized to make those findings.

Costs of Compliance

We estimate that this proposed AD would affect 367 airplanes of U.S. registry. The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

TABLE—ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per product	Number of U.S.-registered airplanes	Fleet cost
Exploratory Inspections	340	\$80	None	\$27,200	367	\$9,982,400

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866,
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Boeing: Docket No. FAA-2009-0642; Directorate Identifier 2009-NM-001-AD.

Comments Due Date

(a) We must receive comments by August 31, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 767-200, -300, -300F, and -400ER series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin

767-53A0193, Revision 1, dated April 9, 2009.

Subject

(d) Air Transport Association (ATA) of America Code 53: Fuselage.

Unsafe Condition

(e) This AD results from reports of scribe lines found at skin lap joints, butt joints, around external repairs and antennas, and at locations where external decals had been cut. We are issuing this AD to detect and correct scribe lines, which can develop into fatigue cracks in the skin and cause sudden decompression of the airplane.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection

(g) At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 767-53A0193, Revision 1, dated April 9, 2009, except as provided in paragraph (h) of this AD, do detailed exploratory inspections for scribe lines of skin lap joints, butt joints, around external repairs and antennas, and at locations where external decals may have been cut. Do all applicable related investigative and corrective actions at the times specified in the service bulletin, by accomplishing all actions specified in the Accomplishment Instructions of the service bulletin, except as provided by paragraph (i) of this AD.

Note 1: The inspection exemptions noted in paragraph 1.E. of Boeing Alert Service Bulletin 767-53A0193, Revision 1, dated April 9, 2009, apply to this AD.

Exceptions to Service Bulletin Specifications

(h) Where Boeing Alert Service Bulletin 767-53A0193, Revision 1, dated April 9, 2009, specifies a compliance time after "the

original issue date on this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(i) Where Boeing Alert Service Bulletin 767-53A0193, Revision 1, dated April 9, 2009, specifies to contact Boeing for appropriate action, accomplish applicable actions before further flight using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

Report

(j) At the applicable time specified in paragraph (j)(1) or (j)(2) of this AD: Submit a report of the findings (both positive and negative) of the inspections required by paragraph (g) of this AD. Operators may use the reporting form contained in Appendixes B and C, as applicable, of Boeing Alert Service Bulletin 767-53A0193, Revision 1, dated April 9, 2009. Send the report to Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. The report must contain, at a minimum, the inspection results, a description of any discrepancies found, the airplane serial number, and the number of flight cycles and flight hours on the airplane. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

Credit for Actions Accomplished Previously

(k) Actions accomplished previously in accordance with Boeing Alert Service Bulletin 767-53A0193, dated November 25, 2008, are considered acceptable for compliance with the applicable actions specified in this AD.

Alternative Methods of Compliance (AMOCs)

(l)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Berhane Alazar, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6577; fax (425) 917-6590. Or, e-mail information to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

Issued in Renton, Washington, on July 2, 2009.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E9-16872 Filed 7-15-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0613; Directorate Identifier 2009-NM-013-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A310-221, -222, -322, -324, and -325 Airplanes, and Model A300B4-620, B4-622, B4-622R, F4-605R, and F4-622R Airplanes, Equipped With Pratt & Whitney PW4000 or JT9D-7R4 Series Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During the year 2000, life extension exercise programs were launched for Airbus A310 and A300-600 aircraft. Certification of Extended Service Goal (ESG) is based on analysis, except for fan cowl and thrust reverser (T/R) latches, which are always certified by tests.

* * * testing of the T/R door centre latch has shown that this does not meet the requirements for ESG.

* * * * *

The unsafe condition is possible failure of the T/R latch and detachment of the T/R from the airplane, which could result in structural damage and consequent reduced controllability of the airplane. The proposed AD would

require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by August 17, 2009.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus SAS-EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the