

be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2019-0279R1 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

(1) For information about EASA AD 2019-0279R1, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADS@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0329.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3223; email Sanjay.Ralhan@faa.gov.

Issued on April 3, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-07464 Filed 4-9-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0371; Project Identifier AD-2019-00124-E]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all General Electric Company (GE) CF6-80C2A1, CF6-80C2A2, CF6-80C2A3, CF6-80C2A5, CF6-80C2A5F, CF6-80C2A8, CF6-80C2B1, CF6-80C2B1F, CF6-80C2B2, CF6-80C2B2F, CF6-80C2B4, CF6-80C2B4F, CF6-80C2B5F, CF6-80C2B6, CF6-80C2B6F, CF6-80C2B6FA, CF6-80C2B7F, CF6-80C2B8F, and CF6-80C2D1F model turbofan engines. This proposed AD was prompted by reports of incidents that resulted in a significant fuel loss during flight and an in-flight shutdown (IFSD) of the engine. This proposed AD would require initial and repetitive shim checks of the hydromechanical unit/main engine control (HMU/MEC) idler adapter on the accessory gearbox (AGB) assembly and, depending on the results of the shim check, possible replacement of the inserts on the HMU/MEC idler adapter. As a terminating action to the repetitive shim checks, this proposed AD would also require a protrusion check and a pull-out test and replacements of inserts on the HMU/MEC idler adapter that fail either test. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 26, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact General Electric Company, 1 Newman Way, Cincinnati, OH 45215, United States; phone: (513) 552-3272; email: aviation.fleetsupport@ae.ge.com. You may view this referenced service information at the FAA, Engine & Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0371; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Matthew Smith, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7735; fax: 781-238-7199; email: matthew.c.smith@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2020-0371; Project Identifier AD-2019-00124-E" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this proposed AD.

Confidential Business Information

Confidential Business Information (CBI) is commercial or financial information that is both customarily and actually treated as private by its owner.

Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Matthew Smith, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Discussion

The FAA received reports regarding incidents on GE CF6–80C2 model turbofan engines that resulted in fuel

loss during flight and an IFSD of the engine. The incidents resulted from inserts on the HMU/MEC idler adapter on the AGB assembly pulling out of the housing. An investigation by the manufacturer discovered improperly cut threads on the inserts and erroneous instructions in the maintenance manual, which contributed to poor thread engagement. This condition, if not addressed, could result in failure of the HMU/MEC, engine fire, and damage to the airplane.

Related Service Information Under 1 CFR Part 51

The FAA reviewed GE CF6–80C2 Service Bulletin (SB) 72–1577 R01, dated August 16, 2019. The SB describes procedures for performing shim checks of the HMU/MEC idler adapter. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

The FAA is proposing this AD because the agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require initial and repetitive shim checks of the HMU/MEC idler adapter on the AGB assembly and, depending on the results of the shim checks, replacement of the inserts on the HMU/MEC idler adapter. As a terminating action to the repetitive shim checks, this proposed AD would also require a protrusion check and a pull-out test and replacements of inserts on the HMU/MEC idler adapter that fail either test.

Costs of Compliance

The FAA estimates that this proposed AD affects 555 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Shim check	1.00 work-hour × \$85.00 per hour = \$85.00	\$0.00	\$85.00	\$47,175
Protrusion Check/Pull-out test	4.00 work-hours × \$85.00 per hour = \$340.00 ..	0.00	340.00	188,700

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the proposed shim check. The FAA has no way of determining the

number of aircraft that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replace HMU/MEC idler adapter insert	4.00 work-hours × \$85.00 per hour = \$340.00	\$50.00	\$390.00

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and

procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

General Electric Company: Docket No. FAA–2020–0371; Project Identifier AD–2019–00124–E.

(a) Comments Due Date

The FAA must receive comments by May 26, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company (GE) CF6–80C2A1, CF6–80C2A2, CF6–80C2A3, CF6–80C2A5, CF6–80C2A5F, CF6–80C2A8, CF6–80C2B1, CF6–80C2B1F, CF6–80C2B2, CF6–80C2B2F, CF6–80C2B4, CF6–80C2B4F, CF6–80C2B5F, CF6–80C2B6, CF6–80C2B6F, CF6–80C2B6FA, CF6–80C2B7F, CF6–80C2B8F, and CF6–80C2D1F model turbofan engines that underwent an engine shop visit prior to November 1, 2018.

(d) Subject

Joint Aircraft System Component (JASC) Code 7321, Fuel Control/Turbine Engines.

(e) Unsafe Condition

This AD was prompted by failure of the hydromechanical unit/main engine control (HMU/MEC) on the accessory gearbox (AGB) assembly. The FAA is issuing this AD to prevent failure of the HMU/MEC. The unsafe condition, if not addressed, could result in engine fire and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Perform a shim check of the HMU/MEC idler adapter inserts in accordance with paragraph 3.B.(1) of GE CF6–80C2 Service Bulletin (SB) 72–1577 R01, dated August 16, 2019, within 1,200 flight hours after the effective date of this AD.

(2) Thereafter, perform a repetitive shim check of the HMU/MEC idler adapter inserts in accordance with paragraph 3.B.(1) of GE CF6–80C2 SB 72–1577 R01, dated August 16, 2019 within every 1,200 flight hours since last shim check.

(3) If any HMU/MEC idler adapter insert fails the shim check required by paragraph (g)(1) or (2) of this AD, perform the following prior to further flight:

(i) Retorque the bolts at each bolt location that failed the shim check, in accordance with paragraph 3.B.(1)(c) of GE CF6–80C2 SB 72–1577 R01, dated August 16, 2019.

(ii) Perform the shim check again, in accordance with paragraph (g)(1) of this AD. If the shim check fails again, perform the terminating action required by paragraph (h) of this AD.

(h) Terminating Action

As a terminating action to the repetitive shim check requirements of paragraph (g)(2) and (g)(3) of this AD, and as required by paragraph (g)(3)(ii) of this AD, perform the following:

(1) Do a protrusion check at all eight bolt locations in accordance with paragraph 3.C.(3) of GE CF6–80C2 SB 72–1577 R01, dated August 16, 2019.

(2) Do a pull-out test at all eight bolt locations in accordance with paragraph 3.C.(4) of GE CF6–80C2 SB 72–1577 R01, dated August 16, 2019.

(3) If the inserts on the HMU/MEC idler adapter fail the protrusion check or pull-out test required by paragraph (h)(1) or (2) of this AD, replace the inserts in accordance with paragraph 3.C.(5) of GE CF6–80C2 SB 72–1577 R01, dated August 16, 2019. After replacement of the inserts is accomplished, the requirements of this AD have been met and no further action is required.

(4) If the inserts on the HMU/MEC idler adapter pass both the protrusion check and the pull-out test required by paragraphs (h)(1) and (2) of this AD, the requirements of this AD have been met and no further action is required.

(i) Credit for Previous Actions

You may take credit for the initial shim check of the HMU/MEC idler adapter required by paragraph (g)(1) of this AD if you performed this shim check before the effective date of this AD using GE CF6–80C2 SB 72–1577 R00, dated October 31, 2018.

(j) Definition

For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine case flanges, except separation of engine flanges solely for the purposes of transportation of the engine without subsequent maintenance, which does not constitute an engine shop visit.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager

of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Matthew Smith, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781–238–7735; fax: 781–238–7199; email: matthew.c.smith@faa.gov.

(2) For service information identified in this AD, contact General Electric Company, 1 Newman Way, Cincinnati, OH 45215, United States; phone: (513) 552–3272; email: aviation.fleet-support@ae.ge.com. You may view this referenced service information at the FAA, Engine & Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781–238–7759.

Issued on April 6, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Office.

[FR Doc. 2020–07565 Filed 4–9–20; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–0328; Product Identifier 2020–NM–030–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A318 series airplanes, Model A319–111, –112, –113, –114, –115, –131, –132, and –133 airplanes, Model A320–211, –212, –214, –216, –231, –232, and –233 airplanes, and Model A321–111, –112, –131, –211, –212, –213, –231, and –232 airplanes. This proposed AD was prompted by reports of crack findings in and around the fastener holes of the central and lateral window frame upper junction; those cracks were found on fastener holes outside of the inspection area specified in a certain airworthiness limitation item (ALI) task. This proposed AD would require repetitive inspections of the upper junction fastener holes at the lateral window frame for cracking; and for certain airplanes, repetitive inspections of the spotface around the fastener holes for cracking; and corrective actions if