

separation of the strut and engine, accomplish the following:

#### Repetitive Inspections

(a) Except as provided by paragraph (b) of this AD, before the accumulation of 10,000 total flight cycles, or within 600 flight cycles after the effective date of this AD, whichever occurs later: Accomplish the inspections required by paragraph (a)(1) or (a)(2) of this AD, as applicable.

(1) Perform a detailed visual inspection of the four aft-most fastener holes in the horizontal tangs of the midspar fitting of the strut to detect cracking, in accordance with Part 1, "Detailed Visual Inspection," of the Accomplishment Instructions of Boeing Service Bulletin 767-54A0101, Revision 1, dated February 3, 2000. If no cracking is detected, repeat the inspection thereafter at the applicable intervals specified in Table 1, "Reinspection Intervals for Part 1—Detailed Visual Inspection" included in Figure 1 of the service bulletin.

**Note 2:** For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(2) Perform a high frequency eddy current inspection of the four aft-most fastener holes in the horizontal tangs of the midspar fitting of the strut to detect discrepancies (cracking, incorrect fastener hole diameter), in accordance with Part 2, "High Frequency Eddy Current (HFEC) Inspection," of the Accomplishment Instructions of the service bulletin. Accomplish the requirements specified in paragraph (a)(2)(i) or (a)(2)(ii) of this AD, as applicable; and repeat the inspection thereafter at the applicable intervals specified in Table 2, "Reinspection Intervals for Part 2—HFEC Inspection" included in Figure 1 of the service bulletin.

(i) If no cracking is detected and the fastener hole diameter is less than or equal to 0.5322 inch, rework the hole in accordance with Part 3 of the Accomplishment Instructions of the service bulletin.

(ii) If no cracking is detected and the fastener hole diameter is greater than 0.5322 inch, accomplish the requirements specified in either paragraph (c)(1) or (c)(2) of this AD.

(b) For airplanes on which the two aft-most fasteners have been inspected in accordance with Boeing Service Bulletin 767-54A0101, Revision 1, dated February 3, 2000, prior to the effective date of this AD: Perform the initial inspection of the four aft-most fasteners in accordance with paragraph (a) of this AD before the accumulation of 10,000 total flight cycles, or within 1,500 flight cycles after the effective date of this AD, whichever occurs later.

#### Corrective Actions

(c) If any cracking is detected after accomplishment of any inspection required by paragraph (a) of this AD, before further

flight, accomplish the requirements specified in either paragraph (c)(1) or (c)(2) of this AD.

(1) Accomplish the terminating action specified in Part 4 of the Accomplishment Instructions of Boeing Service Bulletin 767-54A0101, Revision 1, dated February 3, 2000. Accomplishment of this paragraph terminates the requirements of this AD.

(2) Replace the midspar fitting of the strut with a serviceable part, or repair in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Repeat the applicable inspection thereafter at the applicable time specified in paragraph (a)(1) or (a)(2) of this AD.

(d) If any discrepancies (cracking, incorrect fastener hole diameter) are detected during any inspection required by paragraph (a) of this AD, for which the service bulletin specifies that the manufacturer may be contacted for disposition of those repair conditions: Before further flight, accomplish the corrective actions (including fastener hole rework and/or midspar fitting replacement) in accordance with a method approved by the Manager, Seattle ACO; or in accordance with data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a method to be approved by the Manager, Seattle ACO, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

#### Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

#### Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

#### Incorporation by Reference

(g) Except as provided by paragraphs (c)(2) and (d) of this AD, the actions shall be done in accordance with Boeing Service Bulletin 767-54A0101, Revision 1, dated February 3, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North

Capitol Street, NW., suite 700, Washington, DC.

#### Effective Date

(h) This amendment becomes effective on May 15, 2001.

Issued in Renton, Washington, on April 2, 2001.

**Donald L. Riggan,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 01-8612 Filed 4-9-01; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-NM-178-AD; Amendment 39-12171; AD 2001-07-06]

**RIN 2120-AA64**

#### Airworthiness Directives; Saab Model SAAB 2000 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Saab Model SAAB 2000 series airplanes, that requires a modification involving nondestructive test inspections of the 34 fastener holes in each rear wing spar, corrective action, if necessary, and cold working of the holes to increase fatigue life of the rear spar web. This amendment is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by this AD are intended to prevent fatigue cracking, which could result in fuel leakage and reduced structural integrity of the wings.

**DATES:** Effective May 15, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 15, 2001.

**ADDRESSES:** The service information referenced in this AD may be obtained from Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Saab Model SAAB 2000 series airplanes was published in the **Federal Register** on January 16, 2001 (66 FR 3516). That action proposed to require a modification involving nondestructive test inspections of the 34 fastener holes in each rear wing spar, corrective action, if necessary, and cold working of the holes to increase fatigue life of the rear spar web.

#### Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

#### Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

#### Cost Impact

The FAA estimates that 3 airplanes of U.S. registry will be affected by this AD, that it will take approximately 64 work hours per airplane to accomplish the required inspections and modification, and that the average labor rate is \$60 per work hour. Required parts will be supplied by the manufacturer without cost to the operators. Based on these figures, the cost impact of this AD on U.S. operators is estimated to be \$11,520, or \$3,840 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

#### Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on

the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

##### 2001-07-06 SAAB Aircraft AB:

Amendment 39-12171. Docket 2000-NM-178-AD.

**Applicability:** Model SAAB 2000 series airplanes, serial numbers -003 through -063 inclusive; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by

this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent fuel leakage and reduced structural integrity of the wings due to fatigue cracking, accomplish the following:

#### Modification

(a) Except as required by paragraph (b) of this AD: Prior to the accumulation of 13,000 total flight cycles, accomplish the modification of the rear spar on both wings (including applicable nondestructive test inspections to detect discrepancies (including cracking, scratches, or other damage, and incorrect hole size) and cold working of fastener holes), in accordance with Saab Service Bulletin 2000-57-037, dated April 13, 2000.

**Note 2:** For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

#### Repair

(b) If any discrepancy is found during any inspection required by paragraph (a) of this AD, prior to further flight, repair in accordance with a method approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, or the Luftfartsverket (LFV) (or its delegated agent). For a repair method to be approved by the Manager, International Branch, ANM-116, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

#### Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and who will then send the requests and comments to the Manager, International Branch, ANM-116.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

#### Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Incorporation by Reference**

(e) Except as provided by paragraph (b) of this AD, the actions shall be done in accordance with Saab Service Bulletin 2000-57-037, dated April 13, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 4:** The subject of this AD is addressed in Swedish airworthiness directive 1-157, dated April 13, 2000.

**Effective Date**

(f) This amendment becomes effective on May 15, 2001.

Issued in Renton, Washington, on April 2, 2001.

**Donald L. Riggins,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01-8613 Filed 4-9-01; 8:45 am]

**BILLING CODE 4910-13-U**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2001-NM-43-AD; Amendment 39-12173; AD 2001-07-08]

**RIN 2120-AA64**

**Airworthiness Directives; McDonnell Douglas Model MD-11 Series Airplanes Equipped With Pratt & Whitney Model PW4400 Series Engines**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD) that is applicable to all McDonnell Douglas Model MD-11 series airplanes equipped with Pratt & Whitney Model PW4400 series engines. This action requires revising the Airplane Flight Manual (AFM) to advise the flight crew of applicable operational limits. This action is necessary to ensure that the flight crew is informed of applicable limitations in airplane performance, and to prevent reduced acceleration and climb performance relative to performance data in the AFM, which could result in the airplane overrunning the end of the runway during takeoff or landing, or impacting obstacles or

terrain. This action is intended to address the identified unsafe condition.

**DATES:** Effective April 25, 2001.

Comments for inclusion in the Rules Docket must be received on or before June 11, 2001.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-43-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-43-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

Information pertaining to this amendment may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.

**FOR FURTHER INFORMATION CONTACT:**

Philip C. Kush, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5263; fax (562) 627-5210.

**SUPPLEMENTARY INFORMATION:** The FAA has found that the Operational Limits specified in the Limitations Section of the Airplane Flight Manual (AFM) for McDonnell Douglas Model MD-11 series airplanes equipped with Pratt & Whitney Model PW4400 series engines do not adequately list the performance correction sections in the AFM. Section 4B, the applicable performance correction section for Model MD-11 series airplanes with Pratt & Whitney Model PW4462 engines, is not listed. Model PW4462 engines are rated for higher thrust than other Model PW4400 series engines. Omitting the reference to Section 4B in the required performance correction paragraph of the Operational Limits subsection in the Limitations Section of the AFM could cause the flight crew to be incorrectly informed about limitations in airplane performance.

Also, the FAA has received reports that Pratt & Whitney Model PW4400 series engines with certain early-production fan blades (Phase 0/1, FB2B), as installed on certain McDonnell Douglas Model MD-11 series airplanes, do not produce the amount of thrust indicated in the AFM. This thrust shortfall is due to erosion of the fan blade's leading edge. This condition causes a thrust shortfall of 2.5 percent at high-thrust settings. The flight crew has no indication of this shortfall in thrust. This condition could result in reduced acceleration and climb performance relative to performance data in the AFM, which, if not corrected, could lead to the airplane overrunning the end of the runway during takeoff or landing, or impacting obstacles or terrain.

**Explanation of the Requirements of the Rule**

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design, this AD is being issued to ensure that the flight crew is informed of applicable limitations in airplane performance, and to prevent reduced acceleration and climb performance relative to performance data in the AFM, which could result in the airplane overrunning the end of the runway during takeoff or landing, or impacting obstacles or terrain. This AD requires revising the Limitations Section of the AFM, and, for certain airplanes, Section 4A or 4B of the Performance Section of the AFM, to advise the flight crew of applicable operational limits.

**Interim Action**

This is considered to be interim action until final action is identified, at which time the FAA may consider further rulemaking.

**Determination of Rule's Effective Date**

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

**Comments Invited**

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the