

California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(f) This amendment becomes effective on December 16, 2003.

Issued in Renton, Washington, on November 20, 2003.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-29531 Filed 11-28-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NM-140-AD; Amendment 39-13373; AD 2003-24-04]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-400 and -400F Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 747-400 and -400F series airplanes. This action requires replacing the rudder feel, centering, and trim mechanism with a new or serviceable rudder feel, centering, and trim mechanism. This action is necessary to prevent degradation/loss of rudder feel and centering, which could result in increased pilot workload and could lead to loss of control of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective December 16, 2003.

The incorporation by reference of Boeing Service Bulletin 747-27-2392, dated February 20, 2003, as listed in the regulations, is approved by the Director of the Federal Register as of December 16, 2003.

Comments for inclusion in the Rules Docket must be received on or before January 30, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-140-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal

holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-iarcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2003-NM-140-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Doug Tsuji, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6487; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: The FAA has received reports from the manufacturer of Boeing Model 747-400 series airplanes, indicating that there have been two cases of shafts in the rudder feel, centering, and trim mechanisms with either elongated holes or extra holes and drill starts. The shafts were found installed on airplanes in the factory. The cause of the discrepancies in the shafts is due to manufacturing and quality deficiencies at the supplier. This condition, if not corrected, could result in degradation/loss of rudder feel and centering, which could result in increased pilot workload and could lead to loss of control of the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Service Bulletin 747-27-2392, dated February 20, 2003, which describes procedures for replacing the rudder feel, centering, and trim mechanism with a new or serviceable rudder feel, centering, and trim mechanism. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design that may be registered in the United States at some time in the future,

this AD is being issued to prevent degradation/loss of rudder feel and centering, which could result in increased pilot workload and could lead to loss of control of the airplane. This AD requires replacing the rudder feel, centering, and trim mechanism with a new or serviceable rudder feel, centering, and trim mechanism. The actions are required to be accomplished in accordance with the service bulletin described previously.

Cost Impact

None of the Model 747-400 and -400F series airplanes affected by this action are on the U.S. Register. All airplanes included in the applicability of this rule currently are operated by non-U.S. operators under foreign registry; therefore, they are not directly affected by this AD action. However, the FAA considers that this rule is necessary to ensure that the unsafe condition is addressed in the event that any of these subject airplanes are imported and placed on the U.S. Register in the future.

Should an affected airplane be imported and placed on the U.S. Register in the future, it would require approximately 12 work hours to accomplish the required actions, at an average labor rate of \$65 per work hour. Required parts would cost \$25,537. Based on these figures, the cost impact of this AD would be \$26,317 per airplane.

The manufacturer may cover the cost of replacement parts associated with this AD, subject to warranty conditions. Manufacturer warranty remedies may also be available for labor costs associated with this AD. As a result, the costs attributable to the proposed AD may be less than stated above.

Determination of Rule's Effective Date

Since this AD action does not affect any airplane that is currently on the U.S. register, it has no adverse economic impact and imposes no additional burden on any person. Therefore, prior notice and public procedures hereon are unnecessary and the amendment may be made effective in less than 30 days after publication in the **Federal Register**.

Comments Invited

Although this action is in the form of a final rule and was not preceded by notice and opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the

address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2003-NM-140-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is

contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

2003-24-04 Boeing: Amendment 39-13373. Docket 2003-NM-140-AD.

Applicability: Model 747-400 and -400F series airplanes, line numbers 1254 through 1293 inclusive, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent degradation/loss of rudder feel and centering, which could result in increased pilot workload and could lead to loss of control of the airplane, accomplish the following:

Service Bulletin References

(a) The term "service bulletin" as used in this AD, means the Accomplishment Instructions of Boeing Service Bulletin 747-27-2392, dated February 20, 2003.

Corrective Actions

(b) Within 36 months after the effective date of this AD, replace the feel, centering, and trim mechanism with a new or serviceable rudder feel, centering, and trim mechanism per the service bulletin.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(d) The actions shall be done in accordance with Boeing Service Bulletin 747-27-2392, dated February 20, 2003. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, PO Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal

Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(e) This amendment becomes effective on December 16, 2003.

Issued in Renton, Washington, on November 20, 2003.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-29530 Filed 11-28-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NM-247-AD; Amendment 39-13375; AD 2003-24-06]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Mystere-Falcon 200 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to all Dassault Model Mystere-Falcon 200 series airplanes. This action requires a one-time inspection of the fire extinguishing pipe for each engine to determine whether holes for dispersal of fire-extinguishing agent are present, and corrective action if necessary. This action is necessary to ensure that the flightcrew is able to extinguish an engine fire, should one occur. Inability to extinguish an engine fire could result in loss of control of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective December 1, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 1, 2003.

Comments for inclusion in the Rules Docket must be received on or before December 31, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-247-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal