

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2007-23-06 CTRM Aviation Sdn. Bhd. (Formerly Eagle Aircraft (Malaysia) Sdn. Bhd.): Amendment 39-15252; Docket No. FAA-2007-28957; Directorate Identifier 2007-CE-069-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective December 11, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD affects Model Eagle 150B airplanes, all serial numbers, that are certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 57: Wings.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

An operator has reported severe exfoliation corrosion on Wing/Canard Flap Hinges, P/N 5731D01-16 (middle and outboard hinges) on his Eagle 150B. The corrosion has been detected during 100-hour inspection. The aircraft has accumulated more than 1000 flight hours. The corrosion is so severe that one of the Flap Hinges thickness has been reduced by 50%. The corrosion is not easily detected because the Flap Hinge is sandwiched between the Flap Hinge Support Bracket P/N 5731D01-01.

The failure of the hinge bracket may result in disintegration of flap/canard wing thus leading to loss of control, with catastrophic consequences.

The MCAI requires you to visually inspect the flap hinges and flap hinge support brackets for any corrosion. You are to take corrective action if you find any corrosion.

Actions and Compliance

(f) Unless already done, do the following actions:

(1) Within the next 25 hours time-in-service (TIS) after December 11, 2007 (the effective date of this AD), inspect the flap hinges and flap hinge support brackets for any corrosion, following CTRM Aviation Mandatory Service Bulletin SB 1126, dated July 19, 2007.

(2) Before further flight, if you find any corrosion as a result of any inspection required by paragraph (f)(1) of this AD, take corrective action following CTRM Aviation Mandatory Service Bulletin SB 1126, dated July 19, 2007.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No Differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Department of Civil Aviation Malaysia AD No. CAM AD 001-07-2007, dated July 20, 2007; and CTRM Aviation Mandatory Service Bulletin SB 1126, dated July 19, 2007, for related information.

Material Incorporated by Reference

(i) You must use CTRM Aviation Mandatory Service Bulletin SB 1126, dated July 19, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact CTRM Aviation Sdn. Bhd. (formerly known as Eagle Aircraft Sdn. Bhd.), Locked Bag 1028, Pejabat Pos Besar Melaka, 75150 Melaka, Malaysia; telephone: 06 317 1007; fax: 06 317 7023.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on October 29, 2007.

Kim Smith,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-21667 Filed 11-5-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. **FAA-2007-29064**; Directorate Identifier **2007-NM-128-AD**; Amendment **39-15249**; AD **2007-23-03**]

RIN 2120-AA64

Airworthiness Directives; Fokker Model F.28 Mark 0070 and 0100 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

One Fokker 100 (F28 Mark 0100) operator reported that during maintenance in the APU (auxiliary power unit) compartment, a disconnected nut was discovered on one of the shuttle valves in the deployment lines of the engine fire-extinguishing system. An additional check by the operator revealed that on more aircraft in its fleet, the nuts of the shuttle valves were incorrectly tightened. This condition, if not corrected, could result in failure or deteriorated functioning of the engine fire-extinguishing system in case of an engine fire.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective December 11, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 11, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on August 31, 2007 (72 FR 50274). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

One Fokker 100 (F28 Mark 0100) operator reported that during maintenance in the APU (auxiliary power unit) compartment, a disconnected nut was discovered on one of the shuttle valves in the deployment lines of the engine fire-extinguishing system. An additional check by the operator revealed that on more aircraft in its fleet, the nuts of the shuttle valves were incorrectly tightened. This condition, if not corrected, could result in failure or deteriorated functioning of the engine fire-extinguishing system in case of an engine fire. Since a potentially unsafe condition has been identified that is likely to exist or develop on other aircraft of this type design, this Airworthiness Directive requires a one-time inspection of the nuts and shuttle valves in the deployment lines of the engine fire-extinguishing system in the APU compartment and corrective actions, as necessary.

The one-time inspection is intended to find discrepancies, including incorrectly installed or tightened nuts, and signs of leakage, damage, or corrosion. Corrective actions include tightening or replacing discrepant nuts or shuttle valves, as applicable. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI

to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect about 13 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$1,040, or \$80 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2007-23-03 Fokker Services B.V.:

Amendment 39-15249. Docket No. FAA-2007-29064; Directorate Identifier 2007-NM-128-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective December 11, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Fokker Model F.28 Mark 0070 and 0100 airplanes, all serial numbers; certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 26: Fire protection.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

One Fokker 100 (F28 Mark 0100) operator reported that during maintenance in the APU (auxiliary power unit) compartment, a disconnected nut was discovered on one of the shuttle valves in the deployment lines of the engine fire-extinguishing system. An

additional check by the operator revealed that on more aircraft in its fleet, the nuts of the shuttle valves were incorrectly tightened. This condition, if not corrected, could result in failure or deteriorated functioning of the engine fire-extinguishing system in case of an engine fire. Since a potentially unsafe condition has been identified that is likely to exist or develop on other aircraft of this type design, this Airworthiness Directive requires a one-time inspection of the nuts and shuttle valves in the deployment lines of the engine fire-extinguishing system in the APU compartment and corrective actions, as necessary.

The one-time inspection is intended to find discrepancies, including incorrectly installed or tightened nuts, and signs of leakage, damage or corrosion. Corrective actions include tightening or replacing discrepant nuts or shuttle valves, as applicable.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 6 months after the effective date of this AD, inspect the nuts on the affected shuttle valves in accordance with Section 3., "Accomplishment Instructions," of Fokker Service Bulletin SBF100-26-019, dated January 6, 2006.

(2) When discrepancies are found during the inspection as required by paragraph (f)(1) of this AD, before next flight, tighten or replace the affected nuts, or replace the shuttle valves; as applicable; in accordance with Section 3., "Accomplishment Instructions," of Fokker Service Bulletin SBF100-26-019, dated January 6, 2006.

Note 1: Fokker 70/100 Aircraft Maintenance Manual Task 26-21-03-400-814-A also pertains to this subject.

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows: No difference.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Dutch Airworthiness Directive NL-2006-002, dated January 24, 2006, and Fokker Service Bulletin SBF100-26-019, dated January 6, 2006, for related information.

Material Incorporated by Reference

(i) You must use Fokker Service Bulletin SBF100-26-019, dated January 6, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 27, 2007.

Stephen P. Boyd,

Assistant Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-21673 Filed 11-5-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-29171; Directorate Identifier 2007-NM-154-AD; Amendment 39-15251; AD 2007-23-05]

RIN 2120-AA64

Airworthiness Directives; Saab Model SAAB 2000 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation

product. The MCAI describes the unsafe condition as:

Subsequent to accidents involving Fuel Tank System explosions in flight * * * and on ground, * * * Special Federal Aviation Regulation 88 (SFAR88) * * * required a safety review of the aircraft Fuel Tank System * * *.

Fuel Airworthiness Limitations are items arising from a systems safety analysis that have been shown to have failure mode(s) associated with an 'unsafe condition' * * *. These are identified in Failure Conditions for which an unacceptable probability of ignition risk could exist if specific tasks and/or practices are not performed in accordance with the manufacturers' requirements.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective December 11, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 11, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Mike Borfitz, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-2677; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on September 11, 2007 (72 FR 51722). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

Subsequent to accidents involving Fuel Tank System explosions in flight * * * and on ground, the FAA published Special Federal Aviation Regulation 88 (SFAR 88) in June 2001. SFAR 88 required a safety review of the aircraft Fuel Tank System to determine that the design meets the requirements of FAR (Federal Aviation Regulation) § 25.901 and § 25.981(a) and (b).

A similar regulation has been recommended by the JAA (Joint Aviation Authorities) to the European National Aviation Authorities in JAA letter 04/00/02/07/03-L024 of 3 February 2003. The review was requested to be mandated by NAA's (National Aviation Authorities) using JAR