

(2) Five effective kilograms or more of plutonium, high-enriched uranium or uranium-233.

(3) 10,000 kilograms or more of heavy water. (*Note:* Does not apply to exports of heavy water to Canada.)

(4) Nuclear grade graphite for nuclear end use.

(5) Radioactive waste.

(c) The Commission will also publish in the **Federal Register** a notice of receipt of a license application, including applications for amendment or renewal but not applications for minor amendments, for an import of radioactive waste for which a specific license is required.

34. Section 110.80 is revised to read as follows:

§ 110.80 Basis for hearings.

The procedures in this part will constitute the exclusive basis for hearings on export and import license applications.

35. In § 110.81, paragraph (b) is revised to read as follows:

§ 110.81 Written comments.

* * * * *

(b) These comments should be submitted within 30 days after public notice of receipt of the application on the NRC Web site or in the **Federal Register** and addressed to the Secretary, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, *Attention:* Rulemakings and Adjudications Staff.

* * * * *

36. In § 110.82, paragraph (c) is revised to read as follows:

§ 110.82 Hearing request or intervention petition.

* * * * *

(c) Hearing requests and intervention petitions will be considered timely only if filed not later than:

(1) 30 days after notice of receipt in the **Federal Register**, for those applications published in the **Federal Register**;

(2) 30 days after publication of notice on the NRC Web site at <http://www.nrc.gov>;

(3) 30 days after notice of receipt in the Public Document Room; or

(4) Such other time as may be provided by the Commission.

37. In § 110.112, paragraph (b) is revised to read as follows:

§ 110.112 Reporter and transcript for an oral hearing.

* * * * *

(b) Except for any portions containing classified information, Restricted Data, Safeguards Information, proprietary information, or other sensitive

unclassified information, transcripts will be made available at the NRC Web site, <http://www.nrc.gov>, and/or at the NRC Public Document Room.

* * * * *

Appendix L to Part 110 [Amended]

38. Appendix L to part 110 is amended by adding “Carbon 11 (C 11)”, “Cesium 129 (Cs 129)”, “Cobalt 57 (Co 57)”, “Gallium 67 (Ga 67)”, “Gold 195 (Au 195)”, “Indium 111 (In 111)”, “Iodine 123 (I 123)”, “Iron 52 (Fe 52)”, “Nitrogen 13 (N 13)”, “Oxygen 15 (O 15)”, “Potassium 43 (K 43)”, “Rubidium 81 (Rb 81)”, “Yttrium 87 (Y 87)”, and “Yttrium 88 (Y 88)” in alphabetical order.

Dated at Rockville, Maryland, this 17th day of June 2009.

For the Nuclear Regulatory Commission,
Annette Vietti-Cook,
Secretary of the Commission.

[FR Doc. E9-14679 Filed 6-22-09; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0553; Directorate Identifier 2008-NM-199-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-100, 747-100B, 747-200B, 747-200C, 747-200F, and 747SR Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Boeing Model 747-100, 747-100B, 747-200B, 747-200C, 747-200F, and 747SR series airplanes. This proposed AD would require a one-time general visual inspection for missing fasteners in certain stringer-to-stringer clip joints at the station (STA) 760 through STA 940 frames, and related investigative and corrective actions if necessary. This proposed AD results from a report of broken and cracked frame shear ties, cracks on the frame doubler and frame web, and missing fasteners in the stringer (S)-10L stringer-to-stringer clip joint at the STA 820 frame. We are proposing this AD to detect and correct missing fasteners in the stringer-to-stringer clip joints, which could result in shear tie and skin cracks and rapid in-flight decompression of the airplane.

DATES: We must receive comments on this proposed AD by August 7, 2009.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207; telephone 206-544-9990; fax 206-766-5682; e-mail DDCS@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2009-0553; Directorate Identifier 2008-NM-199-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy

aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report indicating that, during routine maintenance, two operators found broken and cracked frame shear ties at the station (STA) 820 frame between stringer (S)-10AL and S-11L. Also, cracks were found on the frame doubler and frame web near S-11L. Further inspection showed missing fasteners in the S-10L stringer-to-stringer clip joint at the STA 820 frame. The cracks and missing fasteners were found on airplanes that had accumulated 16,087 and 16,421 total flight cycles.

Boeing analysis shows that the cracks were caused by increased load on the shear ties because of the missing fasteners in the stringer-to-stringer clip joint. Boeing investigation shows that similar cracking could occur in the frames adjacent to the tension ties if the

stringer clip fasteners are not installed. Cracks in the shear ties, if not detected and corrected, could result in skin cracks and rapid in-flight decompression of the airplane.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletin 747-53A2751, dated October 9, 2008. The service bulletin describes procedures for a one-time general visual inspection for missing fasteners in the S-10, S-10A, and S-11 stringer-to-stringer clip joints at the STA 760 through STA 940 frames, detailed and surface high frequency eddy current inspections to detect cracking of the adjacent frame and skin structure, installation of missing fasteners, and repairs of the shear ties, frame web, and/or skin. For airplanes on which the repair was done, the service bulletin describes procedures for detailed inspections to detect cracks of the repairs and the adjacent structure within 10 inches of the repairs. The service bulletin also specifies a detailed inspection of the repair and adjacent structure every 3,000 flight cycles.

FAA's Determination and Requirements of this Proposed AD

We are proposing this AD because we evaluated all relevant information and determined the unsafe condition

described previously is likely to exist or develop in other products of the same type design. This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under "Differences Between the Proposed AD and Service Bulletin."

Differences Between the Proposed AD and Service Bulletin

The service bulletin specifies to contact the manufacturer for instructions on how to repair certain conditions, but this proposed AD would require repairing those conditions in one of the following ways:

- Using a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization whom we have authorized to make those findings.

Costs of Compliance

We estimate that this proposed AD would affect 84 airplanes of U.S. registry. The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per product	Number of U.S.-registered airplanes	Fleet cost
Inspection	4	\$80	\$0	\$320 per inspection cycle	84	\$26,880 per inspection cycle.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866,
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Boeing: Docket No. FAA-2009-0553; Directorate Identifier 2008-NM-199-AD.

Comments Due Date

(a) We must receive comments by August 7, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 747-100, 747-100B, 747-200B, 747-200C, 747-200F, and 747SR series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 747-53A2751, dated October 9, 2008.

Subject

(d) Air Transport Association (ATA) of America Code 53: Fuselage.

Unsafe Condition

(e) This AD results from a report of broken and cracked frame shear ties, cracks on the frame doubler and frame web, and missing fasteners in the stringer (S)-10L stringer-to-stringer clip joint at the station (STA) 820 frame. We are proposing this AD to detect and correct missing fasteners at the stringer-to-stringer clip joints, which could result in shear tie and skin cracks and rapid in-flight decompression of the airplane.

Compliance

(f) Comply with this AD within the compliance times specified, unless already done.

Inspection for Missing Fasteners

(g) Within 3,000 flight cycles after the effective date of this AD: Do a one-time general visual inspection for missing fasteners in the left and right side S-10, S-10A, and S-11 stringer-to-stringer clip joints at the STA 760 through 940 frames, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2751, dated October 9, 2008. If any fasteners are missing, before further flight, do detailed and surface high frequency eddy current inspections to detect cracking of the adjacent frame and skin structure in accordance with the Accomplishment Instructions of the service bulletin. Install all missing fasteners before further flight.

(h) If any crack is found during the inspection required by paragraph (g) of this AD: Before further flight, repair any cracked shear ties, frame web, and/or skin in accordance with Boeing Service Bulletin 747-53A2751, dated October 9, 2008.

(i) If any repair is done in accordance with paragraph (h) of this AD, before 20,000 total flight cycles or within 3,000 flight cycles from the repair installation, whichever occurs later: Do a detailed inspection of the repair(s) and the adjacent structure within 10 inches of the repair(s) for cracking. Repeat the inspection thereafter at intervals not to exceed 3,000 flight cycles. If any crack is found during this inspection, before further flight, repair using a method approved in

accordance with the procedures specified in paragraph (j) of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *Attn: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590. Or, e-mail information to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.*

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, in the FAA Flight Standards District Office (FSDO), or lacking a principal inspector, your local FSDO. The AMOC approval letter must specifically reference this AD.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Issued in Renton, Washington, on June 15, 2009.

Dorr M. Anderson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-14677 Filed 6-22-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2009-0565; Directorate Identifier 2008-NM-217-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-2A12 (CL-601) and CL-600-2B16 (CL-601-3A, CL-601-3R, and CL-604) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing

airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

[I]ncidents of throttle jam and engine shutdowns, caused by premature wear of the rack and pinion mechanism of part number (P/N) 2100140-005 and -007 Engine Throttle Control Gearbox (ETCG), installed on Bombardier CL-601 and 604 aircraft.

* * * * *

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by July 23, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Rocco Viselli, Aerospace Engineer,