

to DHS social service programs, or provided in conjunction with any benefits or services supported by direct financial assistance from DHS pursuant to DHS social service programs, is in no way contingent on participation or attendance at such activities.

(d) The restrictions on inherently religious activities set forth in this section do not apply to programs where DHS funds are provided to chaplains to work with inmates in detention facilities or where DHS funds are provided to religious or other organizations for programs in detention facilities, in which such organizations assist chaplains in carrying out their duties.

§ 19.5 Nondiscrimination requirements.

An organization that receives direct financial assistance from DHS pursuant to a social service program for any program or activity shall not favor or discriminate against a beneficiary or prospective beneficiary of said program or activity on the basis of religion, belief or religious practice.

§ 19.6 Independence of faith-based organizations.

(a) A faith-based organization that participates in a social services program administered by DHS or receives direct financial assistance from DHS for its own program or activity will retain its independence from Federal, State, and local governments, and may continue to carry out its mission, including the definition, practice, and expression of its beliefs.

(b) Faith-based organizations may use space in their facilities to provide social services utilizing financial assistance from DHS without removing or concealing religious articles, texts, art or symbols.

(c) A faith-based organization utilizing financial assistance from DHS for social services programs retains its authority over internal governance, and may also retain religious terms in its organization's name, select its board members on a religious basis, and include religious references in its organization's mission statements and other governing documents.

§ 19.7 Exemption from Title VII employment discrimination requirements.

(a) A faith-based organization's exemption from the Federal prohibition on employment discrimination on the basis of religion, set forth in section 702(a) of the Civil Rights Act of 1964 (42 U.S.C. 2000e-1), is not forfeited when the organization seeks or receives funding from DHS for a social services program or otherwise participates in a DHS program.

(b) Where a DHS program contains independent statutory or regulatory provisions that impose nondiscrimination requirements on all grantees, the provisions are not waived or mitigated by this regulation.

Accordingly, grantees should consult with the appropriate DHS program office to determine the scope of any applicable requirements.

§ 19.8 Commingling of Federal and State or local funds.

(a) If a State or local government voluntarily contributes its own funds to supplement federally funded activities, the State or local government has the option to segregate the Federal funds or commingle them.

(b) If the funds are commingled, the requirements of this section apply to all of the commingled funds.

(c) If a State or local government is required to contribute matching funds to supplement a federally funded activity, the matching funds are considered commingled with the Federal assistance and therefore subject to the requirements of this section.

44 CFR CHAPTER 1—FEDERAL EMERGENCY MANAGEMENT AGENCY, DEPARTMENT OF HOMELAND SECURITY

Subchapter A—General

PART 206—[AMENDED]

2. The authority citation for 44 CFR part 206 is revised to read as follows:

Authority: Robert T. Stafford Disaster Relief and Emergency Assistance Act, 42 U.S.C. 5121-5206; Reorganization Plan No. 3 of 1978, 43 FR 41943, 3 CFR, 1978 Comp., p. 329; E.O. 12127, 44 FR 19367, 3 CFR, 1979, Comp., p. 376; E.O. 12148, 44 FR 43239, 3 CFR 1979 Comp., p. 412; E.O. 12673, 54 FR 12571, 3 CFR, 1989 Comp., p. 214; sections 206.226 and 206.434 are also issued under the authority of 5 U.S.C. 301; 6 U.S.C. 111, 112; E.O. 13279, 67 FR 77141 and E.O. 13403, 71 FR 28543.

Subpart H—[Amended]

3. A new paragraph (l) to § 206.226 is added to read as follows:

§ 206.226 Restoration of damaged facilities.

* * * * *

(l) *Facilities owned, operated or controlled by faith-based organizations*—If an organization is otherwise eligible to receive funding under this section, the organization's status as faith-based shall not be considered in determining whether to authorize a grant or the amount of any such grant.

Subpart N—[Amended]

4. Section 206.434(a)(2) is revised to read as follows:

§ 206.434 Eligibility.

(a) * * *
(2) Private nonprofit organizations or institutions that own or operate a private nonprofit facility as defined in § 206.221. If an organization is otherwise eligible to receive funding under this section, the organization's status as faith-based shall not be considered in determining whether to authorize a grant or the amount of any such grant.

* * * * *

Dated: December 31, 2007.

Michael Chertoff,

Secretary.

[FR Doc. E8-463 Filed 1-11-08; 8:45 am]

BILLING CODE 4410-10-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0012; Directorate Identifier 2007-NM-204-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767-200, -300, and -400ER Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 767-200, -300, and -400ER series airplanes. This proposed AD would require an inspection to determine the manufacturer and manufacture date of the oxygen masks in the passenger service units and the flight attendant and lavatory oxygen boxes, as applicable. This proposed AD would also require related investigative/corrective actions if necessary. This proposed AD results from a report that several passenger masks with broken in-line flow indicators were found following a mask deployment. We are proposing this AD to prevent the in-line flow indicators of the passenger oxygen masks from fracturing and separating, which could inhibit oxygen flow to the masks and consequently result in exposure of the passengers and cabin

attendants to hypoxia following a depressurization event.

DATES: We must receive comments on this proposed AD by February 28, 2008.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
 - **Fax:** 202-493-2251.
 - **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
 - **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Susan Letcher, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 917-6474; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0012; Directorate Identifier 2007-NM-204-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report indicating that several passenger masks with broken in-line flow indicators were found following a mask deployment on a Boeing Model 777-200 series airplane. Operators subsequently found several more broken in-line flow indicators after examining the oxygen mask assemblies on other Model 777 series airplanes and on Model 747-400 series airplanes. Investigation revealed that certain flow indicators are weaker and can fracture because of internal residual stresses caused by the flow indicator joint design and manufacturing processes. Fractures cause the in-line flow indicator to separate and consequently prevent oxygen flow to the mask during an emergency. This condition, if not corrected, could result in exposure of the passengers and cabin attendants to hypoxia following a depressurization event.

The oxygen masks on certain Model 777 airplanes and Model 747-400 series airplanes have the same flow indicators as those installed on certain Model 767-200, -300, and -400ER series airplanes. Therefore, the Model 767-200, -300, and -400ER series airplanes may be subject to the identified unsafe condition.

Relevant Service Information

We have reviewed Boeing Special Attention Service Bulletin 767-35-0054, dated July 6, 2006. The service bulletin describes procedures for a general visual inspection to determine the manufacturer and manufacture date of the oxygen masks in the passenger service units and the flight attendant and lavatory oxygen boxes, as applicable. The service bulletin also describes procedures for doing related investigative and corrective actions. The related investigative action is a general visual inspection of the flow indicator to determine the color of the flow direction mark and the word "flow" on the flow indicator, if the identification (ID) label shows that the manufacturer is B/E Aerospace and the manufacture date is between January 1, 2002, and March 1, 2006. The corrective action is the installation of a new oxygen mask having an improved flow indicator, if the existing oxygen mask is found to be one of the discrepant masks.

Boeing Special Attention Service Bulletin 767-35-0054 refers to B/E Aerospace Service Bulletin 174080-35-01, dated February 6, 2006; and Revision 1, dated May 1, 2006; as additional sources of service information for getting a new oxygen mask having an improved flow indicator. B/E Aerospace Service Bulletin 174080-35-01 describes procedures for modifying the oxygen mask assembly by replacing the flow indicator, part number (P/N) 118023-02, with an improved flow indicator, P/N 118023-12. B/E Aerospace Service Bulletin 174080-35-01 also specifies that, as an alternative to modifying the oxygen mask, operators may replace the oxygen mask with a new oxygen mask having the improved flow indicator.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

Clarification Between the Proposed AD and Service Bulletin

Although Boeing Special Attention Service Bulletin 767-35-0054 specifies to install a new oxygen mask having an improved flow indicator, the intent of the service bulletin is to replace it with either a new or modified oxygen mask having an improved flow indicator. Therefore, this proposed AD would require replacing the oxygen mask assembly with a new or modified oxygen mask assembly having an improved flow indicator.

Costs of Compliance

There are about 688 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 242 airplanes of U.S. registry. The proposed actions would take about 53 work hours per airplane, with an average of 360 oxygen masks per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$1,026,080, or \$4,240 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue

rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2008-0012; Directorate Identifier 2007-NM-204-AD.

Comments Due Date

- (a) The FAA must receive comments on this AD action by February 28, 2008.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Boeing Model 767-200, -300, and -400ER series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 767-35-0054, dated July 6, 2006.

Unsafe Condition

(d) This AD results from a report that several passenger masks with broken in-line flow indicators were found following a mask deployment. We are issuing this AD to prevent the in-line flow indicators of the passenger oxygen masks from fracturing and separating, which could inhibit oxygen flow to the masks and consequently result in exposure of the passengers and cabin attendants to hypoxia following a depressurization event.

Compliance

- (e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection and Related Investigative/Corrective Actions if Necessary

(f) Within 60 months after the effective date of this AD, do a general visual inspection to determine the manufacturer and manufacture date of the oxygen masks in the passenger service units and the flight attendant and lavatory oxygen boxes, as applicable, and do the applicable related investigative and corrective actions, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of Boeing Special Attention Service Bulletin 767-35-0054, dated July 6, 2006; except where the service bulletin specifies installing a new oxygen mask, replace the oxygen mask with a new or modified oxygen mask having an improved flow indicator. The related investigative and corrective actions must be done before further flight.

Note 1: The service bulletin refers to B/E Aerospace Service Bulletin 174080-35-01, dated February 6, 2006; and Revision 1, dated May 1, 2006; as additional sources of service information for modifying the oxygen mask assembly by replacing the flow indicator with an improved flow indicator.

Alternative Methods of Compliance (AMOCs)

- (g)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in

accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on December 26, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-378 Filed 1-11-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0017; Directorate Identifier 2007-NM-268-AD]

RIN 2120-AA64

Airworthiness Directives; Saab Model SAAB-Fairchild SF340A (SAAB/SF340A) and SAAB 340B Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Subsequent to accidents involving Fuel Tank System explosions in flight * * * and on [the] ground, the FAA has published Special Federal Aviation Regulation No. 88 (SFAR-88) in June 2001 [which] required [conducting] a design review against explosion risks.

* * * * *

The potential of ignition sources (in certain fuel pumps, fuel switches, refuel shutoff valves, and optical sensors/mechanical switches), in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

DATES: We must receive comments on this proposed AD by February 13, 2008.