

Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) De Havilland Aircraft of Canada Limited Service Bulletin 84-32-167, dated August 12, 2021.

(ii) De Havilland Aircraft of Canada Limited Temporary Revision ALI-0223, dated October 15, 2020.

(3) For service information identified in this AD, contact De Havilland Aircraft of Canada Limited, Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd@dehavilland.com; internet <https://dehavilland.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on December 3, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-27709 Filed 12-17-21; 11:15 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-0869; Project Identifier AD-2021-00176-E; Amendment 39-21878; AD 2021-26-19]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain General Electric Company (GE) CF34-8C and CF34-8E model turbofan engines. This AD was prompted by a report of a quality escape during the manufacturing of a high-pressure turbine (HPT) rotor stage 1 disk. This AD requires removing the HPT rotor stage 1 disk from service and replacing the HPT rotor stage 1 disk with a part eligible for installation. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 25, 2022.

ADDRESSES: For service information identified in this final rule, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; phone: (513) 552-3272; email: aviation.fleetsupport@ge.com; website: <https://www.ge.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0869.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0869; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations U.S. Department of Transportation, Docket Operations, M-30, West Building, Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Scott Stevenson, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7132; fax: (781) 238-7199; email: Scott.M.Stevenson@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain GE CF34-8C5, CF34-

8C5B1, CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E5A2, CF34-8E6, and CF34-8E6A1 model turbofan engines. The NPRM published in the **Federal Register** on October 8, 2021 (86 FR 56217). The NPRM was prompted by GE notifying the FAA of a quality escape that occurred during the manufacturing of an HPT rotor stage 1 disk. The quality escape occurred at a supplier that began production in August 2019. On November 25, 2019, the supplier discovered tool gouges at the forward chamfer on the air holes of an HPT rotor stage 1 disk. These gouges may reduce the life of the HPT rotor stage 1 disk. In the NPRM, the FAA proposed to require removing a certain HPT rotor stage 1 disk from service and replacing the HPT rotor stage 1 disk with a part eligible for installation. The FAA is issuing this AD to address the unsafe condition on these products.

Discussion of Final Airworthiness Directive

Comments

The FAA received a comment from one commenter, the Air Line Pilots Association (ALPA). ALPA supported the NPRM without change.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting the AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. This AD is adopted as proposed in the NPRM.

Related Service Information

The FAA reviewed GE CF34-8C Alert Service Bulletin (ASB) 72-A0344 R01 and GE CF34-8E ASB 72-A0228 R01, both dated December 19, 2019. The ASBs describe procedures for removing the HPT rotor stage 1 disk. The FAA also reviewed GE Repair Document RD #150-1811-P1, dated March 17, 2020. This document describes procedures for repairing the HPT rotor stage 1 disk.

Costs of Compliance

The FAA estimates that this AD affects 23 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Remove and replace HPT rotor stage 1 disk	812 work-hours × \$85 per hour = \$69,020	\$258,100	\$327,120	\$7,523,760

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national

government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–26–19 General Electric Company:

Amendment 39–21878; Docket No. FAA–2021–0869; Project Identifier AD–2021–00176–E.

(a) Effective Date

This airworthiness directive (AD) is effective January 25, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to General Electric Company (GE) CF34–8C5, CF34–8C5B1, CF34–8E2, CF34–8E2A1, CF34–8E5, CF34–8E5A1, CF34–8E5A2, CF34–8E6, and CF34–8E6A1 model turbofan engines with an installed high-pressure turbine (HPT) rotor stage 1 disk, part number (P/N) 4125T22P04, and a serial number (S/N) listed in Figure 1 or Figure 2 to paragraph (c) of this AD.

BILLING CODE 4910–13–P

**Figure 1 to Paragraph (c) – HPT rotor stage 1 disk, P/N 4125T22P04,
installed on CF34-8C5 and CF34-8C5B1 engines**

HPT Rotor Stage 1 Disk S/N
NCU1234C
NCU0180C
NCU0174C
NCU0183C
NCU6175C
NCU6174C
NCU7694C
GATJ8T64
NCU7065C
NCU7068C
NCU6173C
NCU1232C
NCU7698C
GATJ8P5T

**Figure 2 to Paragraph (c) – HPT rotor stage 1 disk, P/N 4125T22P04,
installed on CF34-8E2, CF34-8E2A1, CF34-8E5, CF34-8E5A1, CF34-8E5A2, CF34-
8E6, and CF34-8E6A1 engines**

HPT Rotor Stage 1 Disk S/N
GATJ8PJF
GATJ8P5R
NCU9014C
NCU9654A
GATJ903T
NCU8314C
GATJ8WK4
NCU9785A
NCU1233C
NCU2151C
NCU7070C
NCU2920C
NCU7692C
NCU6171C
GATJ8TCF
GATJ8T63
NCU8313C

(d) Subject

Joint Aircraft System Component (JASC)
Code 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by a report of a quality escape during the manufacturing of an HPT rotor stage 1 disk. The FAA is issuing this AD to prevent failure of the HPT rotor stage 1 disk. The unsafe condition, if not addressed, could result in uncontained disk

release, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

For all affected engines, at the next engine shop visit or before the HPT rotor stage 1 disk accumulates 7,600 cycles since new,

whichever occurs first after the effective date of this AD, remove the HPT rotor stage 1 disk from service and replace with a part eligible for installation.

(h) Definitions

For the purpose of this AD:

(1) An “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine flanges, except that the separation of engine flanges solely for the

purposes of transportation without subsequent engine maintenance does not constitute an engine shop visit.

(2) A “part eligible for installation” is an HPT rotor stage 1 disk that is not listed in Figure 1 or Figure 2 to paragraph (c) of this AD or an HPT rotor stage 1 disk that has been repaired using an FAA-approved repair.

Note 1 to paragraph (h)(2): Guidance for repairing the HPT rotor stage 1 disk can be found in GE Repair Document RD #150–1811–P1, dated March 17, 2020.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: *ANE-AD-AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Scott Stevenson, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7132; fax: (781) 238–7199; email: *Scott.M.Stevenson@faa.gov*.

(k) Material Incorporated by Reference

None.

Issued on December 15, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–27480 Filed 12–20–21; 8:45 am]

BILLING CODE 4910–13–C

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0786; Project Identifier MCAI–2021–00429–A; Amendment 39–21843; AD 2021–24–22]

RIN 2120–AA64

Airworthiness Directives; Pilatus Aircraft Ltd. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2012–06–16, which applied to all Pilatus Aircraft Ltd. (Pilatus) Model PC–6, PC–6–H1, PC–6–H2, PC–6/350, PC–6/350–H1, PC–

6/350–H2, PC–6/A, PC–6/A–H1, PC–6/A–H2, PC–6/B–H2, PC–6/B1–H2, PC–6/B2–H2, PC–6/B2–H4, PC–6/C–H2, and PC–6/C1–H2 airplanes. AD 2012–06–16 required installing a new rudder and elevator locking screw and modifying the installation of the rudder and elevator hinge bolt. Since the FAA issued AD 2012–06–16, the European Union Aviation Safety Agency (EASA) superseded its mandatory continuing airworthiness information (MCAI) to correct an unsafe condition on these products. This AD does not retain any actions required by AD 2012–06–16 and requires inspecting and modifying the rudder, elevator, and right-hand (RH) aileron hinge bolt installations. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 25, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 25, 2022.

ADDRESSES: For service information identified in this final rule, contact Pilatus Aircraft Ltd., Customer Support General Aviation, CH–6371 Stans, Switzerland; phone: +41 848 247 365; email: *techsupport.ch@pilatus-aircraft.com*; website: *https://www.pilatus-aircraft.com*. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Examining the AD Docket

You may examine the AD docket at *https://www.regulations.gov* by searching for and locating Docket No. FAA–2021–0786; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the MCAI, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aviation Safety Engineer, FAA, General Aviation & Rotorcraft Section, International Validation Branch, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329–4059; fax: (816) 329–4090; email: *doug.rudolph@faa.gov*.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2012–06–16, Amendment 39–16997 (77 FR 19061, March 30, 2012) (AD 2012–06–16). AD 2012–06–16 applied to all Pilatus Model PC–6, PC–6–H1, PC–6–H2, PC–6/350, PC–6/350–H1, PC–6/350–H2, PC–6/A, PC–6/A–H1, PC–6/A–H2, PC–6/B–H2, PC–6/B1–H2, PC–6/B2–H2, PC–6/B2–H4, PC–6/C–H2, and PC–6/C1–H2 airplanes and required installing a new elevator and rudder locking screw and modifying the installation of the elevator and rudder hinge bolt. The NPRM published in the **Federal Register** on September 17, 2021 (86 FR 51835).

The NPRM was prompted by AD 2021–0098, dated April 9, 2021 (referred to after this as “the MCAI”), issued by EASA, which is the Technical Agent for the Member States of the European Union. The MCAI states:

Occurrences were reported where, on certain PC–6 aeroplanes, the elevator or the rudders was lost or partially detached during flight. All the occurrences happened on PC–6 aeroplanes in CONFIG 1.

This condition, if not corrected, could lead to in-flight failure of the elevator or rudder attachment, possibly resulting in reduced control of the aeroplane.

To address this potential unsafe condition, Pilatus issued SB 55–001 (original issue and Revision 1) to provide rework instructions for the elevator and rudder hinge bolt locking. Consequently, EASA published AD 2011–0230 to require this rework. Subsequently, Pilatus issued recommended SB 55–003 (later revised) to provide instructions to modify the hinge bolt installation of the elevator and rudder. This [service bulletin] SB, being recommended only, had no impact on the existing EASA AD.

Since that [EASA] AD and the recommended Pilatus SB 55–003 were published, the latest risk assessment determined that the modification of the hinge bolt installation of the elevator, rudder and right-hand (RH) aileron installation must be required to reach an acceptable level of safety for the affected aeroplanes. Consequently, Pilatus issued the SB, as defined in this [EASA] AD, to provide instructions to modify the affected aeroplanes into CONFIG 2 standard.

For the reasons described above, this [EASA] AD supersedes EASA AD 2011–0230 and requires, for certain aeroplanes, a one-time inspection of the elevator and rudder installation, followed by repetitive inspections of the elevator and rudder, and, depending on findings, accomplishment of applicable corrective action(s). This [EASA] AD also requires modification of the elevator, rudder and RH aileron hinge bolt installations into CONFIG 2, which is the terminating action for the repetitive inspections required by this [EASA] AD. Finally, this [EASA] AD prohibits (re)installation of affected parts.