

the bank's or saving association's capital and surplus.

* * * * *

Jonathan V. Gould,

Senior Deputy Comptroller and Chief Counsel.

[FR Doc. 2020-18937 Filed 9-30-20; 8:45 am]

BILLING CODE 4810-33-P

FARM CREDIT ADMINISTRATION

12 CFR Part 624

RIN 3052-AD43

Margin and Capital Requirements for Covered Swap Entities; Correction

AGENCY: Farm Credit Administration.

ACTION: Interim final rule; correction.

SUMMARY: The Farm Credit Administration is correcting a final rule that was published in the **Federal Register** on July 1, 2020. The Farm Credit Administration (FCA), along with the Comptroller of the Currency, the Board of Governors of the Federal Reserve System, the Federal Deposit Insurance Corporation, and the Federal Housing Finance Agency published an interim final rule amending regulations that require swap dealers, security-based swap dealers, major swap participants, and major security-based swap participants under the Agencies' respective jurisdictions to exchange margin with their counterparties for swaps that are not centrally cleared (non-cleared swaps) (Swap Margin Rule). In that publication, the Regulatory Identification Number (RIN) for the FCA was incorrect. This document corrects that error.

DATES: Effective October 1, 2020.

FOR FURTHER INFORMATION CONTACT:

Richard A. Katz, Senior Counsel, Office of General Counsel, (703) 883-4020, TTY (703) 883-4056, Farm Credit Administration, 1501 Farm Credit Drive, McLean, VA 22102-5090.

SUPPLEMENTARY INFORMATION: In FR Doc. 2020-14094, "Margin and Capital Requirements for Covered Swap Entities" that published in the **Federal Register** on Wednesday, July 1, 2020 at 85 FR 39464, in the second column on page 39464, correct the RIN to read 3052-AD43.

Dated: September 1, 2020.

Dale Aultman,

Secretary, Farm Credit Administration Board.

[FR Doc. 2020-19712 Filed 9-30-20; 8:45 am]

BILLING CODE 6705-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0443; Project Identifier AD-2020-00178-E; Amendment 39-21268; AD 2020-20-12]

RIN 2120-AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all General Electric Company (GE) GENx-1B64, -1B64/P1, -1B64/P2, -1B67, -1B67/P1, -1B67/P2, -1B70, -1B70/75/P1, -1B70/75/P2, -1B70/P1, -1B70/P2, -1B70C/P1, -1B70C/P2, -1B74/75/P1, -1B74/75/P2, -1B76/P2, and -1B76A/P2 model turbofan engines. This AD was prompted by reports of combustor case burn-through. This AD requires installation of electronic engine control (EEC) software, version B205 or later. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 5, 2020.

ADDRESSES: For service information identified in this final rule, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; phone: 513-552-3272; email: aviation.fleetsupport@ae.ge.com; website: www.ge.com. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0443.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0443; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Mehdi Lamnyi, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7743; fax: 781-238-7199; email: Mehdi.Lamnyi@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all GE GENx-1B64, -1B64/P1, -1B64/P2, -1B67, -1B67/P1, -1B67/P2, -1B70, -1B70/75/P1, -1B70/75/P2, -1B70/P1, -1B70/P2, -1B70C/P1, -1B70C/P2, -1B74/75/P1, -1B74/75/P2, -1B76/P2, and -1B76A/P2 model turbofan engines. The NPRM published in the **Federal Register** on May 6, 2020 (85 FR 26891). The NPRM was prompted by reports of combustor case burn-through. The NPRM proposed to require installation of EEC software, version B205 or later. The FAA is issuing this AD to address the unsafe condition on these products.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment.

Request To Supersede Existing AD

American Airlines (AAL) suggested that the FAA change this AD to supersede docket number FAA-2019-0683, project identifier 2015-NE-02-AD (84 FR 63820, November 19, 2019) ("NPRM 2015-NE-02-AD"). NPRM 2015-NE-02-AD proposed removing EEC software version B195 and earlier from GENx-1B engines, along with an equivalent EEC software for GENx-2B engines to improve safeguards against ice crystal icing. EEC software version B205 incorporates all required changes that satisfy the intent of NPRM 2015-NE-02.

The FAA disagrees. The unsafe condition addressed by this AD was prompted by reports of combustor case burn-through. In contrast, the final rule to NPRM 2015-NE-02-AD, AD 2020-13-04, Amendment 39-21149 (85 FR 37000, June 19, 2020) ("AD 2020-13-04") was prompted by power loss in ice crystal icing conditions. Although the ice crystal icing required actions of AD 2020-13-04 are achieved through the update to EEC software version B205, the unsafe conditions that prompted each AD are different, and the corrective actions are independent. Further, AD 2020-13-04 affects more GENx model turbofan engines than this AD.