The requirements in Chapter 2, Sections V.A.4 through V.G also apply to a credit union that serves a rural district.

■ 3. Amend Chapter 2 of Appendix B to part 701 by adding Section V.A.8 to read as follows:

## V.A.8 Community Selection Requirements and Review

The NCUA will not approve an application for a community charter consisting of all or a portion of a CSA or a CBSA, including an initial application, amendment, or expansion, unless the applicant demonstrates in its business and marketing plan that (1) the credit union will serve a community that is contiguous and (2) the credit union will provide financial services to low- and moderate-income and underserved people, and that the credit union has not selected its service area in order to exclude low- and moderate-income and underserved people. Upon receipt of this material, the NCUA will evaluate the business and marketing plan to ensure that low- and moderate-income and underserved people will be served and that the credit union has not selected the service area in order to exclude such people. This requirement is in addition to the requirement to document in the business and marketing plan the realistic assumptions that support the credit union's viability and its plan to serve its entire FOM.

The NCUA may conduct such further inquiry or evaluation as it deems appropriate, as authorized by 12 U.S.C. 1754 and consistent with the principles of this Manual, other federal laws, and public policy. If the NCUA determines that the credit union's submission is inaccurate or unsupported, it may deny that application on those grounds, regardless of whether the application satisfies the other criteria for initial chartering, amendment, or expansion.

■ 4. Section V.B of Chapter 2 of Appendix B to part 701 is revised to read as follows:

#### V.B Field of Membership Amendments

A community credit union may amend its field of membership by adding additional affinities or removing exclusionary clauses. This can be accomplished with a housekeeping amendment.

A community credit union also may expand its geographic boundaries. Persons who live, work, worship, or attend school within the proposed well-defined local community, neighborhood or rural district must have common interests and/or interact. The credit union must follow the requirements of Section V.A.4 and Section V.A.8 of this chapter.

A community credit union that is based on a Single Political Jurisdiction, a Statistical Area (*e.g.*, Core Based Statistical Area or Combined Statistical Area) or a rural district may expand its geographic boundaries to add a bordering area, provided the area is well defined and the credit union demonstrates that persons who live, work, worship, or attend school within the proposed expanded community (*i.e.*, on both sides of the boundary separating the existing community and the bordering area) have common interests and/or interact. Such a credit union applying to expand its geographic boundaries to add a bordering area must follow a streamlined version of the business plan requirements of Section V.A.4 of this chapter and the expanded community would be subject to the corresponding population limit—2.5 million in the case of a Single Political Jurisdiction, or a Statistical Area and 1 million in the case of a rural district. The streamlined business plan requirements for adding a bordering area are:

• Anticipated marginal financial impact on the credit union of adding the proposed bordering area, including the need for additional employees and fixed assets, and the associated costs;

• A description of the current and, if applicable, proposed office/branch structure specific to serving the proposed bordering area;

• A marketing plan addressing how the new community will be served for the 24month period after the proposed expansion of a community charter, including detailing how the credit union will address the unique needs of any demographic groups in the proposed bordering community not presently served by the credit union and how the credit union will market to any new groups; and

• Details, terms and conditions of any new financial products, programs, and services to be introduced as part of this expansion.

[FR Doc. 2019–23680 Filed 11–6–19; 8:45 am] BILLING CODE 7535–01–P

### DEPARTMENT OF TRANSPORTATION

## Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0863; Product Identifier 2019-NM-157-AD]

#### RIN 2120-AA64

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A318–112 A319–111, A319–112, A319–113, A319– 114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-216, A320-231, A320-232, A320–233, A320–251N, and A320–271N airplanes. This proposed AD was prompted by a report of marginal clearance between certain fuel sensor covers on both left-hand (LH) and righthand (RH) wings. This proposed AD would require the replacement of certain fuel level sensor brackets, as specified in a European Union Aviation Safety Agency (EASA) AD, which will

be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products. **DATES:** The FAA must receive comments on this proposed AD by December 23, 2019.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

• Federal eRulemaking Portal: Go to https://www.regulations.gov. Follow the instructions for submitting comments.

• Fax: 202–493–2251.

• *Mail:* U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material identified in this proposed AD that will be incorporated by reference (IBR), contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at *https://ad.easa.europa.eu*. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at *http://* www.regulations.gov by searching for and locating Docket No. FAA-2019-0863.

## **Examining the AD Docket**

You may examine the AD docket on the internet at *https:// www.regulations.gov* by searching for and locating Docket No. FAA–2019– 0863; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223. **SUPPLEMENTARY INFORMATION:** 

## **Comments Invited**

The FAA invites you to send any written relevant data, views, or

60002

arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA–2019–0863; Product Identifier 2019–NM–157–AD" at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM based on those comments.

The FAA will post all comments received, without change, to *https:// www.regulations.gov,* including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this NPRM.

### Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0197, dated August 14, 2019 ("EASA AD 2019-0197") (also referred to as the Mandatory Continuing Airworthiness Information, or "the MCAI''), to correct an unsafe condition for certain Airbus SAS Model A318-112, A319-111, A319-112, A319-113 A319–114, A319–115, A319–131, A319– 132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, and A320–271N airplanes. Model A320–215 airplanes are not on the U.S. Register; this AD therefore does not include those airplanes in the applicability.

This proposed AD was prompted by a report of marginal clearance between certain fuel sensor covers on rib 24 and the crown of stringer 15 on both LH and RH wings. A possible contact between the shield and the stringer, and/or possible motion between the stringer and the shield, can make the gap more susceptible to sparking in case of lightning strike. The FAA is proposing this AD to address this condition, which could create a source of ignition in a fuel tank vapor space, possibly resulting in a fire or explosion and consequent loss of the airplane. See the MCAI for additional background information.

## Related IBR Material Under 1 CFR Part 51

EASA AD 2019–0197 describes procedures for the replacement of certain fuel level sensor brackets. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

# FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to a bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

## **Proposed AD Requirements**

This proposed AD would require accomplishing the actions specified in EASA AD 2019–0197 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

## ESTIMATED COSTS FOR REQUIRED ACTIONS

# Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2019–0197 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2019-0197 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in the EASA AD. Service information specified in EASA AD 2019–0197 that is required for compliance with EASA AD 2019-0197 will be available on the internet at https://www.regulations.gov by searching for and locating Docket No. FAA-2019-0863 after the FAA final rule is published.

## **Costs of Compliance**

The FAA estimates that this proposed AD affects 776 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 7 work-hour $\times$ \$85 per hour = Up to \$595	Up to \$609	Up to \$1,204	Up to \$934,304.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action. This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

## **Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866, (2) Will not affect intrastate aviation

in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### §39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus SAS: Docket No. FAA–2019–0863; Product Identifier 2019–NM–157–AD.

#### (a) Comments Due Date

The FAA must receive comments by December 23, 2019.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Airbus SAS Model A318–112, A319–111, A319–112, A319–113, A319–114, A319–115, A319–131, A319–132, A319–133, A320–211, A320–212, A320–214, A320–216, A320–231, A320–232, A320–233, A320–251N, and A320–271N airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2019–0197, dated August 14, 2019 ('EASA AD 2019–0197'').

### (d) Subject

Air Transport Association (ATA) of America Code 28, Fuel.

#### (e) Reason

This AD was prompted by a report of marginal clearance between certain fuel sensor covers on rib 24 and the crown of stringer 15 on both left-hand (LH) and righthand (RH) wings. A possible contact between the shield and the stringer, and/or possible motion between the stringer and the shield, can make the gap more susceptible to sparking in case of lightning strike. The FAA is issuing this AD to address this condition, which could create a source of ignition in a fuel tank vapor space, possibly resulting in a fire or explosion and consequent loss of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2019–0197.

#### (h) Exceptions to EASA AD 2019-0197

(1) Where EASA AD 2019–0197 refers to its effective date, this AD requires using the effective date of this AD.

(2) The "Remarks" section of EASA AD 2019–0197 does not apply to this AD.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOAauthorized signature.

(3) Required for Compliance (RC): For any service information referenced in EASA AD 2019–0197 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (j) Related Information

(1) For information about EASA AD 2019– 0197, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email *ADs*@ *easa.europa.eu*; internet *www.easa.europa.eu*. You may find this EASA AD on the EASA website at *https:// ad.easa.europa.eu*. You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at *https://* 

*www.regulations.gov* by searching for and locating Docket No. FAA–2019–0863.

(2) For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223.

Issued in Des Moines, Washington, on November 1, 2019.

### Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–24269 Filed 11–6–19; 8:45 am] BILLING CODE 4910–13–P

## **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. FAA-2019-0016; Product Identifier 2018-NM-168-AD]

## RIN 2120-AA64

## Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Supplemental notice of proposed rulemaking (SNPRM); reopening of comment period.

**SUMMARY:** The FAA is revising an earlier proposal for all Airbus SAS Model A350–941 and –1041 airplanes. This action revises the notice of proposed rulemaking (NPRM) by including additional part numbers that are affected by the unsafe condition. The FAA is proposing this airworthiness directive (AD) to address the unsafe condition on these products. Since these actions would impose an additional burden over those in the NPRM, the