

Proposed Rules

Federal Register

Vol. 68, No. 74

Thursday, April 17, 2003

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF AGRICULTURE

Agricultural Marketing Service

7 CFR Part 929

[Docket No. FV03-929-2]

Cranberries Grown in the States of Massachusetts, Rhode Island, Connecticut, New Jersey, Wisconsin, Michigan, Minnesota, Oregon, Washington, and Long Island in the State of New York; Continuance Referendum

AGENCY: Agricultural Marketing Service, USDA.

ACTION: Referendum order.

SUMMARY: This document directs that a continuance referendum be conducted among eligible growers of cranberries in the States of Massachusetts, Rhode Island, Connecticut, New Jersey, Wisconsin, Michigan, Minnesota, Oregon, Washington, and Long Island in the State of New York to determine whether they favor continuance of the marketing order regulating the handling of cranberries grown in the production area.

DATES: The referendum will be conducted from May 19 through May 30, 2003. To vote in this referendum, growers must have been engaged in producing cranberries within the production area during the period September 1, 2001, through August 31, 2002.

ADDRESSES: Copies of the marketing order may be obtained from USDA, Washington DC Marketing Field Office, 4700 River Road, Unit 155, Room 2A38, Riverdale, Maryland, 20737, or the Office of the Docket Clerk, Marketing Order Administration Branch, Fruit and Vegetable Programs, Agricultural Marketing Service, U.S. Department of Agriculture, 1400 Independence Avenue SW., Stop 0237, Washington, DC, 20250-0237.

FOR FURTHER INFORMATION CONTACT: Kenneth G. Johnson, Regional Manager, Washington, DC Marketing Field Office,

Marketing Order Administration Branch, Fruit and Vegetable Programs, Agricultural Marketing Service, U.S. Department of Agriculture, 4700 River Road Unit 155, Room 2A38, Riverdale, MD 20737; telephone (301) 734-5243; fax (301) 734-5275; or Melissa Schmaedick, Marketing Order Administration Branch, Fruit and Vegetable Programs, Agricultural Marketing Service, U.S. Department of Agriculture, P.O. Box 1035, Moab, UT 84532; telephone (435) 259-7988; fax (435) 259-4945.

SUPPLEMENTARY INFORMATION: Pursuant to Marketing Order No. 929 (7 CFR part 929), hereinafter referred to as the "order," and the applicable provisions of the Agricultural Marketing Agreement Act of 1937, as amended (7 U.S.C. 601-674), hereinafter referred to as the "Act," it is hereby directed that a referendum be conducted to ascertain whether continuance of the order is favored by growers. The referendum shall be conducted during the period May 19 through May 30, 2003, among eligible cranberry growers in the production area. Only growers that were engaged in the production of cranberries in the States of Massachusetts, Rhode Island, Connecticut, New Jersey, Wisconsin, Michigan, Minnesota, Oregon, Washington, and Long Island in the State of New York during the period of September 1, 2001, through August 31, 2002, may participate in the continuance referendum.

USDA has determined that continuance referenda are an effective means for determining whether growers favor continuation of marketing order programs. The USDA would not consider termination of the order if more than 50 percent of the growers who vote in the referendum and growers of more than 50 percent of the volume of cranberries represented in the referendum favor continuance of their program.

In evaluating the merits of continuance versus termination, the USDA will not only consider the results of the continuance referendum. The USDA will also consider all other relevant information concerning the operation of the order and the relative benefits and disadvantages to growers, processors, and consumers in order to determine whether continued operation of the order would tend to effectuate the declared policy of the Act.

In accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. chapter 35), the ballot materials used in the referendum herein ordered have been submitted to and approved by the Office of Management and Budget (OMB) and have been assigned OMB No. 0581-0103. It has been estimated that it will take an average of 30 minutes for each of the approximately 1,100 producers of cranberries in the production area to cast a ballot. Participation is voluntary. Ballots postmarked after May 30, 2003, will be marked invalid and not included in the vote tabulation.

Kenneth G. Johnson, James B. Wendland, Patricia A. Petrella and Dawana Clark of the Washington, DC Marketing Field Office, Fruit and Vegetable Programs, Agricultural Marketing Service, USDA, are hereby designated as the referendum agents of USDA to conduct such referendum. The procedure applicable to the referendum shall be the "Procedure for the Conduct of Referenda in Connection With Marketing Orders for Fruits, Vegetables, and Nuts Pursuant to the Agricultural Marketing Agreement Act of 1937, as Amended" (7 CFR 900.400 *et seq.*).

Ballots will be mailed to all growers of record and may also be obtained from the referendum agents and from their appointees.

List of Subjects in 7 CFR Part 929

Cranberries, Marketing agreements, Reporting and recordkeeping requirements.

Authority: 7 U.S.C. 601-674.

Dated: April 10, 2003.

A.J. Yates,
Administrator, Agricultural Marketing Service.

[FR Doc. 03-9409 Filed 4-16-03; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-324-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 747 series airplanes. This proposal would require repetitive inspections for discrepancies of certain areas of the forward and aft sides of the body station 2598 bulkhead, and repair if necessary. This action is necessary to find and fix such discrepancies of the bulkhead structure, which could result in failure of the structure to carry flight loads of the horizontal stabilizer, and consequent loss of controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by June 2, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-324-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-324-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Rick Kawaguchi, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6434; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and

be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2001-NM-324-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-324-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received several reports of fatigue cracking in the bulkhead inner chords, outer chords, and diagonal brace attachment fittings on certain Boeing Model 747 series airplanes. The cracks ranged from 0.4 inch to 2.0 inches long and have been found on both the left and right sides of the bulkhead structure. These airplanes had accumulated between 5,982 and 18,487 total flight cycles. In addition, elongated fastener holes have been found in the diagonal brace rods on several airplanes. Such discrepancies of the bulkhead structure, if not found and fixed, could result in failure of the structure to carry flight loads of the horizontal stabilizer,

and consequent loss of controllability of the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 747-53A2467, including Evaluation Form, dated July 26, 2001, which describes procedures for repetitive detailed inspections of the body station 2598 bulkhead for discrepancies (cracking, elongated fastener holes) of the lower aft inner chords; upper aft outer chords; and diagonal brace attachment fittings, flanges, and rods and repair of any cracking or elongated fastener holes, if necessary. The service bulletin also specifies contacting Boeing for repair procedures for cracking of the outer chord. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

Difference Between This Proposed AD and the Service Information

Although the service bulletin specifies that the manufacturer may be contacted for disposition of certain repair conditions, this proposed AD would require the repair of those conditions to be accomplished in accordance with a method approved by the FAA, or in accordance with data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the FAA to make such findings.

Interim Action

This is considered to be interim action. The manufacturer has advised that it currently is developing a modification that will address the unsafe condition identified in this AD. Once this modification is developed, approved, and available, the FAA may consider further rulemaking.

Cost Impact

There are approximately 1,147 airplanes of the affected design in the worldwide fleet. The FAA estimates that 280 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 4 work hours

per airplane to accomplish the proposed inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$67,200, or \$240 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 2001–NM–324–AD.

Applicability: Model 747 series airplanes, line numbers 1 through 1307 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To find and fix discrepancies of the bulkhead structure, which could result in failure of the structure to carry flight loads of the horizontal stabilizer, and consequent loss of controllability of the airplane, accomplish the following:

Repetitive Inspections

(a) Before the accumulation of 10,000 total flight cycles or within 1,000 flight cycles after the effective date of this AD, whichever is later: Do a detailed inspection of the body station 2598 bulkhead for discrepancies (cracking, elongated fastener holes) of the lower aft inner chords; upper aft outer chords; and diagonal brace attachment fittings, flanges, and rods; per Boeing Alert Service Bulletin 747–53A2467, excluding Evaluation Form, dated July 26, 2001. Repeat the inspection after that at intervals not to exceed 3,000 flight cycles.

Note 2: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Repair

(b) If any discrepancy is found during any inspection required by paragraph (a) of this AD: Before further flight, repair per Boeing Alert Service Bulletin 747–53A2467, excluding Evaluation Form, dated July 26,

2001. If any discrepancy is found and the service bulletin specifies to contact Boeing for appropriate action: Before further flight, repair per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved, the approval must specifically reference this AD.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permit

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 11, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 03–9432 Filed 4–16–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2003–14402; Airspace Docket No. 01–AWA–4]

RIN 2120–AA66

Proposed Modification of the Houston Class B Airspace Area; TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to modify the current Houston, TX, Class B airspace area to contain large turbine-powered aircraft during operations to the new Runway 8L/26R at George Bush Intercontinental Airport (IAH), and to the new primary runway (Runway 4) at William P. Hobby Airport (HOU). The FAA is proposing this action to enhance safety, and improve the management of