

suggestion should be considered when the underlying regulation was otherwise being amended by FHFA. In other cases, FHFA determined that an amendment was not necessary because, for example, the comment requested a clarification that could effectively be provided through another means (such as an interpretation or guidance).

### III. FHFA's 2023 Regulatory Review; Request for Comment

Consistent with its Review Plan, FHFA's next regulatory review must begin not later than five years after its prior review, or in April 2023. All current regulations—except, as noted, rules of agency organization, procedure, or practice, or regulations adopted or substantially amended since April 2021 (meaning, within the past two years)—are subject to review. If members of the public comment on recently adopted or amended regulations, FHFA may consider those comments, as it deems appropriate. FHFA does not anticipate responding to individual comments.

Regulations administered by FHFA are published in chapter XII of title 12 of the Code of Federal Regulations, except for two regulations of predecessor agencies which FHFA has not yet moved.<sup>3</sup> FHFA's regulations are also posted on the FHFA website at <https://www.fhfa.gov>.

FHFA hereby requests comment on its regulations for purposes of improving their effectiveness and reducing their burden. Factors that FHFA's Review Plan identifies as relevant to the review, and which FHFA suggests should guide commenters, are:

(1) Legal or regulatory developments—including new laws, executive orders, or judicial decisions that have been adopted since the promulgation of a regulation—that make a regulation inefficient, obsolete, contrary to controlling legal precedent, or unduly burdensome;

(2) Marketplace developments, technological evolution, and related changes that may have rendered a regulation, in whole or in part, inefficient, outmoded, or outdated;

(3) The extent to which provisions of the regulation are written in plain language or need clarification;

(4) Compelling evidence that a consolidation of two or more

regulations, elimination of a duplicative regulation, or other revision to regulatory requirements would facilitate compliance by Fannie Mae, Freddie Mac, any affiliate of either Enterprise, the Banks, or OF with the regulation, or would improve supervision by FHFA of Fannie Mae, Freddie Mac, any affiliate of either Enterprise, the Banks, or OF; and

(5) Demonstration of a better alternative method to effect a regulatory purpose or requirement, supported by compelling evidence of significantly less intrusive means or of a substantially more efficient method of accomplishing the same supervisory purpose.

In accordance with FHFA's Review Plan, the 2023 regulatory review process will be conducted by the FHFA Office of General Counsel, which will review all comments received and consult with other FHFA offices and divisions. After that review, a report of findings and recommendations will be provided to the FHFA Director. The report of findings and recommendations will be privileged and confidential. After receiving the report of findings and recommendations, the Director will determine what steps may be necessary to relieve any unnecessary burden, including amendment to or repeal of existing regulations or issuance of less formal guidance.

The 2023 FHFA regulatory review is not a formal or informal rulemaking proceeding under the Administrative Procedure Act and creates no right of action against FHFA. FHFA's determination whether to conduct or not to conduct a review of a regulation and any determination, finding, or recommendation resulting from any review is not a final agency action and therefore is not subject to judicial review.

**Sandra L. Thompson,**

*Director, Federal Housing Finance Agency.*

[FR Doc. 2023-07928 Filed 4-13-23; 8:45 am]

**BILLING CODE 8070-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2023-0929; Project Identifier MCAI-2022-01401-T]

**RIN 2120-AA64**

### Airworthiness Directives; BAE Systems (Operations) Limited Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all BAE Systems (Operations) Limited Model 4101 airplanes. This proposed AD was prompted by in-service cracking of the passenger door edge member, seal carrier, and inner skin, adjacent to the roller guide bracket. This proposed AD would require a one-time inspection of the external visible surface of the inner skin, door edge member, and seal carrier adjacent to the roller bracket attachment brackets; and the inner skin, door edge member, and seal carrier at the roller bracket attachment bore, and repair if necessary. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by May 30, 2023.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-0929; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

### Material Incorporated by Reference

- For service information identified in this NPRM, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email [RApublications@baesystems.com](mailto:RApublications@baesystems.com); website [regional-services.com](https://www.baesystems.com/regional-services.com).

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the

<sup>3</sup> These are a regulation of the former Office of Federal Housing Enterprise Oversight on Prompt Corrective Action related to the Enterprises, at 12 CFR part 1777, which FHFA has suspended due to the Enterprise conservatorships; and a regulation of the Department of Housing and Urban Development on public-use databases and public information provided by the Enterprises, at 24 CFR part 81, subpart F.

availability of this material at the FAA, call 206–231–3195.

**FOR FURTHER INFORMATION CONTACT:**

Todd Thompson, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3228; email [todd.thompson@faa.gov](mailto:todd.thompson@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2023–0929; Project Identifier MCAI–2022–01401–T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or

responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Todd Thompson, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3228; email [todd.thompson@faa.gov](mailto:todd.thompson@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

The Civil Aviation Authority (CAA), which is the aviation authority for the United Kingdom (U.K.), has issued U.K. CAA AD G–2022–0019, dated October 31, 2022 (U.K. CAA AD G–2022–0019) (also referred to after this as the MCAI), to correct an unsafe condition on all BAE Systems (Operations) Limited Model 4101 airplanes. The MCAI states that in-service cracking occurred on the Jetstream 41 passenger door edge member, seal carrier, and inner skin, adjacent to the roller guide bracket. BAE Systems (Operations) Limited reviewed the fatigue test data and existing inspection requirements, and concluded a new inspection is needed to address this potential unsafe condition.

The FAA is proposing this AD to address undetected cracking of the passenger door. The unsafe condition, if not addressed, could result in a partial failure of the door, hindering passenger evacuation during an emergency or possibly causing cabin pressurization problems during flight, requiring passengers and crew to don oxygen masks.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–0929.

**Related Service Information Under 1 CFR Part 51**

The FAA reviewed BAe JETSTREAM Series 4100 Service Bulletin, Revision 1, dated June 8, 2022. This service information specifies procedures for a one-time eddy current inspection of the external visible surface of the inner skin, door edge member, and seal carrier adjacent to the roller bracket attachment brackets for cracking; a one-time eddy current inspection of the inner skin, door edge member, and seal carrier at the roller bracket attachment bores for cracking; and repair.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**FAA’s Determination**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information described above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Proposed AD Requirements in This NPRM**

This proposed AD would require accomplishing the actions specified in the service information already described.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 12 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = Up to \$170 .....	\$0	\$170	\$2,040

The FAA has received no definitive data on which to base the cost estimates for the on-condition actions specified in this proposed AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce.

This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**BAE Systems (Operations) Limited:** Docket No. FAA–2023–0929; Project Identifier MCAI–2022–01401–T.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by May 30, 2023.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all BAE Systems (Operations) Limited Model 4101 airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

#### (e) Unsafe Condition

This AD was prompted by in-service cracking of the passenger door edge member, seal carrier, and inner skin, adjacent to the roller guide bracket. The FAA is issuing this AD to address undetected cracking of the passenger door. The unsafe condition, if not addressed, could result in a partial failure of the passenger door, and consequent reduced structural integrity of the passenger door.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Inspections

At the applicable time specified in paragraph (g)(1) or (2) of this AD, accomplish an eddy current inspection of the external visible surface of the inner skin, door edge member, and seal carrier adjacent to the roller bracket attachment brackets for cracking; and an eddy current inspection of the inner skin, door edge member, and seal carrier at the roller bracket attachment bores for cracking, in accordance with paragraph 2.B. of the Accomplishment Instructions of BAe JETSTREAM Series 4100 Service Bulletin J41–52–065, Revision 1, dated June 8, 2022.

(1) For airplanes that have accumulated 18,000 total flight cycles or fewer as of the effective date of this AD: Accomplish the inspections prior to the accumulation of 20,000 total flight cycles.

(2) For airplanes that have accumulated more than 18,000 total flight cycles as of the effective date of this AD: Accomplish the inspections within 2,000 flight cycles after the effective date of this AD.

#### (h) Corrective Actions

If, during any inspection required by paragraph (g) of this AD, any crack is detected: Before further flight, repair using a method approved by the Manager, International Validation Branch, FAA; or the United Kingdom Civil Aviation Authority (U.K. CAA); or BAE Systems (Operations) Limited’s U.K. CAA’s (DOA). If approved by the DOA, the approval must include the DOA-authorized signature

#### (i) No Reporting Requirement

Although BAe JETSTREAM Series 4100 Service Bulletin J41–52–065, Revision 1, dated June 8, 2022, specifies to submit certain information to the manufacturer, this AD does not include that requirement.

#### (j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager, International Validation Branch, mail it to the address identified in paragraph (k)(2) of this AD or email to: 9-

AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or the U.K. CAA; or BAE Systems (Operations) Limited’s U.K. CAA’s Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (k) Additional Information

(1) Refer to U.K. CAA G–2022–0019, dated October 31, 2022, for related information. This U.K. CAA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–0929.

(2) For more information about this AD, contact Todd Thompson, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3228; email [todd.thompson@faa.gov](mailto:todd.thompson@faa.gov).

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) BAe JETSTREAM Series 4100 Service Bulletin J41–52–065, Revision 1, dated June 8, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email [RApublications@baesystems.com](mailto:RApublications@baesystems.com); website [regional-services.com](http://regional-services.com).

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov), or go to: [www.archives.gov/federal-register/cfr/ibr-locations.html](http://www.archives.gov/federal-register/cfr/ibr-locations.html).

Issued on April 8, 2023.

**Christina Underwood,**  
Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–07826 Filed 4–13–23; 8:45 am]

**BILLING CODE 4910–13–P**