

During a normal walkaround check on a F28 Mark 0100 aeroplane, a large crack was discovered in the lower portion of the right (RH) MLG piston. The affected MLG unit had accumulated 7909 flight cycles (FC) at the time of detection. The piston has been sent to Goodrich, the landing gear manufacturer, for detailed investigation.

This condition, if not detected and corrected, could lead to MLG failure, possibly resulting in loss of control of the aeroplane during the landing roll-out.

For the reasons described above, this AD requires a one-time detailed visual inspection of the MLG pistons, the replacement of any MLG pistons on which cracks are detected, and the reporting of all findings to the aeroplane TC [type certificate] holder. The inspection results, in combination with the findings of the crack/metallurgical investigation of the cracked piston by Goodrich, will be used to determine the necessity of additional and/or more detailed inspections, or any other corrective action. This AD is considered an interim measure, and further action is likely to follow.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection

(g) Within 30 days after the effective day of this AD, do a detailed visual inspection for cracks of the MLG pistons, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-32-158, dated October 2, 2009.

(h) If any cracked MLG piston is found during the inspection required by paragraph (g) of this AD, before further flight replace the affected piston with a serviceable part, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-32-158, dated October 2, 2009.

(i) At the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, report the inspection results (including no findings) to Fokker Services B.V. by using the Questionnaire provided in Fokker Service Bulletin SBF100-32-158, dated October 2, 2009.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: The applicability of the MCAI includes MLG part number (P/N) 41050-6, which is not an affected part. P/N 41060-6, however, is an affected part, and is included in the applicability of this AD.

Other FAA AD Provisions

(j) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International

Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone 425-227-1137; fax 425-227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(k) For related information, refer to MCAI European Aviation Safety Agency Airworthiness Directive 2009-0221, dated October 14, 2009; and Fokker Service Bulletin SBF100-32-158, dated October 2, 2009.

Issued in Renton, Washington, on October 13, 2010.

John Piccola,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-26561 Filed 10-20-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2010-0771; Airspace Docket No. 10-AGL-12]

Proposed Amendment of Class E Airspace; Mansfield, OH

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace at Mansfield, OH. Additional controlled airspace is necessary to accommodate new Standard Instrument Approach Procedures (SIAPs) at Mansfield Lahm

Regional Airport. The FAA is taking this action to enhance the safety and management of Instrument Flight Rules (IFR) operations at the airport.

DATES: Comments must be received on or before December 6, 2010.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2010-0771/Airspace Docket No. 10-AGL-12, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FOR FURTHER INFORMATION CONTACT: Scott Enander, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone: 817-321-7716.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2010-0771/Airspace Docket No. 10-AGL-12." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking

documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Central Service Center, 2601 Meacham Blvd., Fort Worth, TX 76137.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking 202-267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

This action proposes to amend title 14, Code of Federal Regulations (14 CFR), part 71 by adding additional Class E airspace extending upward from 700 feet above the surface for SIAPs at Mansfield Lahm Regional Airport, Mansfield, OH. Controlled airspace is needed for the safety and management of IFR operations at the airport.

Class E airspace areas are published in Paragraph 6005 of FAA Order 7400.9U, dated August 18, 2010, and effective September 15, 2010, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in title 49 of the U.S. Code. Subtitle I, section

106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in subtitle VII, part A, subpart I, section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would add additional controlled airspace at Mansfield Lahm Regional Airport, Mansfield, OH.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9U Airspace Designations and Reporting Points, dated August 18, 2010, and effective September 15, 2010, is amended as follows:

Paragraph 6005 Class E Airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

AGL OH E5 Mansfield, OH [Amended]

Mansfield, Mansfield Lahm Regional Airport, OH

(Lat. 40°49'17" N., long. 82°31'00" W.)

Galion, Galion Municipal Airport, OH

(Lat. 40°45'12" N., long. 82°43'26" W.)

Shelby, Shelby Community Airport, OH

(Lat. 40°52'22" N., long. 82°41'51" W.)

Willard, Willard Airport, OH

(Lat. 41°02'20" N., long. 82°43'28" W.)

Mansfield VORTAC

(Lat. 40°52'07" N., long. 82°35'28" W.)

That airspace extending upward from 700 feet above the surface within a 6.9-mile radius of Mansfield Lahm Regional Airport, and within a 6.3-mile radius of Galion Municipal Airport, and within a 6.3-mile radius of Shelby Community Airport, and within a 6.3-mile radius of Willard Airport, and within 4 miles each side of the 137° bearing from Mansfield Lahm Regional

Airport extending from the 6.9-mile radius to 11.1 miles southeast of the airport, and within 4 miles each side of the 317° bearing from Mansfield Lahm Regional Airport extending from the 6.9-mile radius to 10.7 miles northwest of the airport, and within 4 miles each side of the 047° bearing from Mansfield Lahm Regional Airport extending from the 6.9-mile radius to 11.2 miles northeast of the airport, and within 4 miles each side of the 227° bearing from Mansfield Lahm Regional Airport extending from the 6.9-mile radius to 10.9 miles southwest of the airport, and within 6.1 miles each side of the Mansfield VORTAC 307° radial extending from the 6.9-mile radius to 13.3 miles northwest of the VORTAC, and within 4.4 miles each side of the Mansfield VORTAC 130° radial extending from the 6.9-mile radius to 13.8 miles southeast of the VORTAC.

Issued in Fort Worth, TX, on October 6, 2010.

Anthony D. Roetzel,

Manager, Operations Support Group, ATO Central Service Center.

[FR Doc. 2010-26528 Filed 10-20-10; 8:45 am]

BILLING CODE 4901-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2010-0770; Airspace Docket No. 10-AGL-11]

Proposed Amendment of Class E Airspace; Columbus, OH

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace in the Columbus, OH area. Additional controlled airspace is necessary to accommodate new Standard Instrument Approach Procedures (SIAPs) at Port Columbus International Airport. The FAA is taking this action to enhance the safety and management of Instrument Flight Rules (IFR) operations at the airport.

DATES: 0901 UTC. Comments must be received on or before December 6, 2010.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2010-0770/Airspace Docket No. 10-AGL-11, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>.