

**(b) Unsafe Condition**

This AD defines the unsafe condition as defective duplex bearings on MGB input modules, due to a quality control issue. This condition could result in damage including corrosion and cracking, which could result in excessive heat of the input module duplex ball bearing inner race and subsequent loss of engine power and loss of helicopter control.

**(c) Effective Date**

This AD becomes effective October 15, 2020.

**(d) Compliance**

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

**(e) Required Actions**

(1) If the P/N and S/N of both MGB input modules are listed in paragraph (a) of this AD, within 300 hours time-in-service (TIS), remove from service each MGB input module.

(2) If the P/N and S/N of only one MGB input module are listed in paragraph (a) of this AD, within 1,200 hours TIS, remove from service that MGB input module.

(3) After the effective date of this AD, do not install an MGB input module with a P/N and S/N listed in paragraph (a) of this AD on any helicopter.

**(f) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Rao Edupuganti, Aviation Safety Engineer, Regulations and Policy Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

**(g) Additional Information**

(1) Leonardo Helicopters Bollettino Tecnico No. 139-303, dated September 20, 2016, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Leonardo S.p.a. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-225074; fax +39-0331-229046; or at <https://www.leonardocompany.com/en/home>. You may view a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency)

(EASA) AD No. 2016-0255R1, dated January 17, 2017. You may view the EASA AD on the internet at <https://www.regulations.gov> in Docket No. FAA-2020-0554.

**(h) Subject**

Joint Aircraft Service Component (JASC)  
Code: 6320, Rotor Drive-Gearbox.

Issued on September 3, 2020.

**Lance T. Gant,**

*Director, Compliance & Airworthiness  
Division, Aircraft Certification Service.*

[FR Doc. 2020-19906 Filed 9-9-20; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF DEFENSE****Office of the Secretary****32 CFR Part 204**

[Docket ID: DOD-2018-OS-0044]

**RIN 0790-AK45**

**User Fees**

**AGENCY:** Office of the Under Secretary of Defense (Comptroller), Department of Defense (DoD).

**ACTION:** Final rule.

**SUMMARY:** This final rule removes DoD's regulation that provides instructions to DoD Components on establishing appropriate fees for authorized services supplied by DoD organizations when such services provide special benefits to an identifiable recipient beyond those that accrue to the general public. User fees paid by the public represent either the full cost to the DoD, or the market value of providing the service, resource, or good. The regulation is unnecessary because it restates current law; sets forth internal policy and procedures; and conveys to the public administrative and procedural information that does not require rulemaking. Therefore, this rule is unnecessary and can be removed from the CFR.

**DATES:** This rule is effective on September 10, 2020.

**FOR FURTHER INFORMATION CONTACT:** Kellie Allison at 703-614-0410.

**SUPPLEMENTARY INFORMATION:** It has been determined that publication of this CFR part removal for public comment is impracticable, unnecessary, and contrary to public interest since it is based on removing DoD guidance that is not required to be codified and is publicly available on the Department's website. DoD guidance will continue to be published in DoD 7000.14-R, Financial Management Regulation, Volume 11A, Chapter 4, "User Fees" available at <https://comptroller>.

[defense.gov/Portals/45/documents/fmr/current/11a/11a\\_04.pdf](https://defense.gov/Portals/45/documents/fmr/current/11a/11a_04.pdf).

This rule is not significant under Executive Order (E.O.) 12866, "Regulatory Planning and Review," therefore, E.O. 13771, "Reducing Regulation and Controlling Regulatory Costs," does not apply.

This removal supports a recommendation of the DoD Regulatory Reform Task Force.

**List of Subjects in 32 CFR Part 204**

Accounting, Armed forces,  
Government property.

**PART 204—[REMOVED]**

■ Accordingly, by the authority of 5 U.S.C. 301, 32 CFR part 204 is removed.

Dated: September 4, 2020.

**Aaron T. Siegel,**

*Alternate OSD Federal Register Liaison  
Officer, Department of Defense.*

[FR Doc. 2020-20005 Filed 9-9-20; 8:45 am]

**BILLING CODE 5001-06-P**

**DEPARTMENT OF DEFENSE****Office of the Secretary****32 CFR Part 217**

[Docket ID: DOD-2020-OS-0059]

**RIN 0790-AL02**

**Service Academies**

**AGENCY:** Office of the Under Secretary of Defense for Personnel and Readiness, Department of Defense (DoD).

**ACTION:** Final rule.

**SUMMARY:** This regulatory action removes this part from the Code of Federal Regulations (CFR), as information contained within this rule is an overview of policy and statute that provides guidance and direction to members of the DoD and not members of the public. Therefore, this rule can be removed from the CFR.

**DATES:** This rule is effective on September 10, 2020.

**FOR FURTHER INFORMATION CONTACT:** Lt Col David Nuckles, (703) 695-5529.

**SUPPLEMENTARY INFORMATION:** This rule was added to the CFR on December 31, 2015 (80 FR 81760-81767). This rule is redundant in that it established policy, assigned responsibilities, and prescribed procedures for members of the DoD on operation and oversight of the Military Service Academies, and does not regulate the public. Internal Departmental policies are current and reflective of these and other requirements in statute, and public