## **Proposed Rules**

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## SMALL BUSINESS ADMINISTRATION

## 13 CFR Parts 107 and 121

## SBA Small Business Investment Company (SBIC) Proposed Regulations Webinar

**AGENCY:** U.S. Small Business Administration (SBA). **ACTION:** Notification of webinar on proposed regulations.

**SUMMARY:** The SBA is holding a webinar to update the public on proposed regulations to the Small Business Investment Company (SBIC) program contained in the proposed rule titled Small Business Investment Company Investment Diversification and Growth. **DATES:** The public webinar will be held on Monday, 11/28/2022, from 4 to 5 p.m. Eastern Time.

**ADDRESSES:** The Small Business Investment Company Investment Diversification and Growth Proposed Regulations Webinar will be live streamed on Microsoft Teams for the public.

**FOR FURTHER INFORMATION CONTACT:** The meeting will be live streamed to the public, and anyone wishing to attend or needing accommodations because of a disability can contact Nathaniel Putnam, SBA, Office of Investment & Innovation (OII), (202)714–1632, *nathaniel.putnam@sba.gov.* 

## SUPPLEMENTARY INFORMATION:

## I. Background

The U.S. Small Business Administration ("SBA" or "Agency") is proposing to revise the regulations for the Small Business Investment Company ("SBIC") program to significantly reduce barriers to program participation for new SBIC fund managers and funds investing in underserved communities and geographies, capital intensive investments, and technologies critical to national security and economic development. This proposed rule, Small Business Investment Company

Investment Diversification and Growth, 87 FR 63436, introduces an additional type of SBIC ("Accrual SBICs") to increase program investment diversification and patient capital financing for small businesses and modernize rules to lower financial barriers to program participation. This proposed rule will help SBA implement the Executive order (''Ē.O.''), Advancing Racial Equity and Support for Underserved Communities Through the Federal Government, by reducing financial and administrative barriers to participate in the SBIC program and modernizing the program's license offerings to align with a more diversified set of private funds investing in underserved small businesses. The proposed rule also incorporates the statutory requirements of the Spurring Business in Communities Act of 2017, which was enacted on December 19, 2018. More information about the proposed regulation can be found here.

## **II. Questions**

For the public webinar, OII strongly encourages that questions be submitted in advance by November 25, 2022. Individuals may email *investinnovate@ sba.gov* with subject line—"[Name/ Organization] Question for 11/28/22 Public Webinar." During the live event, attendees will be in listen-only mode and may submit additional questions via the Q&A Chat feature.

#### III. Comments on the Proposed Regulations

Comments on the proposed rule may be submitted on or before December 19th, 2022, at www.regulations.gov. SBA will analyze any written comments received and respond to all comments in the final rule. However, during the public webinar, SBA officials will not provide responses to public comment or suggestions on the proposed rule. SBA requests that commenters focus on SBA's October 19, 2022, proposed rulemaking and the impacted regulations therein. SBA requests that commenters do not raise issues pertaining to issues not covered under the proposed rule, or issues outside the scope of the rule.

# IV. Information on Service for Individuals With Disabilities

For information on services for individuals with disabilities or to request special assistance contact Federal Register Vol. 87, No. 218 Monday, November 14, 2022

Nathaniel Putnam at the telephone number or email address indicated under the **FOR FURTHER INFORMATION CONTACT** section of this notice.

## Michele Schimpp,

Deputy Associate Administrator, Office of Investment & Innovation, U.S. Small Business Administration.

[FR Doc. 2022–24714 Filed 11–10–22; 8:45 am] BILLING CODE 8026–09–P

## DEPARTMENT OF TRANSPORTATION

### **Federal Aviation Administration**

## 14 CFR Part 39

[Docket No. FAA-2022-1296; Project Identifier MCAI-2022-00628-T]

## RIN 2120-AA64

# Airworthiness Directives; Airbus SAS Airplanes

Editorial Note: Proposed rule document 2022–22047 was originally published on pages 63712 through 63715 in the issue of Thursday, October 20, 2022. In that publication on page 63715, in the second column, under the "(o) Material Incorporated by Reference" heading, paragraph "(3)", "November 25, 2022" should read "[DATE 35 DAYS AFTER PUBLICATION OF THE FINAL RULE]". The corrected document is published here in its entirety.

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2020-20-05 and AD 2022-09-16, which apply to certain Airbus SAS Model A318 series; A319-111, -112, -113, -114, -115, -131, -132, -133, -151N, and -153N; A320 series; and A321 series airplanes. AD 2020-20-05 and AD 2022–09–16 require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. Since the FAA issued AD 2020-20-05 and AD 2022-09-16, the FAA has determined that new or more restrictive airworthiness limitations are necessary. This proposed AD would continue to require the actions in AD 2022–09–16 and require revising the existing maintenance or inspection program, as applicable, to incorporate additional new or more restrictive

68110

airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference. This proposed AD would also revise the applicability to include additional airplanes. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by December 5, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

• Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.

• Fax: 202–493–2251.

• *Mail:* U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at *regulations.gov* under Docket No. FAA–2022–1296; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

• For EASA material that will be incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu;* internet *www.easa.europa.eu.* You may find this material on the EASA website at *ad.easa.europa.eu.* 

• You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket at *regulations.gov* under Docket No. FAA–2022–1296.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231–3225; email *dan.rodina*@ *faa.gov.* 

## SUPPLEMENTARY INFORMATION:

#### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-1296; Project Identifier MCAI-2022-00628-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

#### **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206-231-3225; email dan.rodina@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

## Background

The FAA issued AD 2020–20–05, Amendment 39–21261 (85 FR 65197, October 15, 2020) (AD 2020–20–05), and AD 2022–09–16, Amendment 39–22036

(87 FR 31943, May 26, 2022) (AD 2022-09-16), which apply to all Model A318-111, -112, -121, and -122 airplanes; Model A319-111, -112, -113, -114 -115, -131, -132, -133, -151N, and -153N airplanes; Model A320-211, -212, -214, -216, -231, -232, -233,-251N, -252N, -253N, -271N, -272N, and -273N airplanes; and Model -A321-111,-112, -131, -211, -212, -213, -231, -232, -251N, -251NX, -252N, -252NX, -253N, -253NX, -271N, -271NX, -272N, and -272NX airplanes. AD 2020-20-05 and AD 2022–09–16 require revising the existing maintenance or inspection program, as applicable, to incorporate additional new or more restrictive airworthiness limitations. The FAA issued AD 2020-20-05 and AD 2022-09-16 to address fatigue cracking, accidental damage, or corrosion in principal structural elements, which could result in reduced structural integrity of the airplane.

# Actions Since AD 2020–20–05 and AD 2022–09–16 Were Issued

Since the FAA issued AD 2020–20–05 and AD 2022–09–16, the FAA has determined that new or more restrictive airworthiness limitations are necessary.

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2022–0085, dated May 12, 2022 (EASA AD 2022-0085) (also referred to as the MCAI), to correct an unsafe condition for all Airbus SAS Model A318-111, A318-112, A318-121, A318-122, A319-111, A319–112, A319–113, A319–114, A319– 115, A319-131, A319-132, A319-133, A319-151N, A319-153N, A319-171N, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-252N, A320-253N, A320-271N, A320-272N, A320-273N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231, A321-232, A321-251N, A321-251NX, A321-252N, A321-252NX, A321-253N, A321-253NX, A321-271N, A321-271NX, A321-272N, and A321–272NX airplanes. EASA AD 2022-0085 superseded EASA AD 2020-0036R1, dated June 24, 2020 (EASA AD 2021–0140) (which corresponds to FAA AD 2020–20–05) and EASA AD 2021– 0140, dated June 14, 2021 (which corresponds to FAA AD 2022-09-16). Model A320–215 airplanes are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those airplanes in the applicability.

Airplanes with an original airworthiness certificate or original export certificate of airworthiness issued after February 2, 2022, must comply with the airworthiness limitations specified as part of the approved type design and referenced on the type certificate data sheet; this AD therefore does not include those airplanes in the applicability.

This proposed AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is proposing this AD to address fatigue cracking, accidental damage, or corrosion in principal structural elements, which could result in reduced structural integrity of the airplane. See the MCAI for additional background information.

## **Related Service Information Under** 1 CFR Part 51

EASA AD 2022–0085 specifies new or more restrictive airworthiness limitations for airplane structures and safe life limits.

This proposed AD would also require EASA AD 2021–0140, which the Director of the Federal Register approved for incorporation by reference as of June 30, 2022 (87 FR 31943, May 26, 2022).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### **FAA's Determination**

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI described above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

# Proposed AD Requirements in This NPRM

This proposed AD would retain the requirements of AD 2022–09–16. This proposed AD would also expand the applicability and require revising the existing maintenance or inspection program, as applicable, to incorporate additional new or more restrictive airworthiness limitations, which are specified in EASA AD 2022–0085 described previously, as proposed for incorporation by reference. Any differences with EASA AD 2022–0085 are identified as exceptions in the regulatory text of this AD.

This proposed AD would require revisions to certain operator maintenance documents to include new actions (*e.g.*, inspections). Compliance with these actions is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance (AMOC) according to paragraph (m)(1) of this proposed AD.

# Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to retain the IBR of EASA AD 2021-0140 and incorporate EASA AD 2022-0085 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2021-0140 and EASA AD 2022-0085 in their entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2021-0140 or EASA AD 2022–0085 does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in EASA AD 2021–0140 or EASA AD 2022-0085. Service information required by EASA AD 2021-0140 and EASA AD 2022-0085 for compliance will be available at *regulations.gov* by searching for and locating Docket No. FAA-2022-1296 after the FAA final rule is published.

## Airworthiness Limitation ADs Using the New Process

The FAA's process of incorporating by reference MCAI ADs as the primary source of information for compliance with corresponding FAA ADs has been limited to certain MCAI ADs (primarily those with service bulletins as the primary source of information for accomplishing the actions required by the FAA AD). However, the FAA is now expanding the process to include MCAI ADs that require a change to airworthiness limitation documents, such as airworthiness limitation sections.

For these ADs that incorporate by reference an MCAI AD that changes airworthiness limitations, the FAA requirements are unchanged. Operators must revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in the new airworthiness limitation document. The airworthiness limitations must be followed according to 14 CFR 91.403(c) and 91.409(e).

The previous format of the airworthiness limitation ADs included a paragraph that specified that no alternative actions (*e.g.*, inspections) or intervals may be used unless the actions and intervals are approved as an AMOC in accordance with the procedures specified in the AMOCs paragraph under "Additional FAA Provisions." This new format includes a "New Provisions for Alternative Actions and Intervals" paragraph that does not specifically refer to AMOCs, but operators may still request an AMOC to use an alternative action or interval.

#### **Costs of Compliance**

The FAA estimates that this proposed AD affects 1,864 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

The FAA estimates the total cost per operator for the retained actions from AD 2022–09–16 to be \$7,650 (90 workhours  $\times$  \$85 per work-hour).

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 workhours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate.

The FAA estimates the total cost per operator for the new proposed actions to be \$7,650 (90 work-hours  $\times$  \$85 per work-hour).

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under 68112

that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### **Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Would not affect intrastate aviation in Alaska, and

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### §39.13 [Amended]

■ 2. The FAA amends § 39.13 by:

■ a. Removing AD 2020–20–05, Amendment 39–21261 (85 FR 65197, October 15, 2020); and AD 2022–09–16, Amendment 39–22036 (87 FR 31943, May 26, 2022); and

■ b. Adding the following new AD:

Airbus SAS: Docket No. FAA–2022–1296; Project Identifier MCAI–2022–00628–T.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by December 5, 2022.

## (b) Affected ADs

This AD replaces AD 2020–20–05, Amendment 39–21261 (85 FR 65197, October 15, 2020) (AD 2020–20–05); and AD 2022– 09–16, Amendment 39–22036 (87 FR 31943, May 26, 2022) (AD 2022–09–16).

#### (c) Applicability

This AD applies to Airbus SAS airplanes specified in paragraphs (c)(1) through (4) of this AD, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before February 2, 2022.

(1) Model A318–111, –112, –121, and –122 airplanes.

(2) Model A319–111, –112, –113, –114, –115, –131, –132, –133, –151N, –153N, and

```
–171N airplanes.
```

(3) Model A320–211, –212, –214, –216, –231, –232, –233, –251N, –252N, –253N, –271N, –272N, and –273N airplanes.

(4) Model A321–111, –112, –131, –211,

-212, -213, -231, -232, -251N, -251NX,

–252N, –252NX, –253N, –253NX, –271N,

–271NX, –272N, and –272NX airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

#### (e) Unsafe Condition

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address fatigue cracking, accidental damage, or corrosion in principal structural elements, which could result in reduced structural integrity of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Retained Revision of the Existing Maintenance or Inspection Program, With No Changes

This paragraph restates the requirements of paragraph (g) of AD 2022-09-16, with no changes. For airplanes with an original airworthiness certificate or original export certificate of airworthiness issued on or before November 10, 2020: Except as specified in paragraph (h) of this AD, comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021-0140, dated June 14, 2021 (EASA AD 2021-0140). Accomplishing the revision of the existing maintenance or inspection program required by paragraph (j) of this AD terminates the requirements of this paragraph.

## (h) Retained Exceptions to EASA AD 2021–0140

This paragraph restates the requirements of paragraph (h) of AD 2022–09–16, with no changes.

(1) Where EASA AD 2021–0140 refers to its effective date, this AD requires using June 30, 2022 (the effective date of AD 2022–09–16).

(2) The requirements specified in paragraphs (1) and (2) of EASA AD 2021–0140 do not apply to this AD.

(3) Paragraph (3) of EASA AD 2021–0140 specifies revising "the approved [aircraft maintenance program] AMP" within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.

(4) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2021–0140 is at the applicable "thresholds" as incorporated by the requirements of paragraph (3) of EASA AD 2021–0140, or within 90 days after the effective date of this AD, whichever occurs later.

(5) The provisions specified in paragraph (4) of EASA AD 2021–0140 do not apply to this AD.

(6) The "Remarks" section of EASA AD 2021–0140 does not apply to this AD.

## (i) Retained Provisions for Alternative Actions or Intervals, With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2022–09–16, with no changes. After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (*e.g.*, inspections) or intervals are allowed unless they are approved as specified in the provisions of the "Ref. Publications" section of EASA AD 2021–0140.

## (j) New Revision of the Existing Maintenance or Inspection Program

Except as specified in paragraph (k) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2022–0085, dated May 12, 2022 (EASA AD 2022–0085). Accomplishing the revision of the existing maintenance or inspection program required by this paragraph terminates the requirements of paragraph (g) of this AD.

#### (k) Exceptions to EASA AD 2022-0085

(1) Where EASA AD 2022–0085 refers to its effective date, this AD requires using the effective date of this AD.

(2) The requirements specified in paragraphs (1) and (2) of EASA AD 2022– 0085 do not apply to this AD.

(3) Paragraph (3) of EASA AD 2022–0085 specifies revising "the approved AMP" within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.

(4) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2022–0085 is at the applicable "thresholds" as incorporated by the requirements of paragraph (3) of EASA AD 2022–0085, or within 90 days after the effective date of this AD, whichever occurs later.

(5) The provisions specified in paragraphs (4) and (5) of EASA AD 2022–0085 do not apply to this AD.

(6) The "Remarks" section of EASA AD 2022–0085 does not apply to this AD.

## (l) New Provisions for Alternative Actions and Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (j) of this AD, no alternative actions (*e.g.*, inspections) and intervals are allowed unless they are approved as specified in the provisions of the "Ref. Publications" section of EASA AD 2022–0085.

#### (m) Additional FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (n) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(ii) AMOCs approved previously for AD 2022–09–16 are approved as AMOCs for the corresponding provisions of EASA AD 2021–0140 that are required by paragraph (g) of this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (n) Related Information

For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, FAA, International Validation Branch, 2200 South 216th St., Des Moines, WA 98198; telephone 206–231– 3225; email dan.rodina@faa.gov.

#### (o) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on [DATE 35 DAYS AFTER PUBLICATION OF THE *FINAL RULE*].

(i) European Union Aviation Safety Agency (EASA) AD 2022–0085, dated May 12, 2022.

(ii) [Reserved](4) The following service information was

approved for IBR on June 30, 2022 (87 FR 31943, May 26, 2022).

(i) European Union Aviation Safety Agency (EASA) AD 2021–0140, dated June 14, 2021. (ii) [Reserved]

(5) For the EASA ADs identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email *ADs@easa.europa.eu;* website *easa.europa.eu*. You may find these EASA ADs on the EASA website at *ad.easa.europa.eu*.

(6) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email *fr.inspection@nara.gov*, or go to: *www.archives.gov/federal-register/cfr/ibrlocations.html.* 

Issued on October 3, 2022.

#### Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. R1-2022-22047 Filed 11-10-22; 8:45 am] BILLING CODE 0099-10-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2022-1240; Project Identifier AD-2022-00683-E]

#### RIN 2120-AA64

## Airworthiness Directives; General Electric Company Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain General Electric Company (GE) GE90-76B, GE90-85B, GE90-90B, and GE90–94B model turbofan engines. This proposed AD was prompted by a commanded in-flight shutdown (IFSD) due to cracking and rockback of the high-pressure turbine (HPT) stage 2 nozzles resulting in blade liberation, severe rotor imbalance, and liberation of the exhaust centerbody. This proposed AD would require initial and repetitive borescope inspections (BSIs) of the forward platforms of the HPT stage 2 blades or the leading edges of the HPT stage 2 nozzles and, depending on the results of the inspections, removal and replacement of the HPT stage 2 nozzles with a part eligible for installation. As a mandatory terminating action to the repetitive BSIs of the forward platforms of the HPT stage 2 blades or the leading

edges of the HPT stage 2 nozzles, this proposed AD would require replacement of the HPT stage 2 nozzles. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by December 29, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

• Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.

• Fax: (202) 493–2251.

• *Mail*: U.S. Department of Transportation, Docket Operations, M– 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at *regulations.gov* by searching for and locating Docket No. FAA–2022–1240; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference: For service information identified in this NPRM, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215; phone: (513) 552–3272; email: *aviation.fleetsupport@ge.com.* You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222– 5110.

## FOR FURTHER INFORMATION CONTACT:

Stephen Elwin, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7236; email: *Stephen.L.Elwin@faa.gov.* **SUPPLEMENTARY INFORMATION:** 

#### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA–2022–1240; Project Identifier AD– 2022–00683–E" at the beginning of your comments. The most helpful comments reference a specific portion of the