

**Applicability**

(c) This AD applies to Boeing Model 767–200 and –300 series airplanes; certificated in any category; with a metered fire extinguisher system in the aft cargo compartment.

**Unsafe Condition**

(d) This AD was prompted by one report indicating that an operator found a hole in the discharge tube assembly for the metered fire extinguishing system; and another report indicating that an operator found chafing of the fire extinguishing tube against the auxiliary power unit (APU) duct that resulted in a crack in the tube. We are issuing this AD to prevent fire extinguishing agent from leaking out of the tube assembly in the aft cargo compartment which, in the event of a fire in the aft cargo compartment, could result in an insufficient concentration of fire extinguishing agent, and consequent inability of the fire extinguishing system to suppress the fire.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Inspections and Corrective Actions**

(f) Within 24 months or 8,000 flight hours after the effective date of this AD, whichever is first: Accomplish the actions required by paragraphs (f)(1) and (f)(2) of this AD, as applicable.

(1) For airplanes identified in Boeing Service Bulletin 767–26A0130, Revision 2, dated October 31, 2006: Perform detailed and general visual inspections for discrepancies of the fire extinguishing tube assemblies between station (STA) 1140 and STA 1340, and the insulation of the metered fire extinguisher system and the bleed air duct couplings of the APU located in the aft cargo compartment, and any applicable corrective actions, by doing all the applicable actions specified in the Accomplishment Instructions of Boeing Service Bulletin 767–26A0130, Revision 2, dated October 31, 2006. Do all applicable corrective actions before further flight in accordance with the service bulletin. Repeat the inspections thereafter at intervals not to exceed 24 months or 8,000 flight hours, whichever is first. Installation of the tube assembly in the correct location, in accordance with the service bulletin, terminates the repetitive inspections for that assembly only.

(2) For airplanes identified in Boeing Alert Service Bulletin 767–26A0123, dated August 22, 2002: Accomplish the actions required by paragraphs (f)(2)(i) and (f)(2)(ii) of this AD, as applicable.

(i) Perform a general visual inspection for sufficient clearance between the fire extinguishing tube and the APU duct on the left sidewall from STA 1355 through 1365 inclusive, and do all applicable modifications, by doing all the actions specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 767–26A0123, dated August 22, 2002. Do all applicable modifications before further flight.

(ii) If there is insufficient clearance between the fire extinguishing tube and the

APU duct: Before further flight, accomplish the modification of the fire extinguishing tube assembly by doing all the actions specified in the Accomplishment Instructions of Boeing Service Bulletin 767–26–0118, Revision 2, dated December 21, 2004. Accomplishing the modification in this paragraph terminates the repetitive inspections for that assembly only.

**Credit for Actions Accomplished Previously**

(g) Accomplishing the inspections and corrective actions required by paragraph (f)(1) of this AD before the effective date of this AD, in accordance with Boeing Alert Service Bulletin 767–26A0130, dated December 2, 2004, or Revision 1, dated December 15, 2005; is considered acceptable for compliance with the corresponding actions in paragraph (f)(1) of this AD.

(h) Accomplishing the actions required by paragraph (f)(2)(ii) of this AD before the effective date of this AD, in accordance with Boeing Service Bulletin 767–26–0118, dated June 20, 2002, or Revision 1, dated October 3, 2002; is considered acceptable for compliance with the corresponding actions in paragraph (f)(2)(ii) of this AD for accomplishing the modification of the fire extinguishing tube assembly.

**Alternative Methods of Compliance (AMOCs)**

(i)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

**Material Incorporated by Reference**

(j) You must use Boeing Service Bulletin 767–26A0130, Revision 2, dated October 31, 2006; Boeing Alert Service Bulletin 767–26A0123, dated August 22, 2002; and Boeing Service Bulletin 767–26–0118, Revision 2, dated December 21, 2004; as applicable; to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 30, 2007.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7–8767 Filed 5–8–07; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA 2007–27512, Airspace  
Docket No. 07–AEA–01]

**Establishment of Class E Airspace;  
Front Royal-Warren County, VA**

**AGENCY:** Federal Aviation  
Administration (FAA), DOT.

**ACTION:** Direct final rule; request for  
comments.

**SUMMARY:** This action establishes a Class E airspace area at Front Royal-Warren County Airport, Front Royal, VA (KFFR) to provide for adequate controlled airspace for those aircraft using the new Area Navigation (RNAV) Instrument Approach Procedure to the Airport.

**DATES:** Effective 0901 UTC, July 5, 2007. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

Comments for inclusion in the Rules Docket must be received on or before June 8, 2007.

**ADDRESSES:** Send comments on the rule to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590–0001. You must identify the docket number, FAA–2007–27512; airspace docket number, 07–AEA–01, at the beginning of your comments. You may also submit comments on the Internet at <http://dms.dot.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person at the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1–800–647–5527) is located on the plaza level of the Department of Transportation NASSIF Building at the street address stated above.

An informal docket may be examined during normal business hours in the FAA Eastern Service Center, by contacting the Manager, Systems Support, AJO–2E2, Federal Aviation Administration, Eastern Service Center, 1701 Columbia Ave, College Park, GA, 30337.

**FOR FURTHER INFORMATION CONTACT:**

Mark D. Ward, Manager, Systems Support, AJO–2E2, FAA Eastern Service Center, 1701 Columbia Ave., College Park, GA, 30337; telephone (404) 305–5570; fax (404) 305–5099.

**SUPPLEMENTARY INFORMATION:** A new Standard Instrument Approach Procedure (SIAP) to Front Royal-Warren County Airport, Front Royal, VA (KFFR), RNAV (GPS)—A, requires the establishment of Class E airspace extending upward from 700 feet above the surface in the vicinity of the airport. This action provides adequate controlled airspace to contain those aircraft executing the RNAV (GPS)—A approach. Class E airspace designations for airspace areas extending upward from 700 feet above the surface of the earth are published in paragraph 6005 of FAA Order 7400.9P, effective September 16, 2006, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in this Order.

#### The Direct Final Rule Procedure

The FAA anticipates that this regulation will not result in adverse or negative comment, and, therefore, issues it as a direct final rule. The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Unless a written adverse or negative comment or a written notice of intent to submit an adverse or negative comment is received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative comments were received and confirming the date on which the final rule will become effective. If the FAA does receive, within the comment period, an adverse or negative comment, or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

#### Comments Invited

Although this action is in the form of a direct final rule, and was not preceded by a notice of proposed rulemaking, interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended or withdrawn in light of the comments received.

Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of this action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this action will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA 2007-27512; Airspace Docket No. 07-AEA-01." The postcard will be date stamped and returned to the commenter.

#### Agency Findings

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is non-controversial and unlikely to result in adverse or negative comments. For the reasons discussed in the preamble, I certify that this regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as these routine matters will only affect air traffic procedures and air navigation. It is certified that these proposed rules will not have significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

#### Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration amends part 71 of the Federal Aviation Regulations (14 CFR part 71) as follows:

#### PART 71—[Amended]

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

■ 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9P, Airspace Designations and Reporting Points, dated September 1, 2006 and effective September 15, 2006, is amended as follows:

*Paragraph 6005 Class E Airspace Areas Extending Upward from 700 Feet or More Above the Surface of the Earth.*

\* \* \* \* \*

#### AEA VA E5 FRONT ROYAL, VA [New]

Front Royal-Warren County Airport, VA  
(Lat. 38°55'03.11" N., long. 78°15'12.65" W.)

That airspace extending upward from 700 feet above the surface within a 11.3-mile radius of Front Royal-Warren County Airport, VA.

\* \* \* \* \*

Issued in College Park, GA, on April 18, 2007.

**Lynda Otting,**

*Acting Group Manager, System Support, A/J02-E2, Eastern Service Center.*

[FR Doc. 07-2210 Filed 5-8-07; 8:45am]

**BILLING CODE 4910-13-M**

## DEPARTMENT OF HEALTH AND HUMAN SERVICES

### Food and Drug Administration

#### 21 CFR Part 510

#### New Animal Drugs; Change of Sponsor's Name and Address

**AGENCY:** Food and Drug Administration, HHS.

**ACTION:** Final rule.

**SUMMARY:** The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect a change of sponsor's name from American Pharmaceutical Partners, Inc., to Abraxis Pharmaceuticals Products and to change the sponsor's mailing address.

**DATES:** This rule is effective May 9, 2007.