

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**The Boeing Company:** Docket No. FAA–2010–0376; Directorate Identifier 2009–NM–267–AD.

#### Comments Due Date

(a) We must receive comments by May 24, 2010.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to The Boeing Company Model 777–200, –200LR, –300, and –300ER series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 777–57–0063, Revision 1, dated May 14, 2009.

#### Subject

(d) Air Transport Association (ATA) of America Code 57: Wings.

#### Unsafe Condition

(e) This AD results from reports of fuel leakage from the center tank. We are issuing this AD to detect and correct improperly applied sealant, which could result in the disbonding and displacing of sealant, and consequent fuel leaks. On the ground, uncontained fuel leakage could result in pooling, and pooling combined with an ignition source, could result in a fire.

#### Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### Removal and Repair of Sealant

(g) Within 36 months or 6,000 flight cycles after the effective date of this AD, whichever occurs first: Remove and repair the sealant at the four lower corners of the wing center section and the four lower t-chord segment gaps on each side of the wing center section, in accordance with the Accomplishment Instructions of Boeing Special Attention

Service Bulletin 777–57–0063, Revision 1, dated May 14, 2009.

#### Credit For Actions Accomplished According to Previous Issue of Service Bulletin

(h) Actions accomplished before the effective date of this AD in accordance with Boeing Special Attention Service Bulletin 777–57–0063, dated November 20, 2008, are considered acceptable for compliance with the corresponding action specified in this AD.

#### Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Kevin Nguyen, Aerospace Engineer, Propulsion Branch, ANM–140S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 917–6501; fax (425) 917–6590. Information may be e-mailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Issued in Renton, Washington, on April 1, 2010.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2010–7946 Filed 4–7–10; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA–2010–0095; Airspace Docket No. 10–ASO–18]

#### Amendment of Class D Airspace; Goldsboro, NC

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to amend the Class D airspace at Seymour Johnson AFB, Goldsboro, NC, to reflect the part-time operating status of the control tower, enhancing the safety and management of aircraft operations.

**DATES:** Comments must be received on or before May 24, 2010.

**ADDRESSES:** Send comments on this proposal to: U.S. Department of

Transportation, Docket Operations, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590–0001; Telephone: 1–800–647–5527; Fax: 202–493–2251. You must identify the Docket Number FAA–2010–0095; Airspace Docket No. 10–ASO–18, at the beginning of your comments. You may also submit and review received comments through the Internet at <http://www.regulations.gov>.

#### FOR FURTHER INFORMATION CONTACT:

Melinda Giddens, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305–5610.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2010–0095; Airspace Docket No. 10–ASO–18) and be submitted in triplicate to the Docket Management System (*see ADDRESSES* section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: “Comments to Docket No. FAA–2010–0095; Airspace Docket No. 10–ASO–18.” The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

#### Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through <http://www.regulations.gov>

[www.regulations.gov](http://www.regulations.gov). Recently published rulemaking documents can also be accessed through the FAA's Web page at [http://www.faa.gov/airports/airtraffic/air\\_traffic/publications/airspace\\_amendments/](http://www.faa.gov/airports/airtraffic/air_traffic/publications/airspace_amendments/).

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays. An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, Room 210, 1701 Columbia Avenue, College Park, Georgia 30337.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

### The Proposal

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to amend Class D airspace at Seymour Johnson AFB, Goldsboro, NC, to reflect the part-time operations of the airport control tower, establishing in advance the dates and times by a Notice to Airmen.

Class D airspace designations are published in Paragraph 5000 of FAA Order 7400.9T, signed August 27, 2009, and effective September 15, 2009, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designation listed in this document will be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in subtitle VII, part A, subpart I, section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This proposed regulation is within the scope of that authority as it would amend Class D airspace at Seymour Johnson AFB, Goldsboro, NC.

### Lists of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

### PART 71—DESIGNATION OF CLASS A, B, C, D AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

#### § 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9T, Airspace Designations and Reporting Points, signed August 27, 2009, effective September 15, 2009, is amended as follows:

*Paragraph 5000 Class D Airspace.*

\* \* \* \* \*

#### ASO NC D Goldsboro, NC [Amended]

Seymour Johnson AFB, NC  
(Lat. 35°20'22" N., long. 77°57'38" W.)

That airspace extending upward from the surface to and including 2,600 feet MSL within a 5.7-mile radius of Seymour Johnson AFB. This Class D airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective dates and times will thereafter be continuously published in the Airport/Facility Directory.

Issued in College Park, Georgia, on March 31, 2010.

**Barry A. Knight,**

*Acting Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.*

[FR Doc. 2010-8016 Filed 4-7-10; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2010-0299 Airspace Docket No. 10-AAL-9]

#### Proposed Revision of Class E Airspace; Galena, AK

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to revise Class E airspace at Galena, AK. The amendment of three Standard Instrument Approach Procedures (SIAPs), and the development of one Obstacle Departure Procedure (ODP) at the Edward G. Pitka Sr. Airport have made this action necessary to enhance safety and management of Instrument Flight Rules (IFR) operations.

**DATES:** Comments must be received on or before May 24, 2010.

**ADDRESSES:** Send comments on the proposal to the Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2010-0299/ Airspace Docket No. 10-AAL-9 at the beginning of your comments. You may also submit comments on the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

An informal docket may also be examined during normal business hours at the office of the Manager, Safety, Alaska Flight Service Operations, Federal Aviation Administration, 222 West 7th Avenue, Box 14, Anchorage, AK 99513-7587.

**FOR FURTHER INFORMATION CONTACT:** Gary Rolf, Federal Aviation Administration,