

ACTION: Notice; Issuance of Advisory Bulletin.

SUMMARY: PHMSA is issuing an advisory bulletin to alert all pipeline owners and operators of the circumstances of the Cherry Valley, Illinois derailment and remind them of the importance of assuring that pipeline facilities have not been damaged either during a railroad accident or other event occurring in the right-of-way. Further, the advisory bulletin reminds pipeline owners and operators of the importance of providing pertinent information to rail operators and emergency response officials during an incident. This information should include the presence, depth and location of the pipelines so that the movement of heavy equipment and debris on the right-of-way does not damage or rupture the pipeline or otherwise pose a hazard to people working in, and around, the accident location. The advisory also encourages pipeline owners and operators to inform rail operators and emergency response officials of the benefits of using the 811 "Call Before You Dig" program to identify and notify underground utilities that an incident has occurred in the vicinity of their buried facilities.

FOR FURTHER INFORMATION CONTACT: David Appelbaum by phone at 202-366-1419 or by email at david.appelbaum@dot.gov. Information about PHMSA may be found at <http://phmsa.dot.gov>.

SUPPLEMENTARY INFORMATION:

Background

On Friday, June 19, 2009, at approximately 8:36 p.m., CST, a Canadian National Railway Company (CN) freight train U70691-18, traveling eastbound at 36 mph, derailed at a highway/rail grade crossing in Cherry Valley, Illinois. The train consisted of two locomotives and 114 cars, 19 of which derailed. All of the derailed cars were tank cars carrying denatured fuel ethanol, a flammable liquid. Thirteen of the derailed tank cars were breached or lost product and caught fire. At the time of the derailment, several motor vehicles were stopped on either side of the grade crossing waiting for the train to pass. As a result of the fire that erupted after the derailment, a passenger in one of the stopped cars was fatally injured, two passengers in the same car received serious injuries, and five occupants of other cars waiting at the highway-rail crossing were injured. Two responding firefighters also sustained minor injuries. The release of ethanol and the resulting fire prompted a mandatory evacuation of about 600

residences within a ½-mile radius of the accident site.

The National Transportation Safety Board (NTSB) determined that the probable cause of the accident was the washout of the track structure that was discovered about one hour before the train's arrival, and CN's failure to notify the train crew of the known washout in time to stop the train because of the inadequacy of CN's emergency communication procedures.

At the site of the derailment was a 12-inch diameter underground natural gas transmission pipeline operated by Nicor Gas. The pipeline well exceeded Federal standards for protective ground cover. Yet, as the wreckage was removed from above the pipeline, Nicor's crews discovered that a railcar wheel and axle assembly had impinged on the pipeline. Although the pipeline was buried about 11 feet deep and protected within a 16-inch diameter casing, the rail car wheels impacted and severely dented the pipeline. The impact caused a severe flattening of the pipe casing with sharp angular bends at two locations where it was contacted by the rail car wheel assembly. This degree of deformation to the 16-inch casing pipe likely caused similar damage to the 12-inch carrier pipe. The NTSB concluded that had the gas pipeline been installed at the railroad crossing with the minimum level of ground cover permitted by the current Federal and industry pipeline construction standards, it likely would have failed as a result of being struck by derailed equipment in this accident.

Advisory Bulletin (ADB-2012-08)

To: Owners and Operators of Hazardous Liquid and Gas Pipeline Systems.

Subject: Inspection and Protection of Pipeline Facilities after Railway Accidents.

Advisory: To further enhance the Department's safety efforts, PHMSA is issuing this advisory bulletin as a reminder for pipeline owners and operators to appropriately inspect and protect pipeline facilities following railroad accidents that occur in pipeline right-of-ways.

As illustrated in the June 19, 2009, Cherry Valley, Illinois train derailment, buried pipelines are susceptible to damage even when depth-of-cover protection exceeds minimum Federal requirements. Pipeline owners and operators should inspect their facilities following a railroad accident or other significant event occurring in right-of-ways to ensure pipeline integrity. Also, during response operations, pipeline owners and operators need to inform rail operators and emergency response

officials of the presence, depth and location of the pipelines so that the movement of heavy equipment on the right-of-way does not damage or rupture the pipeline or otherwise pose a hazard to people working in, and around, the accident location.

Additionally, PHMSA encourages pipeline owners and operators, as a part of their public awareness program, to inform rail operators and emergency response officials of the benefits of using the 811 "Call Before You Dig" program to identify and notify underground utilities that an incident has occurred in the vicinity of their buried facilities.

Linda Daugherty,

Deputy Associate Administrator for Policy and Programs.

[FR Doc. 2012-18571 Filed 7-30-12; 8:45 am]

BILLING CODE 4910-60-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

Proposed Collection; Comment Request for Form 14145

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice and request for comments.

SUMMARY: The Department of the Treasury, as part of its continuing effort to reduce paperwork and respondent burden, invites the general public and other Federal agencies to take this opportunity to comment on proposed and/or continuing information collections, as required by the Paperwork Reduction Act of 1995, Public Law 104-13 (44 U.S.C. 3506(c)(2)(A)). Currently, the IRS is soliciting comments concerning Form 14145, IRS Applicant Contact Card.

DATES: Written comments should be received on or before October 1, 2012 to be assured of consideration.

ADDRESSES: Direct all written comments to Yvette Lawrence, Internal Revenue Service, room 6129, 1111 Constitution Avenue NW., Washington, DC 20224.

FOR FURTHER INFORMATION CONTACT: Requests for additional information or copies of the form and instructions should be directed to R. Joseph Durbala, (202) 622-3634, at Internal Revenue Service, room 6129, 1111 Constitution Avenue NW., Washington, DC 20224, or through the Internet at RJoseph.Durbala@irs.gov.

SUPPLEMENTARY INFORMATION: Title: IRS Applicant Contact Card.

OMB Number: 1545-XXXX.

Form Number: Form 14145.

Abstract: The Internal Revenue Service contact card is used to collect contact information from individuals who may be interested in working for the IRS now, or at any time in the future (potential applicants). Form 14145 requests information to enter into a database to allow the IRS to send information about jobs to potential applicants. Cards are then destroyed after input into the database. The potential applicant is only contacted about jobs which correspond to the job categories selected by the IRS Recruiter on Form 14145.

Current Actions: This is a new request for approval.

Type of Review: Exiting IC in use that does not contain an OMB control number.

Affected Public: Individuals and households.

Estimated Number of Respondents: 16,045.

Estimated Time per Respondent: 4 hours 6 minutes.

Estimated Total Annual Burden Hours: 66,085.

The following paragraph applies to all of the collections of information covered by this notice:

An agency may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the collection of information displays a valid OMB control number. Books or records relating to a collection of information must be retained as long as their contents may become material in the administration of any internal revenue law. Generally, tax returns and tax return information are confidential, as required by 26 U.S.C. 6103.

Request for Comments: Comments submitted in response to this notice will be summarized and/or included in the request for OMB approval. All comments will become a matter of public record. Comments are invited on:

(a) Whether the collection of information is necessary for the proper performance of the functions of the agency, including whether the information shall have practical utility; (b) the accuracy of the agency's estimate of the burden of the collection of information; (c) ways to enhance the quality, utility, and clarity of the information to be collected; (d) ways to minimize the burden of the collection of information on respondents, including through the use of automated collection techniques or other forms of information technology; and (e) estimates of capital or start-up costs and costs of operation, maintenance, and purchase of services to provide information.

Approved: July 23, 2012.

Yvette Lawrence,

IRS Reports Clearance Officer.

[FR Doc. 2012-18587 Filed 7-30-12; 8:45 am]

BILLING CODE 4830-01-P