

Proposed Rules

Federal Register

Vol. 88, No. 138

Thursday, July 20, 2023

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1499; Project Identifier MCAI-2023-00458-T]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A330-202, A330-203, A330-223, A330-243, and A330-841 airplanes. This proposed AD was prompted by a determination that the cold working process was partially completed on a certain circumferential joint. This proposed AD would require modification of the circumferential joint, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by September 5, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1499; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material that is proposed for IBR in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1499.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

FOR FURTHER INFORMATION CONTACT:

Timothy Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone 206-231-3667; email Timothy.P.Dowling@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1499; Project Identifier MCAI-2023-00458-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each

substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Timothy Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone 206-231-3667; email Timothy.P.Dowling@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2023-0054, dated March 14, 2023 (EASA AD 2023-0054) (also referred to as the MCAI), to correct an unsafe condition for Airbus SAS Model A330-202, A330-203, A330-223, A330-243, and A330-841 airplanes, manufacturer serial numbers (MSNs) 1780, 1782, 1784, 1785, 1787, 1799, 1805, 1808, 1822, 1823, 1830, 1835, 1845, 1847, 1848, 1854, 1857, 1859, 1864, 1872, 1877, 1878, 1882, 1883, 1886, 1888, 1891, 1911, 1916, 1919, 1932, 1936, 1942, 1945, 1960, 1964, 1965, 1968, and 1969. Airbus SAS Model A330-243 airplanes, MSNs 1787, 1799, 1808, 1822, 1830, 1848, 1857, 1883, 1886, 1891, 1911, 1916, 1919, 1942, 1945, 1960, 1965, and 1968, were modified to Airbus SAS Model A330-243 Multi Role Transport Tanker (MRTT) airplanes. The MRTT airplanes are not type certificated by the FAA and not included on the U.S. type certificate data sheet; this proposed AD therefore does not include those airplanes in the

applicability. The MCAI states the cold working process was partially completed on the circumferential joint at frame 58. This condition, if not addressed, could affect the structural integrity of the airplane and result in catastrophic failure.

The FAA is proposing this AD to address the unsafe condition on these products. You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2023–1499.

Related Service Information Under 1 CFR Part 51

EASA AD 2023–0054 specifies procedures for modifying the circumferential joint at frame 58. Modification includes accomplishing rotating probe inspections of the fastener holes for cracks, cold work of the fastener holes, and measuring the maximum hole diameter. EASA AD 2023–0054 also specifies contacting the manufacturer for instructions if any discrepancy (*i.e.*, any crack or if the existing hole diameter is more than or equal to the minimum starting hole diameter) is found during any inspection. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in ADDRESSES.

FAA’s Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2023–0054 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating

this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2023–0054 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2023–0054 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2023–0054 does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in EASA AD 2023–0054. Service information required by EASA AD 2023–0054 for compliance will be available at *regulations.gov* under Docket No. FAA–2023–1499 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect one airplane of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 86 work-hours × \$85 per hour = \$7,310	\$500	Up to \$7,810	Up to \$7,810.

The FAA has received no definitive data on which to base the cost estimate for the on-condition actions specified in this proposed AD.

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA

with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus SAS Airplanes: Docket No. FAA–2023–1499; Project Identifier MCAI–2023–00458–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by September 5, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus SAS Model A330–202, A330–203, A330–223, A330–243, and A330–841 airplanes, certificated in any category, manufacturer serial numbers 1780, 1782, 1784, 1785, 1805, 1823, 1835, 1845, 1847, 1854, 1859, 1864, 1872, 1877, 1878, 1882, 1888, 1932, 1936, 1964, and 1969.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by a determination that the cold working process was partially performed on the circumferential joint at frame 58. The FAA is issuing this AD to address a partially completed cold working process on the circumferential joint at frame 58. The unsafe condition, if not addressed, could affect the structural integrity of the airplane and result in catastrophic failure.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2023–0054, dated March 14, 2023 (EASA AD 2023–0054).

(h) Exceptions to EASA AD 2023–0054

(1) This AD does not adopt the “Remarks” section of EASA AD 2023–0054.

(2) Where paragraph (2) of EASA AD 2023–0054 specifies contacting Airbus before further flight for approved instructions if any discrepancy is detected during accomplishment of any inspection that is part of the modification, this AD requires repairing the discrepancy before further flight using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Where paragraph (3) of EASA AD 2023–0054 refers to its effective date, this AD requires using the effective date of this AD.

(4) Where Note 2 of EASA AD 2023–0054 specifies Airbus Operators Information Telex (OIT) 999.0086/11 can be used to determine whether an airplane is operated short range

(SR) or long range (LR), this AD requires using the following definitions: the term “short range” applies to an airplane with an average flight time lower than 1.5 flight hours per flight cycle, and the term “long range” applies to an airplane with an average flight time equal to or higher than 1.5 flight hours per flight cycle. For determining the SR and LR airplanes, the average flight time is the total accumulated flight hours, counted from takeoff to touchdown, divided by the total accumulated flight cycles at the effective date of this AD.

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraphs (h)(2) and (i)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Additional Information

For more information about this AD, contact Timothy Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone 206–231–3667; email Timothy.P.Dowling@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023–0054, dated March 14, 2023.

(ii) [Reserved]

(3) For EASA AD 2023–0054, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on July 13, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–15273 Filed 7–19–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2023–1498; Project Identifier MCAI–2023–00459–T]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A330–200, A330–200 Freighter, A330–300, A330–800, and A330–900 series airplanes. This proposed AD was prompted by a determination that part of a certain production ground test procedure used to confirm inner fuel tank integrity was not accomplished properly on certain airplanes. This proposed AD would require a fuel tank leak test and, depending on findings, accomplishment of applicable corrective action, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to