

S/B 72–A0212, Revision 04, dated October 27, 2008; already inspected using GE ASB CF34–BJ S/B 72–A0212, Revision 03, dated June 27, 2007, or earlier issue, perform a TEV inspection and an ECI on the Tier 3 fan disks at the next shop visit. Use paragraph 3.A of the Accomplishment Instructions of GE ASB CF34–BJ S/B 72–A0212, Revision 04, dated October 27, 2008, or use paragraph 3.A of the Accomplishment Instructions of GE ASB CF34–BJ S/B 72–A0234, dated October 27, 2008, to perform the TEV inspection and ECI.

(3) Repetitive ECI on the Tier 3 fan disks are not required.

#### Alternative Methods of Compliance

(n) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

#### Mandatory Terminating Action

(o) Remove from service, Tier 1 and Tier 2 fan disks listed by P/N, SN, and Tier in Table 1 of GE ASB CF34–AL S/B 72–A0233, Revision 04, dated October 27, 2008; or CF34–BJ S/B 72–0212, Revision 04, dated October 27, 2008, before they exceed their limited life cycles or September 30, 2018, whichever occurs first.

#### Related Information

(p) Contact Tara Chaidez, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: [tara.chaidez@faa.gov](mailto:tara.chaidez@faa.gov); telephone (781) 238–7773; fax (781) 238–7199, for more information about this AD.

#### Material Incorporated by Reference

(q) You must use the service information specified in the following Table 1 to perform

the inspections required by this AD. The Director of the Federal Register approved the incorporation by reference of the documents listed in the following Table 1 in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact General Electric Company via Lockheed Martin Technology Services, 10525 Chester Road, Suite C, Cincinnati, Ohio 45215; telephone (513) 672–8400; fax (513) 672–8422, for a copy of this service information. You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

TABLE 1—INCORPORATION BY REFERENCE

Service Bulletin No.	Page	Revision	Date
CF34–AL S/B 72–A0233. Total Pages—107	ALL	04	October 27, 2008.
CF34–AL S/B 72–A0252. Total Pages—22	ALL	Original	October 27, 2008.
CF34–AL S/B 72–A0253. Total Pages—77	ALL	Original	October 27, 2008.
CF34–BJ S/B 72–A0212. Total Pages—111	ALL	04	October 27, 2008.
CF34–BJ S/B 72–A0234. Total Pages—82	ALL	Original	October 27, 2008.
CF34–BJ S/B 72–A0235. Total Pages—20	ALL	Original	October 27, 2008.

Issued in Burlington, Massachusetts, on December 11, 2009.

**Francis A. Favara,**

*Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. E9–30471 Filed 1–6–10; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### 14 CFR Part 97

[Docket No. 30704; Amdt. No. 3355]

#### Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This rule establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are

designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective January 7, 2010. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 7, 2010.

**ADDRESSES:** Availability of matter incorporated by reference in the amendment is as follows:

#### For Examination—

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located;

3. The National Flight Procedures Office, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: [http://www.archives.gov/federal\\_register/](http://www.archives.gov/federal_register/)

*code\_of\_federal\_regulations/ibr\_locations.html*.

**Availability—**All SIAPs are available online free of charge. Visit [nfdc.faa.gov](http://nfdc.faa.gov) to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from:

1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue, SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

#### FOR FURTHER INFORMATION CONTACT:

Harry J. Hodges, Flight Procedure Standards Branch (AFS–420) Flight Technologies and Programs Division, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082 Oklahoma City, OK 73125) telephone: (405) 954–4164.

**SUPPLEMENTARY INFORMATION:** This rule amends Title 14, Code of Federal Regulations, Part 97 (14 CFR part 97) by amending the referenced SIAPs. The complete regulatory description of each SIAP is listed on the appropriate FAA Form 8260, as modified by the National Flight Data Center (FDC)/Permanent Notice to Airmen (P–NOTAM), and is incorporated by reference in the amendment under 5 U.S.C. 552(a), 1

CFR part 51, and § 97.20 of Title 14 of the Code of Federal Regulations.

The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained in FAA form documents is unnecessary. This amendment provides the affected CFR sections and specifies the types of SIAP and the corresponding effective dates. This amendment also identifies the airport and its location, the procedure and the amendment number.

#### The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP as amended in the transmittal. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained for each SIAP as modified by FDC/P-NOTAMs.

The SIAPs, as modified by FDC P-NOTAM, and contained in this amendment are based on the criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these changes to SIAPs, the TERPS criteria were applied only to specific conditions existing at

the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a FDC NOTAM as an emergency action of immediate flight safety relating directly to published aeronautical charts. The circumstances which created the need for all these SIAP amendments requires making them effective in less than 30 days.

Because of the close and immediate relationship between these SIAPs and safety in air commerce, I find that notice and public procedure before adopting these SIAPs are impracticable and contrary to the public interest and, where applicable, that good cause exists for making these SIAPs effective in less than 30 days.

#### Conclusion

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore—(1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 97

Air traffic control, Airports, Incorporation by reference, and Navigation (Air).

Issued in Washington, DC, on December 25, 2009.

**John M. Allen,**

*Director, Flight Standards Service.*

#### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, Title 14, Code of Federal regulations, part 97, 14 CFR part 97, is amended by amending Standard Instrument Approach Procedures, effective at 0901 UTC on the dates specified, as follows:

#### PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

1. The authority citation for part 97 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721–44722.

2. Part 97 is amended to read as follows:

By amending: § 97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; § 97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; § 97.27 NDB, NDB/DME; § 97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; § 97.31 RADAR SIAPs; § 97.33 RNAV SIAPs; and § 97.35 COPTER SIAPs, Identified as follows:

*Effective Upon Publication*

AIRAC date	State	City	Airport	FDC No.	FDC date	Subject
14-Jan-10 ...	TX .....	Longview .....	East Texas Rgnl .....	9/5041	12/16/09	VOR/DME or TACAN Rwy 31, Amdt 7.
11-Feb-10 ...	WA .....	Seattle .....	Seattle-Tacoma Intl .....	9/5533	12/18/09	ILS or LOC Rwy 16R, Orig-B; ILS Rwy 16R (Cat II), Orig-B; ILS Rwy 16R (Cat III), Orig-B.

[FR Doc. E9-31311 Filed 1-6-10; 8:45 am]

BILLING CODE 4910-13-P

#### DEPARTMENT OF TRANSPORTATION

#### Federal Aviation Administration

#### 14 CFR Part 97

[Docket No. 30703 Amdt. No 3354]

#### Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

#### ACTION: Final Rule.

**SUMMARY:** This establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under

instrument flight rules at the affected airports.

**DATES:** This rule is effective January 7, 2010. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 7, 2010.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows: