radio management panel (RMP) function installed by Airbus modification 207423.

### (d) Subject

Air Transport Association (ATA) of America Code 23, Communications.

#### (e) Unsafe Condition

This AD was prompted by reports of loss of data synchronization between RMPs and the audio management unit (AMU). The FAA is issuing this AD to address loss of radio communication, uncommanded changes of transponder and traffic alert and collision

avoidance system (TCAS) settings, and activation of standby navigation mode on all RMPs. This condition, if not corrected, could result in total loss of radio communication if RMP 3 is inoperative prior to dispatch, including loss of transponder functionality and standby navigation.

### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

### (g) Airplane Flight Manual (AFM) Revision

Within 7 days after the effective date of this AD, revise the Emergency Procedures section of the existing AFM to include the information in figure 1 to paragraph (g) of this AD. This may be done by inserting a copy of figure 1 to paragraph (g) of this AD into the existing AFM. Using a different document with information identical to that contained in figure 1 to paragraph (g) of this AD is acceptable for compliance with the requirements of this paragraph.

Figure 1 to Paragraph (g)—AFM Procedure

### **Dual Loss of RMP Data Synchronization**

Switch off RMP 1 and RMP 2.

Note: When RMP 1 and RMP 2 are switched off:

- The aural alerts are not available on loudspeakers.
- The communication is only available on RMP 3.

Check communication, transponder, TCAS and radio navigation settings.

### (h) Minimum Equipment List (MEL) Revision

Before further flight after accomplishing the requirements of paragraph (g) of this AD, revise the existing FAA-approved MEL to prohibit airplane dispatch (operation) with an inoperative RMP 3 under the MEL item equivalent to FAA master minimum equipment list (MMEL) 23–81–01.

### (i) Credit for Previous Actions

(1) This paragraph provides credit for the AFM revision required by paragraph (g) of this AD, if the revision was performed before the effective date of this AD using Airbus A330/A340 Operations Engineering Bulletin (OEB) 58, issue 1.0, dated February 7, 2025.

(2) This paragraph provides credit for the AFM revision required by paragraph (g) of this AD, if the revision was performed before the effective date of this AD using Airbus A330 Airplane Flight Manual Temporary Revision TR819, Issue 1, dated March 6, 2025.

### (j) Additional AD Provisions4

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of AIR–520, Continued

Operational Safety Branch, FAA, send it to the attention of the person identified in paragraph (k)(1) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, AIR–520, Continued Operational Safety Branch, FAA; or European Union Aviation Safety Agency (EASA); or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

### (k) Additional Information

(1) For more information about this AD, contact James Clary, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 817–222–5138; email: James.Clary@faa.gov.

(2) Material identified in this AD that is not incorporated by reference is available at Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness. A330-A340@airbus.com; website airbus.com.

## (l) Material Incorporated by Reference None.

Issued on April 25, 2025.

### Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2025–07453 Filed 4–25–25; 4:15 pm]
BILLING CODE 4910–13–P

## DEPARTMENT OF HOMELAND SECURITY

### **Coast Guard**

### 33 CFR Part 165

[Docket No. USCG-2025-0125]

# Safety Zone; Recurring Events in Captain of the Port Duluth Zone—Pointe to La Pointe Swim

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notification of enforcement of regulation.

**SUMMARY:** The Coast Guard will enforce the safety zone for the Pointe to La Pointe Swim event in Bayfield, WI from 7 a.m. through 12 noon on August 2, 2025. This action is necessary to protect participants and spectators during the event. During the enforcement period, entry into, transiting, or anchoring within the safety zone is prohibited

unless authorized by the Captain of the Port, Duluth or a designated on-scene representative.

**DATES:** The regulations in 33 CFR 165.943 will be enforced as listed in table 1, Event (9) to 33 CFR 165.943 from 7 a.m. through 12 noon on August 2, 2025.

### FOR FURTHER INFORMATION CONTACT: If

you have questions about this notification of enforcement, call or email LT Zachary Fedak, Marine Safety Unit Duluth, U.S. Coast Guard; telephone (218) 725–3818, email DuluthWWM@uscg.mil.

**SUPPLEMENTARY INFORMATION:** The Coast Guard will enforce the safety zone for the annual Pointe to La Pointe Swim event in 33 CFR 165.943, table 1, Event (9) from 7 a.m. through 12 noon on August 2, 2025 on all waters between Bayfield, WI and Madeline Island, WI within a polygon formed by straight lines using the following coordinates: Starting Position 46°48′50″ N, 090°48′44" W, moving southeast to 46°46′44″ N, 090°47′33″ W, then moving northeast to 46°46′52″ N, 090°47′17″ W, then moving northwest to 46°49'03" N, 090°48′25″ W, and finally returning to the starting position.

Entry into, transiting, or anchoring within the safety zone is prohibited unless authorized by the Captain of the Port Duluth or a designated on-scene representative.

This notice of enforcement is issued under authority of 33 CFR 165.943 and 5 U.S.C. 552 (a). In addition to this publication in the **Federal Register**, the Coast Guard will provide the maritime community with advance notification of the enforcement of this safety zone via Broadcast Notice to Mariners or Local Notice to Mariners. The Captain of the Port Duluth may be contacted via Channel 16, VFH–FM or at (218) 428–9357.

Dated: April 15, 2025.

### J.P. Botti,

Commander, U.S. Coast Guard, Captain of the Port Duluth.

[FR Doc. 2025–07100 Filed 4–29–25; 8:45 am]

BILLING CODE 9110-04-P

## FEDERAL COMMUNICATIONS COMMISSION

### 47 CFR Part 73

[MB Docket No. 25-84; RM-11995; DA 25-336; FR ID 290347]

### Television Broadcasting Services Silver City and Truth or Consequences, New Mexico

**AGENCY:** Federal Communications

Commission. **ACTION:** Final rule.

**SUMMARY:** This document amends the Table of TV Allotments (table) of the Federal Communications Commission's (Commission) rules by deleting channel 12 at Silver City, New Mexico and reallotting channel 12 from Silver City to Truth or Consequences, New Mexico in response to a Petition for Rulemaking filed by TV-49, Inc., the permittee of an unbuilt full power television station KKAB on channel 12 allotted to Silver City, New Mexico. The staff engineering analysis finds that the proposal is in compliance with the Commission's principal community coverage and technical requirements. TV-49, Inc. also requested modification of its construction permit to specify Truth or Consequences as its community of license.

**DATES:** Effective April 30, 2025.

### FOR FURTHER INFORMATION CONTACT:

Emily Harrison, Media Bureau, at *Emily.Harrison@fcc.gov*, (202) 418–1665, or Mark Colombo, Media Bureau, at *Mark.Colombo@fcc.gov*, (202) 418–7611.

**SUPPLEMENTARY INFORMATION:** This is a synopsis of the Commission's *Report and Order*, MB Docket No. 25–84; RM–11995; DA 25–336, adopted April 11, 2025, and released April 11, 2025. The proposed rule was published at 90 FR 10044 on February 21, 2025. The full text of this document is available online at <a href="https://www.fcc.gov/edocs.">https://www.fcc.gov/edocs.</a>

This document does not contain information collection requirements subject to the Paperwork Reduction Act of 1995, Public Law 104–13. In addition, therefore, it does not contain any proposed information collection burden "for small business concerns with fewer

than 25 employees," pursuant to the Small Business Paperwork Relief Act of 2002, Public Law 107–198, see 44 U.S.C. 3506(c)(4). Provisions of the Regulatory Flexibility Act of 1980, 5 U.S.C. 601–612, do not apply to this proceeding.

The Commission will send a copy of this *Report and Order* in a report to be sent to Congress and the Government Accountability Office pursuant to the Congressional Review Act, *see* 5 U.S.C. 801(a)(1)(A).

### List of Subjects in 47 CFR Part 73

Television.

Federal Communications Commission.

### Thomas Horan,

 ${\it Chief of Staff, Media Bureau.}$ 

### **Final Rule**

For the reasons discussed in the preamble, the Federal Communications Commission amends 47 CFR part 73 as follows:

## PART 73—RADIO BROADCAST SERVICES

■ 1. The authority citation for part 73 continues to read as follows:

**Authority:** 47 U.S.C. 154, 155, 301, 303, 307, 309, 310, 334, 336, 339.

■ 2. In § 73.622, in the table in paragraph (j), under New Mexico, revise the entry for "Silver City" and add an entry in alphabetical order for "Truth or Consequences" to read as follows:

## § 73.622 Digital television table of allotments.

[FR Doc. 2025-07334 Filed 4-29-25; 8:45 am]

BILLING CODE 6712-01-P