

**(a) Comments Due Date**

We must receive comments by December 1, 2014.

**(b) Affected ADs**

This AD replaces AD 2014-06-08, Amendment 39-17812 (79 FR 17390, March 28, 2014).

**(c) Applicability**

This AD applies to Bombardier, Inc. Model DHC-8-101, -102, -103, -106, -201, -202, -301, -311, and -315 airplanes, certificated in any category, serial numbers 003 through 672 inclusive.

**(d) Subject**

Air Transport Association (ATA) of America Code 32, Landing gear.

**(e) Reason**

This AD was prompted by a report that the emergency downlock indication system (EDIS) had given a false landing gear down-and-locked indication and a determination that a terminating action modification is necessary to address the identified unsafe condition. We are issuing this AD to detect and correct a false down-and-locked landing gear indication, which, on landing, could result in possible collapse of the landing gear.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Retained Functional Check With Repair Approval Clarification**

This paragraph restates the requirements of paragraph (g) of AD 2014-06-08, Amendment 39-17812 (79 FR 17390, March 28, 2014), with specific delegation approval language. Within 600 flight hours or 100 days, whichever occurs first after April 14, 2014 (the effective date of AD 2014-06-08): Perform a functional check of the alternate indication phototransistors of the nose and main landing gear; and do all applicable corrective actions; in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-32-173, Revision A, dated December 17, 2012; except where Bombardier Service Bulletin 8-32-173, Revision A, dated December 17, 2012, specifies to contact the manufacturer for further instructions, before further, flight, repair using a method approved by the Manager, New York Aircraft Certification Office, ANE-170, Engine and Propeller Directorate, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). Do all applicable corrective actions before further flight. Repeat the functional check thereafter at intervals not to exceed 600 flight hours or 100 days, whichever occurs first, until accomplishment of the applicable actions specified in paragraph (h) of this AD.

**(h) New Requirement of This AD: Terminating Action**

Within 6,000 flight hours or 36 months after the effective date of this AD, whichever occurs first: Do the applicable actions specified in paragraphs (h)(1) through (h)(3)

of this AD. Accomplishment of the applicable actions specified in paragraphs (h)(1) through (h)(3) of this AD terminates the requirements of paragraph (g) of this AD.

(1) For airplanes configured as described in Modsum 8/1519: Incorporate Modsum 8Q101968, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-33-56, Revision A, dated February 22, 2013.

(2) For airplanes configured as described in Modsum 8/0235, 8/0461, and 8/0534: Incorporate Modsum 8Q101955, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-32-176, Revision A, dated February 22, 2013.

(3) For airplanes not configured as described in Modsum 8/0534: Incorporate Modsum 8Q101969, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-32-177, dated October 9, 2013.

**(i) Credit for Previous Actions**

(1) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 8-32-173, dated October 28, 2011, which is not incorporated by reference in this AD.

(2) This paragraph provides credit for actions required by paragraph (h)(1) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 8-33-56, dated February 11, 2013, which is not incorporated by reference in this AD.

(3) This paragraph provides credit for actions required by paragraph (h)(2) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 8-32-176, dated February 11, 2013, which is not incorporated by reference in this AD.

**(j) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by

the Manager, New York Aircraft Certification Office, ANE-170, Engine and Propeller Directorate, FAA; or TCCA; or Bombardier, Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

**(k) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2014-11, dated February 13, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0752.

(2) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email [thd.qseries@aero.bombardier.com](mailto:thd.qseries@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on September 24, 2014.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2014-24696 Filed 10-16-14; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2014-0293; Airspace Docket No. 14-ANE-5]

**Proposed Establishment of Class E Airspace; Plainville, CT**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to establish Class E Airspace at Plainville, CT, to accommodate new Area Navigation (RNAV) Global Positioning System (GPS) Standard Instrument Approach Procedures (SIAPs) serving Robertson Field Airport. This action would enhance the safety and airspace management of Instrument Flight Rules (IFR) operations within the National Airspace System.

**DATES:** Comments must be received on or before December 1, 2014.

**ADDRESSES:** Send comments on this rule to: U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey SE., Washington, DC 20590-

0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2014-0293; Airspace Docket No. 14-ANE-5, at the beginning of your comments. You may also submit and review received comments through the Internet at <http://www.regulations.gov>.

**FOR FURTHER INFORMATION CONTACT:** John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-6364.

#### **SUPPLEMENTARY INFORMATION:**

##### **Comments Invited**

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2014-0293; Airspace Docket No. 14-ANE-5) and be submitted in triplicate to the Docket Management System (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Persons wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2014-0293; Airspace Docket No. 14-ANE-5." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

##### **Availability of NPRMs**

An electronic copy of this document may be downloaded from and comments submitted through <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at [http://www.faa.gov/airports\\_](http://www.faa.gov/airports_)

[airtraffic/air\\_traffic/publications/airspace\\_amendments/](#).

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal Holidays. An informal docket may also be examined between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal Holidays, at the office of the Eastern Service Center, Federal Aviation Administration, Room 350, 1701 Columbia Avenue, College Park, Georgia 30337.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory circular No. 11-2A, Notice of Proposed Rulemaking distribution System, which describes the application procedure.

##### **The Proposal**

The FAA is considering an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to establish Class E airspace at Plainville, CT, providing the controlled airspace required to support the new RNAV (GPS) standard instrument approach procedures for Robertson Field Airport. Controlled airspace extending upward from 700 feet above the surface within a 9.5-mile radius of the airport would be established for IFR operations.

Class E airspace designations are published in Paragraph 6005 of FAA order 7400.9Y, dated August 8, 2014, and effective September 15, 2014, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, would not have a significant economic impact on a substantial number of small

entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This proposed rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This proposed regulation is within the scope of that authority as it would establish Class E airspace at Robertson Field Airport, Plainville, CT.

This proposal will be subject to an environmental analysis in accordance with FAA Order 1050.1E, "Environmental Impacts: Policies and Procedures" prior to any FAA final regulatory action.

##### **Lists of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (air).

##### **The Proposed Amendment**

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

##### **PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

- 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

##### **§71.1 [Amended]**

- 2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9Y, Airspace Designations and Reporting Points, dated August 8, 2014, effective September 15, 2014, is amended as follows:

*Paragraph 6005 Class E Airspace Areas Extending Upward from 700 Feet or More Above the Surface of the Earth.*

\* \* \* \* \*

##### **ANE CT E5 Plainville, CT [New]**

Robertson Field Airport, CT  
(Lat. 41°41'22" N., long. 72°51'53" W.)

That airspace extending upward from 700 feet above the surface within a 9.5-mile radius of Robertson Field Airport.

Issued in College Park, Georgia, on October 7, 2014.

**Myron A. Jenkins,**

*Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.*

[FR Doc. 2014-24616 Filed 10-16-14; 8:45 am]

**BILLING CODE 4910-13-P**

## ENVIRONMENTAL PROTECTION AGENCY

### 40 CFR Part 52

[EPA-R10-OAR-2014-0744, FRL-9918-05-Region 10]

### Approval and Promulgation of Implementation Plans; Washington: Infrastructure Requirements for the Fine Particulate Matter National Ambient Air Quality Standards

**AGENCY:** Environmental Protection Agency.

**ACTION:** Proposed rule.

**SUMMARY:** The Environmental Protection Agency (EPA) is proposing to partially approve and partially disapprove the State Implementation Plan (SIP) submittal from Washington demonstrating that the SIP meets the infrastructure requirements of the Clean Air Act (CAA) for the National Ambient Air Quality Standards (NAAQS) promulgated for fine particulate matter (PM<sub>2.5</sub>) on July 18, 1997, October 17, 2006, and December 14, 2012 (collectively the PM<sub>2.5</sub> NAAQS). The CAA requires that each state, after a new or revised NAAQS is promulgated, review their SIP to ensure that it meets the infrastructure requirements necessary to implement the new or revised NAAQS. On September 22, 2014, Washington certified that the Washington SIP meets the infrastructure requirements of the CAA for the PM<sub>2.5</sub> NAAQS, except for those requirements related to the Prevention of Significant Deterioration (PSD) permitting program currently operated under a Federal Implementation Plan (FIP), certain elements of the regional haze program currently operated under a FIP, and specific requirements related to interstate transport which will be addressed in a separate submittal. The EPA is proposing to find that Washington's SIP is adequate for purposes of the infrastructure SIP requirements of the CAA with the exceptions noted above. The EPA is proposing to find that the SIP deficiencies related to PSD permitting and regional haze, however, have been adequately addressed by the existing EPA FIPs and, therefore, no further action is required by Washington or the

EPA for those elements. The EPA will address the remaining interstate transport requirements in a separate action.

**DATES:** Comments must be received on or before November 17, 2014.

**ADDRESSES:** Submit your comments, identified by Docket ID No. EPA-R10-OAR-2014-0744, by any of the following methods:

- *Email:* R10-Public\_Comments@epa.gov.
- *www.regulations.gov:* Follow the on-line instructions for submitting comments.
- *Mail:* Jeff Hunt, EPA Region 10, Office of Air, Waste and Toxics (AWT-150), 1200 Sixth Avenue, Suite 900, Seattle, WA 98101.
- *Hand Delivery:* EPA Region 10 Mailroom, 9th Floor, 1200 Sixth Avenue, Suite 900, Seattle, WA 98101. Attention: Jeff Hunt, Office of Air, Waste and Toxics, AWT-107. Such deliveries are only accepted during normal hours of operation, and special arrangements should be made for deliveries of boxed information.

*Instructions:* Direct your comments to Docket ID No. EPA-R10-OAR-2014-0744. The EPA's policy is that all comments received will be included in the public docket without change and may be made available online at [www.regulations.gov](http://www.regulations.gov), including any personal information provided, unless the comment includes information claimed to be Confidential Business Information (CBI) or other information the disclosure of which is restricted by statute. Do not submit information that you consider to be CBI or otherwise protected through [www.regulations.gov](http://www.regulations.gov) or email. The [www.regulations.gov](http://www.regulations.gov) Web site is an "anonymous access" system, which means the EPA will not know your identity or contact information unless you provide it in the body of your comment. If you send an email comment directly to the EPA without going through [www.regulations.gov](http://www.regulations.gov) your email address will be automatically captured and included as part of the comment that is placed in the public docket and made available on the Internet. If you submit an electronic comment, the EPA recommends that you include your name and other contact information in the body of your comment and with any disk or CD-ROM you submit. If the EPA cannot read your comment due to technical difficulties and cannot contact you for clarification, the EPA may not be able to consider your comment. Electronic files should avoid the use of special characters, any form of encryption, and be free of any defects or viruses.

*Docket:* All documents in the docket are listed in the [www.regulations.gov](http://www.regulations.gov) index. Although listed in the index, some information is not publicly available, e.g., CBI or other information the disclosure of which is restricted by statute. Certain other material, such as copyrighted material, is not placed on the Internet and will be publicly available only in hard copy. Publicly available docket materials are available either electronically in [www.regulations.gov](http://www.regulations.gov) or in hard copy during normal business hours at the Office of Air, Waste and Toxics, EPA Region 10, 1200 Sixth Avenue, Seattle, WA 98101.

**FOR FURTHER INFORMATION CONTACT:** Jeff Hunt at: (206) 553-0256, [hunt.jeff@epa.gov](mailto:hunt.jeff@epa.gov), or the above EPA, Region 10 address.

#### SUPPLEMENTARY INFORMATION:

Throughout this document wherever "we," "us" or "our" is used, it is intended to refer to the EPA. Information is organized as follows:

#### Table of Contents

- I. Background
- II. CAA Sections 110(a)(1) and (2) Infrastructure Elements
- III. The EPA's Approach to Review of Infrastructure SIP Submittals
- IV. Analysis of the State's Submittal
- V. Proposed Action
- VI. Statutory and Executive Order Reviews

#### I. Background

On July 18, 1997, the EPA promulgated a new 24-hour and a new annual NAAQS for PM<sub>2.5</sub> (62 FR 38652). On October 17, 2006, the EPA revised the standards for PM<sub>2.5</sub>, tightening the 24-hour PM<sub>2.5</sub> standard from 65 micrograms per cubic meter (μg/m<sup>3</sup>) to 35 μg/m<sup>3</sup>, and retaining the annual PM<sub>2.5</sub> standard at 15 μg/m<sup>3</sup> (71 FR 61144). Subsequently, on December 14, 2012, the EPA revised the level of the health based (primary) annual PM<sub>2.5</sub> standard to 12 μg/m<sup>3</sup> (78 FR 3086, published January 15, 2013).<sup>1</sup>

States must submit SIPs meeting the requirements of CAA sections 110(a)(1) and (2) within three years after promulgation of a new or revised standard. CAA sections 110(a)(1) and (2) require states to address basic SIP requirements, including emissions inventories, monitoring, and modeling to implement, maintain, and enforce the standards, so-called "infrastructure"

<sup>1</sup> In the EPA's 2012 PM<sub>2.5</sub> NAAQS revision, we left unchanged the existing welfare (secondary) standards for PM<sub>2.5</sub> to address PM-related effects such as visibility impairment, ecological effects, damage to materials and climate impacts. This includes an annual secondary standard of 15.0 μg/m<sup>3</sup> and a 24-hour standard of 35 μg/m<sup>3</sup>.