

Actions and Compliance

(e) Unless already done, within 75 flight hours after the effective date of this AD, replace the S/N DECU's listed in applicability paragraph (c) of this AD:

- (1) With a DECU having a S/N not listed in paragraph (c); or
- (2) With a DECU having a S/N listed in paragraph (c), that has been returned to an approved repair center since January 1, 2010.

FAA AD Differences

(f) This AD differs from the Mandatory Continuing Airworthiness Information (MCAI) and/or service information as follows:

(1) EASA AD 2010-0068-E (corrected), dated April 13, 2010, requires, for helicopters having two affected DECU's, that one of the DECU's be replaced before the next flight, and the other DECU be replaced within 75 flight hours after the effective date of the AD.

(2) This AD requires all affected DECU's be replaced within 75 flight hours after the effective date of this AD.

(3) Although EASA AD 2010-0068-E (corrected), dated April 13, 2010, also applies to the Makila 2A1 engine, this AD does not apply to that model because it has no U.S. type certificate.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2010-0068-E (corrected), dated April 13, 2010, and Turbomeca Alert Mandatory Service Bulletin No. A298 73 2815, Version A, dated March 18, 2010, for related information. Contact Turbomeca, 40220 Tarnos, France; telephone 33 05 59 74 40 00, fax 33 05 59 74 45 15, for a copy of this service information.

(i) Contact Kevin Dickert, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: kevin.dickert@faa.gov; telephone (781) 238-7117; fax (781) 238-7199, for more information about this AD.

Material Incorporated by Reference

(j) None.

Issued in Burlington, Massachusetts, on April 23, 2010.

Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2010-9963 Filed 4-29-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2009-1002; Airspace Docket No. 09-ANM-18]

Establishment of Class E Airspace; Bonners Ferry, ID

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action will establish Class E airspace at Bonners Ferry, ID, to accommodate aircraft using a new Area Navigation (RNAV) Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) at Boundary County Airport. This will improve the safety and management of Instrument Flight Rules (IFR) operations at the airport.

DATES: Effective date, 0901 UTC, July 29, 2010. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Eldon Taylor, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue, SW., Renton, WA 98057; telephone (425) 203-4537.

SUPPLEMENTARY INFORMATION:**History**

On November 13, 2009, the FAA published in the **Federal Register** a notice of proposed rulemaking to amend controlled airspace at Bonners Ferry, ID (74 FR 58570). Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9T signed August 27, 2009, and effective September 15, 2009, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in that Order.

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) part 71 by establishing Class E airspace extending upward from 700 feet above the surface, at Boundary County Airport, to accommodate IFR aircraft executing new RNAV GPS SIAPs at the airport. This action is necessary for the safety and management of IFR operations.

The FAA has determined this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, section 106 discusses the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in subtitle VII, part A, subpart I, section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes additional controlled airspace at Boundary County Airport, Bonners Ferry, ID.

List of Subjects in 14 CFR Part 71

Airspace, incorporation by reference, Navigation (air).

Adoption of the Amendment

■ In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9T, Airspace Designations and Reporting Points, signed August 27, 2009, and effective September 15, 2009, is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ANM WA E5 Bonners Ferry, ID [New]
Boundary County Airport, ID
(Lat. 48°43'34" N., long. 116°17'43" W.)
That airspace extending upward from 700 feet above the surface within a 5-mile radius of Boundary County Airport, Bonners Ferry, ID.
Issued in Seattle, Washington, on April 20, 2010.
Clark Desing,
Manager, Operations Support Group, Western Service Center.
[FR Doc. 2010-10044 Filed 4-29-10; 8:45 am]
BILLING CODE 4910-13-P

DEPARTMENT OF DEFENSE

Department of the Navy

32 CFR Part 706

Certifications and Exemptions Under the International Regulations for Preventing Collisions at Sea, 1972

AGENCY: Department of the Navy, DoD.
ACTION: Final rule.

SUMMARY: The Department of the Navy is amending its certifications and exemptions under the International Regulations for Preventing Collisions at Sea, 1972 (72 COLREGS), to reflect that the Deputy Assistant Judge Advocate General (Admiralty and Maritime Law) has determined that USS MISSOURI (SSN 780) is a vessel of the Navy which, due to its special construction and purpose, cannot fully comply with certain provisions of the 72 COLREGS

without interfering with its special function as a naval ship. The intended effect of this rule is to warn mariners in waters where 72 COLREGS apply.

DATES: This rule is effective April 30, 2010 and is applicable beginning April 21, 2010.

FOR FURTHER INFORMATION CONTACT: Lieutenant Commander Ted Cook, (Admiralty and Maritime Law), Office of the Judge Advocate General, Department of the Navy, 1322 Patterson Ave., SE., Suite 3000, Washington Navy Yard, DC 20374-5066, telephone 202-685-5040.

SUPPLEMENTARY INFORMATION: Pursuant to the authority granted in 33 U.S.C. 1605, the Department of the Navy amends 32 CFR Part 706.

This amendment provides notice that the Deputy Assistant Judge Advocate General (Admiralty and Maritime Law), under authority delegated by the Secretary of the Navy, has certified that USS MISSOURI (SSN 780) is a vessel of the Navy which, due to its special construction and purpose, cannot fully comply with the following specific provisions of 72 COLREGS without interfering with its special function as a naval ship: Annex I, paragraph 2(a)(i), pertaining to the height placement of the masthead light above the hull; Annex I, paragraph 2(k), pertaining to the height and relative positions of the anchor lights; Annex I, paragraph 3(b), pertaining to the location of the sidelights; and Rule 21(c), pertaining to the location and arc of visibility of the sternlight. The Deputy Assistant Judge Advocate General (Admiralty and Maritime Law) has also certified that the lights involved are located in closest possible compliance with the applicable 72 COLREGS requirements.

Moreover, it has been determined, in accordance with 32 CFR Parts 296 and 701, that publication of this amendment for public comment prior to adoption is impracticable, unnecessary, and contrary to public interest since it is based on technical findings that the placement of lights on this vessel in a manner differently from that prescribed herein will adversely affect the vessel's ability to perform its military functions.

List of Subjects in 32 CFR Part 706

Marine safety, Navigation (water), and Vessels.

■ For the reasons set forth in the preamble, the Navy amends part 706 of title 32 of the Code of Federal Regulations as follows:

PART 706—CERTIFICATIONS AND EXEMPTIONS UNDER THE INTERNATIONAL REGULATIONS FOR PREVENTING COLLISIONS AT SEA, 1972

■ 1. The authority citation for part 706 continues to read as follows:

Authority: 33 U.S.C. 1605.

■ 2. Section 706.2 is amended as follows:

■ A. In Table One by adding, in alpha numerical order, by vessel number, an entry for USS MISSOURI (SSN 780); and

■ B. In Table Three by adding, in alpha numerical order, by vessel number, an entry for USS MISSOURI (SSN 780).

The additions read as follows:

§ 706.2 Certifications of the Secretary of the Navy under Executive Order 11964 and 33 U.S.C. 1605.

* * * * *

TABLE ONE

| Vessel | | | | Number | Distance in meters of forward masthead light below minimum required height. § 2(a)(i), Annex I |
|--------------------|--|--|--|---------------|--|
| * * * * * | | | | | |
| USS MISSOURI | | | | SSN 780 | 2.76 |
| * * * * * | | | | | |

* * * * *