

(3) Where Boeing Alert Service Bulletin 747–53A2427, Revision 6, dated July 14, 2011, specifies a compliance time after the date on Revision 6 of this service bulletin, this AD requires compliance within the specified compliance time “after the effective date of this AD.”

(4) If any cracking is found during any inspection required by this AD, and Boeing Alert Service Bulletin 747–53A2427, Revision 6, dated July 14, 2011; or Boeing Service Bulletin 747–53A2473, Revision 4, dated December 1, 2011; specifies to contact Boeing for appropriate action: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (o) of this AD.

(5) If, during any inspection required by paragraph (g) of this AD, any cracking is found in the doubler, before further flight, repair, using a method approved in accordance with the procedures specified in paragraph (o) of this AD.

(6) Where Part 1 of the Accomplishment Instructions of Boeing Alert Service Bulletin 747–53A2427, Revision 6, dated July 14, 2011, specifies accomplishing inspections for cracks for forward and aft inner chords, splice fittings, floor supports, and upper and lower web panels, this AD also requires doing an open-hole HFEC inspection of the doubler.

(7) Where Boeing Service Bulletin 747–53A2473, Revision 4, dated December 1, 2011, specifies a compliance time after the date on Revision 2 of the service bulletin, this AD requires compliance within the specified compliance time as of August 5, 2010 (the effective date of AD 2010–14–07, Amendment 39–16352 (75 FR 38001, July 1, 2010)).

(8) Where Boeing Service Bulletin 747–53A2473, Revision 4, dated December 1, 2011, specifies a compliance time after the date on Revision 3 or 4 of the service bulletin, this AD requires compliance within the specified compliance time “after the effective date of this AD.”

**(n) Terminating Action for Certain Requirements of AD 2010–14–07, Amendment 39–16352 (75 FR 38001, July 1, 2010)**

(1) Accomplishing the inspections, repairs, and modification in accordance with Boeing Service Bulletin 747–53A2473, Revision 4, dated December 1, 2011, is a terminating action for the corresponding inspections, repairs, and modification at the STA 2598 support frame required by paragraphs (i), (j), (k)(1), (m), (n), (o), (p), (q), (r), (s), (t), (u), and (v) of AD 2010–14–07, Amendment 39–16352 (75 FR 38001, July 1, 2010). When Boeing Service Bulletin 747–53A2473, Revision 4, dated December 1, 2011, specifies to contact Boeing for repair instructions, the repair instructions must be approved by the FAA in accordance with paragraph (o) of this AD. All provisions of AD 2010–14–07 that are not specifically referenced in this paragraph remain fully applicable and must be complied with.

(2) Accomplishing the inspections, repairs and interim modification in accordance with Boeing Service Bulletin 747–53A2427, Revision 6, dated July 14, 2011, is a

terminating action for the corresponding inspections, repairs and interim modification at the STA 2598 bulkhead required by paragraphs (i), (j), (o), (s), (t), (u), and (v) of AD 2010–14–07, Amendment 39–16352 (75 FR 38001, July 1, 2010). When Boeing Service Bulletin 747–53A2427, Revision 6, dated July 14, 2011, specifies to contact Boeing for repair data, the repair data must be approved by the FAA in accordance with paragraph (o) of this AD. All provisions of AD 2010–14–07 that are not specifically reference in this paragraph remain fully applicable and must be complied with.

**(o) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

**(p) Related Information**

(1) For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6432; fax: 425–917–6590; email: [bill.ashforth@faa.gov](mailto:bill.ashforth@faa.gov).

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on May 17, 2013.

**Jeffrey E. Duven,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2013–12618 Filed 5–24–13; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

[Docket No. FAA–2013–0282; Airspace Docket No. 13–AAL–3]

**Proposed Amendment of Class E Airspace; Gustavus, AK**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to amend Class E airspace at Gustavus Airport, Gustavus, AK. Decommissioning of the Gustavus Nondirectional Radio Beacon (NDB) has made this action necessary for the safety and management of Instrument Flight Rules (IFR) operations at the airport. This action also would adjust the geographic coordinates of the airport.

**DATES:** Comments must be received on or before July 12, 2013.

**ADDRESSES:** Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590; telephone (202) 366–9826. You must identify FAA Docket No. FAA–2013–0282; Airspace Docket No. 13–AAL–3, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>.

**FOR FURTHER INFORMATION CONTACT:** Eldon Taylor, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue SW., Renton, WA 98057; telephone (425) 203–4537.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2013–0282 and Airspace Docket No. 13–AAL–3) and be submitted in triplicate to the Docket Management System (see

**ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA-2013-0282 and Airspace Docket No. 13-AAL-3". The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

#### Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at [http://www.faa.gov/airports\\_airtraffic/air\\_traffic/publications/airspace\\_amendments/](http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/).

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for the address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays. An informal docket may also be examined during normal business hours at the Northwest Mountain Regional Office of the Federal Aviation Administration, Air Traffic Organization, Western Service Center, Operations Support Group, 1601 Lind Avenue SW., Renton, WA 98057.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

#### The Proposal

The FAA is proposing an amendment to Title 14 Code of Federal Regulations (14 CFR) Part 71 by amending Class E airspace extending upward from 700 feet above the surface at Gustavus Airport, Gustavus, AK. Airspace

reconfiguration is necessary due to the decommissioning of the Gustavus NDB. The geographic coordinates of the airport would be adjusted in accordance with the FAA's aeronautical database. This action would enhance the safety and management of aircraft operations at Gustavus Airport, Gustavus, AK.

Class E airspace designations are published in paragraph 6005, of FAA Order 7400.9W, dated August 8, 2012, and effective September 15, 2012, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in this Order.

The FAA has determined this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation; (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified this proposed rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority for the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would amend controlled airspace at Gustavus Airport, Gustavus, AK.

This proposal will be subject to an environmental analysis in accordance with FAA Order 1050.1E, "Environmental Impacts: Policies and Procedures" prior to any FAA final regulatory action.

#### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR Part 71 as follows:

#### PART 71—DESIGNATION OF CLASS A, B, C, D AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

■ 1. The authority citation for 14 CFR Part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

##### § 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9W, Airspace Designations and Reporting Points, dated August 8, 2012, and effective September 15, 2012 is amended as follows:

*Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.*

\* \* \* \* \*

##### AAL AK E5 Gustavus, AK [Amended]

Gustavus Airport, AK  
(Lat. 58°25'31" N., long. 135°42'27" W.)

That airspace extending upward from 700 feet above the surface within a 6.8-mile radius of the Gustavus Airport and within 4 miles each side of the 229° bearing of the airport extending from the 6.8-mile radius to 16.7 miles southwest of the airport, and within 3 miles northeast and 7 miles southwest of the airport 135° bearing extending from the 6.8-mile radius to 24 miles southeast of the airport.

Issued in Seattle, Washington, on May 15, 2013.

**Clark Desing,**

*Manager, Operations Support Group, Western Service Center.*

[FR Doc. 2013-12625 Filed 5-24-13; 8:45 am]

**BILLING CODE 4910-13-P**

#### DEPARTMENT OF HOMELAND SECURITY

##### Coast Guard

##### 33 CFR Part 64

[Docket No. USCG-2012-0054]

RIN 1625-AA97

##### Waiver for Marking Sunken Vessels With a Light at Night

**AGENCY:** Coast Guard, DHS.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This proposed rulemaking would revise Coast Guard regulations to